Submit 1 Copy To Appropriate District		New Me		Form C-103
District I - (575) 393-6161	Energy, Minerals	and Natu	ral Resources	Revised July:18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	OH COMCEDI	7 A TTION	DIMIGION	30-015-42315
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		· ·	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410				STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fc, NM 87505	Santa Fe	e, NM 87	505	6. State Oil & Gas Lease No. VB-1667
SUNDRY NOT	ICES AND REPORTS OF	N WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Colossal BUO State 8. Well Number	
PROPOSALS.) 1. Type of Well: Oil Well	: Oil Well 🔯 Gas Well 🗌 Other			2H
2. Name of Operator			Man gar	9. OGRID Number
Mewbourne Oil Company	saturns .		*,	. 14744
3. Address of Operator			10. Pool name or Wildcat	
PO Box 5270, Hobbs NM 88241				Undesignated; 2 nd Bone Spring Sand
4. Well Location		·		
Unit Letter P :	_660 feet from the _Sc	outh	_ line and200	feet from theEastline
Section 32	Township 23S	Range	27E	NMPM Eddy County
	11. Elevation (Show what 3230' GL	hether DR,	RKB, RT, GR, etc	2.)
	*			
12. Check	Appropriate Box to In	dicate Na	ature of Notice	e, Report or Other Data
	-	1		•
	ITENTION TO:			BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS		REMEDIAL WO	
PULL OR ALTER CASING	MULTIPLE COMPL	Н	CASING/CEME	
DOWNHOLE COMMINGLE	MOETH LE COMI E			11 000
CLOSED-LOOP SYSTEM				
OTHER:			OTHER [
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
proposed templation of 144	ompiction.			
MOC request to P&A well by pouring redi-mix from surface.				
Approved for plugging of well bore only. Liability under bond is retained pending receipt				under bond is retained pending receipt
			of C-10.	S (Subsequent Report of Well Plugging)
			which to	hav be found at OCD Web Page under
			Forms, v	www.cmnrd.state.nm.us/oed.
Spud Date: 05/29/14	R	lig Release	Date:	
WELL MUST BE PLUBBED BY 3-11-2017				
I hereby certify that the information				lge and belief.
•	•		•	
SIGNATURE CONTROL TITLE Regulatory DATE 03/10/16				
Type or print nameJackie Lathan E-mail address: jlathan@mewbourne.com PHONE: 575-393-5905				
APPROVED BY: Jaht 1 Sal TITLE COMPLIANCE OFFICER DATE 3/11/2016 Conditions of Approval (if any): 575-626-0836				
APPROVED BY: /alt/	Hyel TITI	E COM	PLIANCE	OFFICEAL DATE 3/11/2016
Conditions of Approval (if any):	575-62	6-083	36	

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Opera	tor:
Well I API #	Name & Number:
	,
1.	Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
2.	Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
	Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
4.	Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
5.	A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
6.	If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
7.	Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
8.	Cement Retainers may not be used.
9. 10	Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD. Plugs may be combined after consulting with and getting approval from NMOCD. Minimum WOC time for tag plugs will be 4 Hrs.
12	. 19.15.7.16: B. In the case of a dry hole, a complete record of the well on form C-105 with the
	attachments listed in Subsection A of 19.15.7.16 NMAC shall accompany the notice of intention to plug the well, unless previously filed. The division shall not approve the plugging report or release the bond the operator has complied with 19.15.7.16 NMAC.

DATE:

APPROVED BY:

N.M.O.C.D.- Guidelines For Plugging

- All cement plugs will be a minimum of 100' in length, or a minimum of 25sx. Of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sx. Of gel per 100 bbls. Of water.
- A cement plug is required to be set 50' below, and 50' above all casing shoes, and casing stubs. These plugs must be tagged.
- A CIBP with 35' of cement on top, may be set instead of 100' plug.
- A plug as indicated above, must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set above and below all salt zones, must be tagged.
- No more than 2000' is to be allowed between plugs in open hole, and no more than 3000' between plugs in cased hole.
- D.V. tools are required to have a 100' cement plug set 50' above, and 50' below the tool. This plug must be tagged.

Formations to be isolated with plugs placed at the top of each formation are:

- Fusselman
- Devonian
- Morrow
- Wolfcamp
- Bone Springs
- Delaware
- Any salt section (plug at top and bottom)
- Abo
- Glorietta
- Yates (this plug is usually at base of salt section)

If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths, or casing must be perforated and squeezed behind casing at the formation depths.

In the R-111P area (Potash mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated, and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible.