

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

APR 06 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	RKI E&P, LLC	Contact	Taylor Jones
Address	210 Park Ave. - Ste. 700, OKC, OK 73102	Telephone No.	539-573-7558
Facility Name:	Ginger Federal I	Facility Type :	Oil and Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-25744
------------------------	------------------------	----------------------

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	24	26S	30E	460	FSL	1880	FEL	Eddy

Latitude: 32.02174 Longitude: -103.8318447

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 195 Bbls	Volume Recovered: 146 Bbls
Source of Release Oil Line between oil tanks	Date and Hour of Occurrence 04/06/16 - 0900hrs MT	Date and Hour of Discovery 04/06/16 - 0900hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson and Shelly Tucker	
By Whom? Taylor Jones	Date and Hour: 04/06/16 - 1:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Oil load line between the two oil tanks on location ruptured, causing the release of crude oil.		
Describe Area Affected and Cleanup Action Taken.* Spill was contained to earthen (unlined) berm, with exception of 0.5 bbls of oil which went through berm, but stayed on location. Recovered standing fluid by vacuum truck, recovered 146 bbls of oil. All affected soil to be removed and taken to disposal.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Taylor Jones	Approval Date: 4/7/16	Expiration Date: N/A
Title: Safety Specialist II	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	
E-mail Address: Taylor.jones@wpenergy.com	Attached <input type="checkbox"/>	
Date: 04/06/16 Phone: 539-573-7558	LATER THAN: 5/1/16	

* Attach Additional Sheets If Necessary

2RP-3635