

NM OIL CONSERVATION

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

ARTESIA DISTRICT

APR 07 2016

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAME DAB1609941598 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production Company **Contact** Enrique Campos, Production Foreman

Address 6488 Seven Rivers Hwy Artesia, NM 88210 **Telephone No.** 575.513.1933

Facility Name Todd 22B Fed 2 **Facility Type** Gas

Surface Owner Federal **Mineral Owner** Federal **API No** 30-015-32203

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	22	23S	31E	510	FNL	1980	FEL	Eddy

Latitude: 32.29576

Longitude: 103.76357

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 2BBLS Oil & 48BBLS PW	Volume Recovered 1BBL Oil & 44BBLS PW
Source of Release Manway gasket on horizontal separator	Date and Hour of Occurrence 4/5/2016 @ 1:52pm	Date and Hour of Discovery 4/5/2016 @ 1:52pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Shelly Tucker BLM-Mike Bratcher	
By Whom? Jeremy Porras, Assistant Production Foreman	Date and Hour OCD-4/6/2016 @ 3:10pm BLM-4/6/2016 @ 3:05pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

The manway gasket located on the horizontal heater gave out causing 2 BBLS oil and 48 BBLS produced water to be released. The line was isolated from production to prevent further release. The equipment was tagged and locked until repairs are made.

Describe Area Affected and Cleanup Action Taken.*

2BBLS oil and 48BBLS of produced water was released and 1BBL oil and 44BBLS produced water was recovered via vacuum truck. The release originated from the manway gasket on the horizontal heater on the Southwest side of pad. Oil and produced water was released into the bermed containment surrounding the equipment. Approximately 3 gallons of oil and 2BBLS of PW escaped the bermed containment. Approximately 2 gallons of oil and produced water mix sprayed in a fine mist onto the vegetation on the Southwest side of the pad. The approximate total size of the affected area was 30' x 30' on pad. An environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Dana DeLaRosa</u>	OIL CONSERVATION DIVISION	
Printed Name: <u>Dana DeLaRosa</u>	Signed By: <u>[Signature]</u> Approved by Environmental Specialist:	
Title: <u>Field Admin Support</u>	Approval Date: <u>4/7/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: <u>dana.delarosa@dmn.com</u>	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Submit Remediation Proposal No	
Date: <u>4-7-2016</u> Phone: <u>575.746.5594</u>	LATER THAN: <u>5/11/16</u>	

* Attach Additional Sheets If Necessary

2RP-3640