

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

APR 06 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1609926539

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Jake Harrington, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	432-214-5175
Facility Name	Snapping 2 State I-Y	Facility Type	Oil

Surface Owner State	Mineral Owner State	API No.	30-015-39104
---------------------	---------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	26S	31E	330	FSL	1710	FWL	Eddy

Latitude: 32.0657578

Longitude: -103.7519608

NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced water release	5bbls	0bbls
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Heater treater fire tube	April 2, 2016 @ 11:33 AM	April 2, 2016 @ 11:33 AM
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	Kellie Jones, OCD	
By Whom?	Date and Hour	
Ray Carter, Assistant Production Foreman	April 3, 2016 @ 7:05 AM	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Fire tube on heater treater had a hole releasing approximately 5bbls produced water on to location. The immediate actions were to make sure the well was down so the inlet on the heater treater could be closed and the drain opened to send the remaining fluid to the water tanks to stop any further release. A vacuum truck was able to pull the remaining fluid from the heater treater to ensure it was completely empty. The heater treater has been taken out of service until repairs can be made.

Describe Area Affected and Cleanup Action Taken.* The release was 5bbls produced water with 0bbls recovered located on the West side of location close to the heater treater in approximately a 15'x20' area. All fluid remained on location. An environmental agency will be contacted for remediation of the affected area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By <i>Mike Brander</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Sheila.Fisher@dm.com	Approval Date: 4/7/16	Expiration Date: N/A
Date: April 6, 2016 Phone: 575.748.1829	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input checked="" type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 5/11/16	

* Attach Additional Sheets If Necessary

2RP-3636