

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

APR 22 2016

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1611653621

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Apache Corporation 873	Contact Bruce Baker	
Address: 2350 W Marland Blvd Hobbs, NM 88240	Telephone No. (432) 631-6982	
Facility Name Cedar Lake Federal CA 335H	Facility Type: Oil Well	
Surface Owner Federal	Mineral Owner	API No. 30-15-42140

LOCATION OF RELEASE

Unit Letter M	Section 3	Township 17S	Range 31E	Feet from the 930'	North/South Line FSL	Feet from the 557'	East/West Line FWL	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

32.858879

Latitude Longitude

103.864418

NATURE OF RELEASE

Type of Release: produced water and oil	Volume of Release 5 barrels of oil and 2 barrels of water	Volume Recovered 2 barrels of oil
Source of Release: Well Head	Date and Hour of Occurrence 4/6/2016	Date and Hour of Discovery 4/6/2016
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker (BLM) via email	
By Whom? Bruce Baker	Date and Hour 4/7/2015 at	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Analog gauge at well head broke resulting in the release. The release was isolated and repaired.		
Describe Area Affected and Cleanup Action Taken.* The majority of the standing fluid from the release was contained on the well pad. Approximately 1,000 square feet of light oil overspray affected the pasture north and northeast of the pad. The affected vegetation from the overspray will be washed with Dawn dishwashing soap.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Bruce Baker		OIL CONSERVATION DIVISION	
Printed Name: Bruce Baker		Approved by Environmental Specialist: [Signature]	
Title: Environmental Technician		Approval Date: 4/25/16	Expiration Date: N/A
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 4/22/2016	Phone: (432) 631-6982		

* Attach Additional Sheets If Necessary

LATER THAN: 5/26/16

2RP-3658