

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-24973
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator WS OIL AND GAS OPERATING, LLC		6. State Oil & Gas Lease No. VB-0405
3. Address of Operator PO BOX 5375, Midland, TX 79704		7. Lease Name or Unit Agreement Name FINA STATE
4. Well Location Unit Letter E : 2310 feet from the N line and 990 feet from the W line Section 36 Township 18S Range 29E NMPM County EDDY		8. Well Number 001
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 370922
		10. Pool name or Wildcat 61020: Turkey Track 7 RVRS QU GB SA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL. <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>		OTHER: <input checked="" type="checkbox"/> ACIDIZE	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

NM OIL CONSERVATION
ARTESIA DISTRICT

APR 25 2016

RECEIVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carie Stoker TITLE Regulatory Affairs Coordinator DATE 4/21/2016

Type or print name Carie Stoker E-mail address: carie@stokeroilfield.com PHONE: 432.664.7659

APPROVED BY: [Signature] TITLE "Geologist" DATE 4/28/16
Conditions of Approval (if any):

FINA STATE #001

04/20/16

MIRU. UNHANG WELL. UNSEATED PUMP AND POOH WITH PUMP AND RODS. ND WELLHEAD. NU BOP. POOH WITH TUBING. PU 5-1/2" X 2-3/8" BAKER TYPE AD-1 TENSION PACKER. RIH TO 2500'. CIRCULATED WELL CLEAN WITH 50 BBLS FW. SET PACKER AND ACIDIZED QUEEN PERF2645' - 86' WITH 750 GALS 15% NEFE HCL ACID WITH ADDITIVES DOWN 2-3/8" TUBING. STARTING RATE 4 BPM @ 500 PSI. ACID ON FORMATION RATE 4 BPM @ 400 PSI. PUMPED 70 BBLS 35/65 XCHEM CHEMICAL AND FLUSHED WITH 11.4 BBLS FW. ISIP WELL ON VACUUM. SWISDON FOR ACID TO SPEND.

4/21/16

WELL ON VACUUM. POOH WITH PACKER AND TUBING. RIH WITH 2-3/8" SEATING NIPPLE ON 2-3/8" J55 EUE 8RD BB TUBING. PU 2 EXTRA JOINTS TO CIRCULATE WELL CLEAN WITH 50 BBLS FW. LAID DOWN 2 JTS. ND BOP. NU WELLHEAD. PREP FOR RODS. RIH WITH PUMP AND RODS. SPACED OUT WELL AND HWO. TEST PUMP TO 500 PSI. OK. CLEANED LOCATION. AND WELLHEAD. RDMO.

TUBING

KB	3.00'	3.00'
87 JTS 2-3/8" BLUE BAND TUBING	2709.80'	2712.80'
2-3/8" STANDARD SEATING NIPPLE	1.10'	2713.90'

RODS

1-1/4" X 16' POLISH ROD WITH 1-1/2" LINER	11.00'
87 X 3/4: RODS	2175.00'
20 X 7/8" RODS	500.00'
2 X 1-1/2 X 12' RWBC HVR PUMP	12.00'