## NM OIL CONSERVATION

ARTESIA DISTRICT

State of New Mexico **Energy Minerals and Natural Resources** 

Form C-141

MAY 0 2 2016

Revised August 8, 2011

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
811 S. First St., Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District\_IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505

Submit 1 Copy to appropriate District Office in **RECEIVED** rdance with 19.15.29 NMAC.

			Th I	<b>N</b> Y 4909		1.0	4. A	4.				
Release Notification and Corrective Action												
NAB 1412432557						OPERATOR					Final Report	
						Contact Jake Harrington, Production Foreman						
Address 6488 Seven Rivers Hwy Artesia, NM 88220						<b>Telephone No.</b> 432-214-5175						
Facility Na	me Snappi	ing 2 State 1	-Y		] ]	Facility Type Oil						
Surface Owner State Mineral Owner						State API No. 30-015-39104						
· · · · · · · · · · · · · · · · · · ·						1						
LOCATION OF RELEASE												
Unit Letter	, , , , , , , , , , , , , , , , , , , ,				1	South Line	Feet from the	East/West Lin				
N	2	26S	31E	330		FSL	1710	FWL	Eddy	Eddy		
<b>Latitude:</b> 32.0657578 <b>Longitude:</b> -103.7519608												
NATURE OF RELEASE												
Type of Release						· •			ne Recovere	Recovered		
Natural Gas						60 MCF			0 MCF			
Source of Release										Hour of Discovery		
Buy back gas line						April 25, 2016 @ 11:01 AM					1	
Was Immediate Notice Given?  ✓ Yes ☐ No ☐ Not Required						If YES, To Whom?  Shelly Tucker, BLM						
☑ 1.cs ☐ 140 ☐ 140t Kednited						Mike Bratcher, OCD						
By Whom?						Date and Hour						
Ray Carter, Asst. Production Foreman						Shelly Tucker, BLM April 28, 2016 @ 10:39 AM						
						Mike Bratcher, OCD April 28, 2016 @ 10:42 AM						
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse						
☐ Ycs ☒ No N/A												
If a Watercourse was Impacted, Describe Fully.* N/A												
	use of Prob	lem and Ren	nedial Ac	tion Taken.*				<del></del> ,				
Describe Cause of Problem and Remedial Action Taken.*  The buyback gas line ruptured releasing 60 MCF. The valves on both sides of the line were immediately shut to stop any further release. The wells have												
been shut in until an investigation and repairs are complete.												
D 4. A A. C												
Describe Area Affected and Cleanup Action Taken.*  The line rupture caused a 60 MCF eir release. No further action is required.												
Sas.												
				e is true and comp								
regulations a	ll operators	are required t	o report a	nd/or file certain r	elease no	otifications a	nd perform correc	tive actions for	releases whi	ch may e	endanger	
				ce of a C-141 repo								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
rederar, state.	or rocal la	wa and or rege	1144471151			OIL CONSERVATION DIVISION						
Signature: Sheila Fisher							OIL COIL	<u> </u>	<u> </u>	101.		
· · · · · · · · · · · · · · · · · · ·						Signed By Mile Breeze						
Printed Name: Sheila Fisher						Approved by Environmental Specialist.						
							1c: 5/3/14		<b>.</b>	114		
Title: Field A	Admin Sup	port			- +	Approval Da	ic: UVIII	Expirat	ion Date:	4/1		
E-mail Addre	ess: Sheila l	Fisher@dvn	com			Conditions of	f Approval: -			. —		
E-mail Address: Sheila.Fisher@dvn.com						FINAL Attached						

\* Attach Additional Sheets If Necessary

Phone: 575.748.1829

Date: 5/2/16

269-3671