State of New Mexico Energy Minerals and Natural Resources

.

.

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr.. Santa Fc, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

	-c, NM 87505	
	on and Corrective Action	n
MAB1612340054	OPERATOR	🛛 Initial Report 🗌 Final Report
Name of Company: COG Operating LLC 224/3/	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: BUENA VISTA 2 STATE #001H	Facility Type: Battery	
Surface Owner: State Mineral Owner	: State	API No. 30-015-40789
LOCATIC	ON OF RELEASE	
	h/South Line Feet from the East	/West Line County East Eddy
		Fast Fudy
Latitude 32.59815	22 Longitude -103.9353943	,
	E OF RELEASE	
Produced Water	Volume of Release: 8 bbls PW	Volume Recovered: 5 bbls PW
Source of Release:	Date and Hour of Occurrence:	Date and Hour of Discovery:
littings/Connections	4/14/2016 10:00 am	4/14/2016 10:00 am
Was Immediate Notice Given?	If YES, To Whom?	
🗌 Yes 🔲 No 🖾 Not Required	d	
3y Whom?	Date and Hour:	
Was a Watercourse Reached?	If YES, Volume Impacting the Wa	itercourse.
f a Watercourse was Impacted, Describe Fully.*		Alla
		ARTESIA DISTRICT APR 29 2016
	ck was dispatched to recover all standi	ARTESIA DISTRICT APR 29 2016 ng fluid. RECEIVED
Describe Cause of Problem and Remedial Action Taken.* This release was caused by a pipe fitting on battery lines. A vacuum tru Describe Area Affected and Cleanup Action Taken.*	ck was dispatched to recover all standi	ARTESIA DISTRICT APR 29 ZUIG
This release was caused by a pipe fitting on battery lines. A vacuum tru Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined containment of the facility. Concl		···CEIVED
This release was caused by a pipe fitting on battery lines. A vacuum tru Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined containment of the facility. Concl he release. I hereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedi or the environment. In addition, NMOCD acceptance of a C-141 report	no will have the spill site inspected to d the best of my knowledge and underst notifications and perform corrective ac the NMOCD marked as "Final Report" ate contamination that pose a threat to does not relieve the operator of respon	letermine any possible contamination from land that pursuant to NMOCD rules and ctions for releases which may endanger does not relieve the operator of liability ground water, surface water, human health hsibility for compliance with any other
This release was caused by a pipe fitting on battery lines. A vacuum tru Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined containment of the facility. Concl he release. Thereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release bublic health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedi or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations.	no will have the spill site inspected to d the best of my knowledge and underst notifications and perform corrective ac the NMOCD marked as "Final Report" ate contamination that pose a threat to does not relieve the operator of respon	letermine any possible contamination from tand that pursuant to NMOCD rules and etions for releases which may endanger ' does not relieve the operator of liability ground water, surface water, human health
This release was caused by a pipe fitting on battery lines. A vacuum tru Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined containment of the facility. Concl he release. I hereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedi or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations.	no will have the spill site inspected to d the best of my knowledge and underst notifications and perform corrective ac the NMOCD marked as "Final Report" ate contamination that pose a threat to does not relieve the operator of respon OIL CONSER	letermine any possible contamination from tand that pursuant to NMOCD rules and etions for releases which may endanger does not relieve the operator of liability ground water, surface water, human health hsibility for compliance with any other VATION DIVISION
This release was caused by a pipe fitting on battery lines. A vacuum tru Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined containment of the facility. Concl he release. Thereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release bublic health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedi or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations.	no will have the spill site inspected to d the best of my knowledge and underst notifications and perform corrective ac the NMOCD marked as "Final Report" ate contamination that pose a threat to does not relieve the operator of respon	letermine any possible contamination from land that pursuant to NMOCD rules and etions for releases which may endanger does not relieve the operator of liability ground water, surface water, human health hsibility for compliance with any other VATION DIVISION
This release was caused by a pipe fitting on battery lines. A vacuum tru Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined containment of the facility. Concl he release. Thereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release bublic health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedi or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations.	no will have the spill site inspected to d the best of my knowledge and underst notifications and perform corrective ac the NMOCD marked as "Final Report" ate contamination that pose a threat to does not relieve the operator of respon OIL CONSER	letermine any possible contamination from tand that pursuant to NMOCD rules and etions for releases which may endanger does not relieve the operator of liability ground water, surface water, human health hsibility for compliance with any other VATION DIVISION
This release was caused by a pipe fitting on battery lines. A vacuum true Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined containment of the facility. Conclude release. I hereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedi or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations. Signature: Printed Name: Robert Grubbs Jr. Title: Senior Environmental Coordinator	the best of my knowledge and underst notifications and perform corrective as the NMOCD marked as "Final Report" ate contamination that pose a threat to does not relieve the operator of respon OIL CONSER Approved by Environmental Special Approval Date: 52110	letermine any possible contamination from land that pursuant to NMOCD rules and etions for releases which may endanger does not relieve the operator of liability ground water, surface water, human health hsibility for compliance with any other VATION DIVISION ist:
This release was caused by a pipe fitting on battery lines. A vacuum tru Describe Area Affected and Cleanup Action Taken.* This release occurred within the lined containment of the facility. Concl the release. I hereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remedi or the environment. In addition, NMOCD acceptance of a C-141 report federal, state, or local laws and/or regulations.	no will have the spill site inspected to d the best of my knowledge and underst notifications and perform corrective ac the NMOCD marked as "Final Report" ate contamination that pose a threat to does not relieve the operator of respon <u>OIL CONSER</u> Approved by Environmental Special Approval Date: 52110	letermine any possible contamination from tand that pursuant to NMOCD rules and etions for releases which may endanger does not relieve the operator of liability ground water, surface water, human health hsibility for compliance with any other VATION DIVISION ist: Expiration Date: N/A Les & GuideNifaGfied