
Subrit 1 Copy To Appropriate District	State of New Mexico		Form C-103 Revised July 18, 2013		
<sup>*</sup> <u>Sistrict I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-23204		
District III - (505) 334-6178	1220 South St. Fran		5. Indicate Type of Lease STATE SEE S		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM					
87505 SUNDRY NOT	FICES AND REPORTS ON WELLS		7. Lease Name or Un	it Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			Rushing NJ		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number		
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other			1		
2. Name of Operator			9. OGRID Number		
Yates Petroleum Corporation    3. Address of Operator			025575 10. Pool name or Wildcat		
105 South Fourth Street, Artesia, NM 88210			Penasco Draw; San Andres		
4. Well Location					
Unit Letter O :	330 feet from the South	line and	1650 feet from the	East line	
Section 6	Township 19S Rar		NMPM Eddy	County	
	11. Elevation (Show whether DR,				
ter at the second stated and the first of the second stated and the first of the second stated at the second state	3596'	GR	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	<u>i na </u>	
12 Check	Appropriate Box to Indicate N	ature of Notice	Papart or Other Da	to	
12. Check	Appropriate Box to indicate N	ature of Notice,	Report or Other Da	la	
	NTENTION TO:		SEQUENT REPO		
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WO					
	TEMPORARILY ABANDON CHANGE PLANS COMMENCE DE PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEI			AND A	
DOWNHOLE COMMINGLE			ТЈОВ Ц	i	
CLOSED-LOOP SYSTEM					
OTHER:		OTHER:	·		
	pleted operations. (Clearly state all p vork). SEE RULE 19.15.7.14 NMAC				
proposed completion or re		. For Multiple Co	inpletions. Attach went	ore diagram of	
Yates Petroleum Corporation plans	to plug and abandon this well as foll	ows:			
1. MIRU all safety equipment as n	eeded. TOH with production equipm	nent.			
2. Set a 4-1/2" CIBP at 2297' and cap it with 40 sx Class "C" cement. This will place a 568' plug on top of the CIBP and across Glorieta					
3. Spot a 25 sx Class "C" cement plug at 997'. This will place a 360' plug from 617'-997' across casing shoe. WOC and tag, reset if necessary.					
2	olug at 485'. This will place a 485' p	lug from surface to	485' forming the surface	ce plug and casing shoe	
plug. WOC and tag, reset if necess		Approved for electric			
5. Cut off wellhead, install dry hol	e marker and clean location.	Approved for plugging Liability under bond is	of well bore only. retained pending receipt		
Wellbore schematics attached Wellbore schematics attached Wellbore schematics attached Wellbore schematics attached Which may be found at OCD Web Page under Events, www.cmprd.state.nm.us/ord ARTESIA DISTRUCTION					
		Forms, www.cmnrd.stat	e.nm.us/ocd.	ARTESIA DISTRICT	
				MAY 0 2 2016	
Spud Date:	Rig Release Da	ite:		0 2 2010	
·				RECEIVED	
WELL MUST BE PL	uceed BY 5/2/201	17		NECEIVED	
	n above is true and complete to the be	est of my knowledg	ge and belief.		
SIGNATURE (Ara) Hearto TITLE Regulatory Reporting Supervisor DATE April 28, 2016					
		natory reporting 5		<u>pm 20, 2010</u>	
Type or print name <u>Tina Hu</u>	ierta E-mail address: tinah	@yatespetroleum.c	om PHONE: <u>57</u>	5-748-4168	
For State Use Only					
APPROVED BY: MULTITLE COMPLIANCE OFFICER DATE 5/2/2016					
APPROVED BY: <u>futut 1 lyce</u> TITLE <u>COMPLIANCE OFFICER</u> DATE 5/2/10/6 Conditions of Approval (if any): SEE ATTACHED COA-5					
	A JUL MILACTA	v con/			




` \*4

,

.

۴



# \*

.

. .

•

#### NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

## CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:	
Well Name & Number:	
API #:	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.

10. Plugs may be combined after consulting with and getting approval from NMOCD.

- 11. Minimum WOC time for tag plugs will be 4 Hrs.
- 12. 19.15.7.16 : B. In the case of a dry hole, a complete record of the well on form C-105 with the attachments listed in Subsection A of 19.15.7.16 NMAC shall accompany the notice of intention to plug the well, unless previously filed. The division shall not approve the plugging report or release the bond the operator has complied with 19.15.7.16 NMAC.

DATE:

### **APPROVED BY:**

**REVISED:11/2015** 

## **GUIDELINES FOR PLUGGING AND ABANDONMENT**

#### DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - o Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- r If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
  Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).