Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NMNM70335

Do not use this form for proposals to drill or to re-enter an Artesia abandoned well. Use form 3160-3 (APD) for such proposals.								
					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agree	ment, Name and/or No.		
Type of Well		8. Well Name and No. LIVINGSTON RIDG 3						
Name of Operator CONOCOPHILLIPS COMPANY E-Mail: GREG BRYANT@BASICENERGYSERVICES.COM					9. API Well No. 30-015-26437-00-S1			
3a. Address MIDLAND, TX 79710 1810	3b. Phone No. (included Ph.: 432-563-335		·-···	10. Field and Pool, or Exploratory CABIN LAKE				
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description)				11. County or Parish, a	and State		
Sec 1 T22S R30E SWNW					EDDY COUNTY	, NM		
12. CHECK APPE	ROPRIATE BOX(ES) TO	INDICATE NAT	URE OF N	NOTICE, RE	PORT, OR OTHER	RDATA		
TYPE OF SUBMISSION								
Notice of Intent	☐ Acidize	□ Deepen		□ Producti	on (Start/Resume)	■ Water Shut-Off		
_	☐ Alter Casing	☐ Fracture Tr	eat	☐ Reclama	tion	■ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	☐ New Const	ruction	☐ Recomp	lete	☐ Other		
☐ Final Abandonment Notice	☐ Change Plans	Plug and A	bandon	☐ Temporarily Abandon				
	Convert to Injection	□ Plug Back] Plug Back		isposal			
Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit. 1) MIRU, NDWH, NUBOP. PC 2) Set 5-1/2" CIBP @ 6,500'. (3) Spot 25sx cmt @ 6,030' - 5 4) Spot 25sx cmt @ 4,650' - 4 5) Spot 25sx cmt @ 4,650' - 4 5) Spot 25sx cmt @ 3,830' - 3 6) Perf @ 1,500' - Sqz 40sx cm 7) Perf @ 600' - Sqz 55sx cmt 8) Perf @ 600' - Circ 25sx cmt 9) Top off well. RDMO. Cut off	operations. If the operation results and onment Notices shall be filed in all inspection.) OOH w/ Prod Equip Circ hole w/ MLF. Cap BP v. 880' (500' - WOC-Tag mt to 1,400' - WOC-Tag to 423'. WOC-Tag os urface	Its in a multiple complonly after all requirer N/ 25sx cmt to 6,3 Perf Sq2 C	letion or reconnents, includ	ompletion in a n ing reclamation ω	ew interval, a Form 3160, have been completed, a	0-4 shall be filed once and the operator has		
NMACD					NIM OIL CONS ARTESIA D	SERVATION ISTRICT		
Prairie Chicken COAs Attached					MAY 1.9	2016		
14. I hereby certify that the foregoing is Co Name (Printed/Typed) GREG BR	Electronic Submission #33 For CONOCOPH mmitted to AFMSS for proce			e Carlsbađ 03/21/2016 (1		IVED		
Signature (Floritonic S		Data	02/47/2	016				
Signature (Electronic S	THIS SPACE FOI	R FEDERAL OR	03/17/2 STATE		SE			
Approved By All World			Ena	·		Date 5/16/16		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu		e CFO						

WELLBORE SKETCH ConocoPhillips Company - Lower 48 - Mid-Continent BU / Permian Operations

Date March 8, 2016 RKB 数 <u>3314'</u> CF 数 <u>3312'</u> Subarea Lease & Well No. Livingston Ridge Legal Description 1450 FNI, & 660 FWL, Sec. 1, T-22S, R-30E 17 1/2" Hole County Eddy New Mexico Field Cabin Lake (Delaware) Date Spudded 11/20/1990 Rig Released: 12/9/1990 13 3/8" 61# K-55 @ 473" AP! Number 30-015-26437 Freducing Cmt'd w/ 800 sxs. are 218 sxs Status TOC @ Surface State Lease No. NM-70335 017643 OGRID No. Top Salt @ 587 Stimulation History: Lbs. Max Max interval Date Type Gais Sand Press ISIP Pate Down 1/10/1991 Perf 7406-7428 & 7456-7536 7406-7536 1/11/1991 7 1/2% NEFE 2000 160,000 TOC 5 1/2" @ 1560" (TS) 7406-7536 1/12/1991 Potyemutsian 54.CC0 4/5/1991 Perf 7290-7322 w/ 2 SPF 7290-7322 4/6/1991 7 1/2% NEFE 6**CO** Base Salt @ 1550 7290-7322 4/8/1991 Polyemulsion 17,000 60.000 4/11/1991 Port 6568-6590 w/ 2 SPF 6568-6590 4/12/1991 7 1/2% NEFE 500 Castile 1555 9568-6590 4/16/1991 Polyemulsion 34,000 140,000 12 1/4" Hote 8 5/8" 24# K-55 @ 3700" Crnt'd w/ 1600 sxs, circ 185 sxs TOC @ Surface 6568-6593 7290-7322 7406-7428 Formation Tops: 7456-7526 Rustler Salado 626 Delaware 3750 4600 Cherry Canyon 7 7/8" Hole 5980 Brushy Canyon 5 1/2" 15.5# J-55 @ 7716' 7650 Bone Springs Crntid w/ 1150 sxs: FOC @ 1560' (TS) * PBTD @ 7668*

100

7716

RKB @ 3314 DF @

> 17 1/2" Hold P&S 25sx cmt @ 🙃 😙 13 3/8" 61# K-55 @ 473" Critia w/ 800 sxs, circ 218 sxs

TOC @ Surface

P&S 55ss cmt @ (**

TOC 5 1/2" @ 1560" (TS)

140-Surface P&S 404x cmt @ 1500: 5400

due to R-111-P + Cave/Karst

Subaren Livingston Ridge #3 1450 FNL & 660 FWL, Sec. 1, T-22S, R-30E Lease & Well No Legal Description County Eddy State New Mexico Field Cabin Lake (Delaware) Date Spudded 12/2/1990 11/20/1999 Rip Released: APLHumber 30-015-20437 Status Producing NM-70335

Stimulation History:

OGRID No. 017643

				Lbs.	Max		Max
Interval	Date	Type	Gats	5and	Press	<u> 1512</u>	Rate Down
	1/10/1991	Perl 7406-7428	& 7456-75	36			
7406-7536	1/11/1991	7 1/2% NEFE	2000				
7496-7536	1/13/1991	Potyemulsion	54,000	160.000			
	4/5/1991	Parl 7290-7322	w/ 2 SPF				
7790-7322	4/6/1901	7.1/2% NEFE	600				
7290-7322	4/8/1991	Polyemutsion	17,000	60,000			
	4/11/1991	Perl 6568-6590					
6568-6590	4/12/1991	7 1/2% NEFE	500				
6568-6590	4/16/1901	Polyemulsion	34,000	140,000			

12 1/41 Hale B 5/8" 24# K-55 @ 3700" Cmt'd w/ 1600 sxs, circ 185 sxs TOC @ Surface

Forfy Attach to Sq Z

Spot 255x cmt @ 4650'-4500'

Spot 25sx cmt @ 6030'-5860'

Spot 25sx cmt @ 6500'-6350' Sat CIBP @ 6500

6568-6590

7290-7322

7406-7428

7450-7536

7 7/81 Hale 5 1/2" 15.5# J-55 @ 7716" Cmt'd w/ 1150 sxs. TOC @ 1560 (TS)

PBTD @ 7669 TD @ 7716 то 🧟

Formation Tops: 315 Rustler Salado 620 Delaware 3780 Cherry Casyon 4600 5980 Brushy Canyon Bone Springs 7650

State Lease No.

Date. March 8, 2016

1

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.

- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
 - 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
 - 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
 - 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias **Environmental Protection Specialist** 575-234-6230

Linda Denniston **Environmental Protection Specialist** 575-234-5974

Henryetta Price **Environmental Protection Specialist** 575-234-5951

Dara Glass **Environmental Protection Specialist** 575-234-5924

Shelly Tucker **Environmental Protection Specialist** 575-234-5979