

Submit 1 Copy	To Appropriate District	State of New Me	exico	Form C-103 Revised July 18, 2013	
⁴ District I – (575) 393-6161 1625 N. French Dr., Hanna Dilles CONSERVITIES, Minerals and Natural Resou			iral Resources	WELL API NO.	
<u>District II</u> – (57) 811 S. First St.	Submit 1 Copy To Appropriate District Office District 1 – (575) 393-6161 1625 N. French Dr., HANA OILS CONSERVITION, Minerals and Natural Resources District II – (575) 748-1283 ARTESIA DISTRICT District II – (575) 748-1283 ARTESIA DISTRICT 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 MAY 1 2 2010 IL CONSERVATION DIVISION 1220 South St. Francis Dr.			30-015-26623	
District_III - (50				5. Indicate Type of Lease STATE S FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NIRECEIVED 87505				6. State Oil & Gas Lease No. K-6385	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				7. Lease Name or Unit Agreement Name Dee 36 SE State	
PROPOSALS.) 1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other				8. Well Number 3	
2. Name of Operator				9. OGRID Number	
Yates Petroleum Corporation 3. Address of Operator				025575 10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210				Canyon; Wolfcamp	
4. Well Location Unit Letter J : 1650 feet from the South line and 1980 feet from the East line					
Section			inge 24E	NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3603'GR					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
DEDEODM		ON TO: IND ABANDON 🖾	REMEDIAL WC		
TEMPORAR	RILLING OPNS P AND A				
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB					
DOWNHOLE COMMINGLE					
OTHER:			OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion. Approved for plugging of well bore only.					
Yates Petroleum Corporation plans to plug and abandon this well as follows: Lability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging)					
1. MIRU all safety equipment as needed. NU BOP.				which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.	
 Tag the CIBP at 7530' and cap it with 25 sx Class "H" cement. Set a 7" CIBP at 6400' and spot an 87 sx Class "C" cement plug on top of it. This will place a 535' plug on top of the CIBP up to 					
5865'. This will place a plug on top of open perfs and across Wolfcamp top and stage tool. WOC and tag, reset if necessary.					
 Set a 25 sx Class "C" cement plug from 3340'-3490'. This will place a plug across Bone Spring top. Set a 25 sx Class "C" cement plug from 1990'-2140'. This will place a plug across Glorieta top. 					
6. Set a 25 sx Class "C" cement plug from 1101'-1251'. This will place a plug across casing shoe. WOC and tag, reset if necessary.					
 7. Set a 25 sx Class "C" cement plug from 0-150'. This will be the surface plug. WOC and tag, reset if necessary. 8. Cut off wellhead, install dry hole marker and clean location. 					
Wellbore schematics attached A SIEE ATTACHED COA-S					
Spud Date:		Rig Release D			
WELL MUST BE PLUBBED BY 5/13/2017 OR AN EXTENSION HAS TO BE					
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE TITLE Regulatory Reporting Supervisor DATE May 9, 2016					
Type or print For State Use		E-mail address: <u>ti</u>	nah@yatespetrole	eum.com PHONE: <u>575-748-4168</u>	
APPROVED Conditions of	BY: <u>funt</u> 2 f	TITLE_COM	Limbe of	<u> ĤCER DATE 5/13/2016</u>	





NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:	
Well Name & Number:	
API #:	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMQCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.

10. Plugs may be combined after consulting with and getting approval from NMOCD.

- 11. Minimum WOC time for tag plugs will be 4 Hrs.
- **12. 19.15.7.16 :** B. In the case of a dry hole, a complete record of the well on form C-105 with the attachments listed in Subsection A of 19.15.7.16 NMAC shall accompany the notice of intention to plug the well, unless previously filed. The division shall not approve the plugging report or release the bond the operator has complied with 19.15.7.16 NMAC.

DATE:

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).