

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-015-21758

5. Indicate Type of Lease
STATE ☒ FEE ☐

State Oil & Gas Lease No.

8. Lease Name or Unit Agreement Name
Eddy FV State COM

9. Well Number #1

9. OGRID Number
17985

10. Pool name or Wildcat
Penlon Bone Spring East

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Premier Oil & Gas, Inc.

3. Address of Operator
PO BOX 1246 Artesia, NM 88211-1246

4. Well Location

Unit Letter H : 1980 feet from the North line and 990 feet from the East line
Section 25 Township 20S Range 27E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3352' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐


13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Premier Oil & Gas Inc. wishes to perform workover in the Bone Springs on the subject well and remove it from T/A status. If the two zones proposed are shown to be unproductive or uneconomical, Premier wishes to Plug and Abandon the well.


1. Drill out CIBP @ 6270'.
2. Perforate from 8182 - 8198'.
3. Acidize/Test perforations.
4. If zone is not economical, set CIBP @ 8100' w/35" cmt.
5. Perforate from 5822 - 5890'.
6. Acidize/Test perforations.
7. If zone is not economical, set CIBP @ 5750'.
8. Premier will file to Plug and Abandon well with a final wellbore diagram.

B. Spg
4790-8580

Spud Date:




Rig Release Date:



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE



TITLE: Vice President


DATE: 6/2/2016

Type or print name Daniel Jones

E-mail address: dan.jones@premieroilgas.com PHONE: 972-470-0228

For State Use Only

APPROVED BY:



TITLE

"Geologist"

DATE

6/7/16

Conditions of Approval (if any):

Eddy FV STATE COM #1
1980' FNL & 990' FEL
H-25-205-27E

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 06 2016

30-015-21758

Eddy, NM

RECEIVED
Zerd: 17' AGL
GL: 3352'
KB: 3369'

