

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

JUN 16 2016

Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. *260737* Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS 026H Facility Type: Exploration and Production

Surface Owner: Federal Mineral Owner: API No. 30-015-42375

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	23	24S	30E	100		1040		Eddy

Latitude: 32.210419 Longitude: 103.846107

NATURE OF RELEASE

Type of Release: Crude Oil and Produced Water	Volume of Release: 16 barrels Oil, 15 barrels of Produced Water	Volume Recovered: 10 barrels Oil, 10 barrels Produced Water
Source of Release: Stuffing Box	Date and Hour of Occurrence: 6-15-16 @ 7:00am	Date and Hour of Discovery: 6-15-16 @ 7:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson via Email	
By Whom? Bradley Blevins	Date and Hour: 6-15-16 @ 1:58pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Packing failed in the stuffing box releasing fluid to ground surface surrounding the wellhead. A vacuum truck was called to the location to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.*

Packing failed in the stuffing box releasing fluid to ground surface surrounding the wellhead. A vacuum truck was called to the location to recover the standing fluid. All fluid remained on the well pad. A remediation crew will be sent to the location to remove the saturated soils and conduct a sampling event.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>H. Blevins</i>	
Title: Assistant Remediation Foreman	Approval Date: 6/17/16	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input checked="" type="checkbox"/>	
Date: 6-16-16 Phone: 432-214-3704	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 7/17/16

2RP-3745