

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

JUL 21 2016

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1620727724

Name of Company Breitburn <u>370080</u>		OPERATOR	<input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report
Address 1401 McKinney St Suite 2400 Houston TX 77010		Contact Matt Cottrell	
Facility Name State 647 711 SWD		Telephone No. 432-967-7266	
		Facility Type SWD	
Surface Owner COG		Mineral Owner State of New Mexico/ Breitburn	API No. 30-015-02055

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	27	18S	28 E	2310	South	1650	West	Eddy

Latitude 32.71950 Longitude 104.16423

NATURE OF RELEASE

Type of Release Fire	Volume of Release 5 bbls water	Volume Recovered None
Source of Release Burnt Tanks	Date and Hour of Occurrence 7/8/16	Date and Hour of Discovery 7/8/16
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*

Lightning struck the facility around 9 PM causing 2 fiber glass tanks to catch fire and burn to the ground. We got our pumper out and he shut in the wells going to this facility.

Describe Area Affected and Cleanup Action Taken.*

The affected area was contained inside the berm. We dug out 18 to 24 inches inside the berm and are in the process of rebuilding this facility. We will be sending soil samples to Cardinal lab in Hobbs New Mexico. This is a lined facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Matt Cottrell</u>		OIL CONSERVATION DIVISION	
Printed Name: Matt Cottrell		Approved by Environmental Specialist <u>[Signature]</u>	
Title: EHS Coordinator		Approval Date: <u>7/21/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: matt.cottrell@breitburn.com		Conditions of Approval:	
Date: 7-21-2016 Phone: 432-967-7266		Attached <input type="checkbox"/>	

Remediation per O.C.D. Rules & Guidelines

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 8/25/16

2RP-3796

* Attach Additional Sheets If Necessary