Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources Revised July 18, 2013 District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 30-015-20894 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District_III - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 STATE X FEE \square Santa Fe, NM 87505 District IV -(505) 476-3460 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM B-2071-28 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CHUKKA - WDW - 2 DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number: WDW - 2 1. Type of Well: Oil Well Gas Well X Other: Injection Well 2. Name of Operator: 9. OGRID Number: 15694 HollyFrontier Navaio Refining LLC. 10. Pool name or Wildcat: 3. Address of Operator: P.O. BOX 159, ARTESIA, NM. 88211; 501 E. MAIN, ARTESIA, NM. 88210 PENN 96918 4. Well Location Unit Letter: E : 1980 feet from the NORTH line and 660 feet from the WEST Township 18S County: EDDY Section Range 27E NMPM 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3607' GL., 3623' RKB 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: REMEDIAL WORK PERFORM REMEDIAL WORK □ PLUG AND ABANDON П ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS П COMMENCE DRILLING OPNS.□ P AND A PULL OR ALTER CASING П MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE П CLOSED-LOOP SYSTEM \Box OTHER: \Box X: OTHER: PERFORM PRESSURE FALLOFF TEST 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. July 22, 2016 -Install bottomhole gauges into WDW-1, WDW-2, and WDW-3 by 11:45am. Continue injection into all three wells. July 23, 2016 - Continue injection into all three wells. July 24, 2016 - At 2:00 PM, the offset wells WDW-1 and WDW-3 will be shut-in. A constant injection rate will be established for WDW-2 at 160 GPM and continue for a 30-hour injection period. Do not exceed 1400 psig wellhead July 25, 2016 – At 8:00pm, WDW-2 will be shut in for a 30-hour falloff period. WDW-1 and WDW-3 will remain shut-in. July 26, 2016— All three wells will continue to be shut in while monitoring falloff pressure in all three wells. July 27, 2016 – At 8:00am, acquire downhole pressure gauges from all three wells. Tag bottom of fill and come out of hole very slowly, making 7-minute gradient stops while coming out of WDW-2 every 1000 feet (7000 ft, 6000 ft, 5000 ft, 4000 ft, 3000 ft, 2000 ft, 1000 ft, surface). Turn the wells back to Navajo personnel NM OIL CONSERVATION ARTESIA DISTRICT JUL 13 2016 Spud Date: Rig Release Date: RECEIVED I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE: < Type or print name: Lewis Dade E-mail address: Lewis.Dade@hollyfrontier.com PHONE: 575-746-5281 For State Use Only

TITLE

in Opapec-adu DATE 7-13-16

Conditions of Approval (if any):

APPROVED BY