

**JUL 25 2016**

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
Submit Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

<b>NAME</b> <u>NAB 1421054550</u>		<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company <u>Burnett Oil Co. Inc.</u>		Contact <u>Leslie Garvis</u>			
Address <u>801 Cherry Street, Suite 1500, Fort Worth, TX 76102</u>		Telephone No. <u>817-573-8730</u>			
Facility Name <u>Gissler B 3-3</u>		Facility Type <u>Tank Battery</u>			
Surface Owner <u>BLM</u>		Mineral Owner <u>BLM</u>		API No. <u>30-015-41276</u>	

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	11	17S	30E	330'	South	820'	West	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release <u>Produced Water</u>	Volume of Release <u>40 bbls</u>	Volume Recovered <u>10 bbls</u>
Source of Release <u>Transfer line</u>	Date and Hour of Occurrence <u>7/18/16 1530</u>	Date and Hour of Discovery <u>7/18/16 1530</u>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <u>Verbal - BLM/S.Tucker, Vmail - OCD/H.Paterson</u>	
By Whom? <u>Leslie Garvis</u>	Date and Hour <u>7/18/16 1730</u>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A


Describe Cause of Problem and Remedial Action Taken.\*

Transfer Line Ruptured. Line was repaired and put back into service.

Describe Area Affected and Cleanup Action Taken.\*

Approx. 50% of the spill stayed on the lease road. The rest flowed into a 2'x30' section on the east side of the road. Two other spots went onto the Gissler B 22 location which was previously reclaimed. Impacted area to be remediated to regulatory standards.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: _____		<b>OIL CONSERVATION DIVISION</b>	
		Approved by Environmental Specialist: 	
Printed Name: <u>Leslie Garvis</u>		Approval Date: <u>7/26/16</u>	Expiration Date: <u>N/A</u>
Title: <u>Regulatory Coordinator</u>		Conditions of Approval:	
E-mail Address: <u>lgarvis@burnettoil.com</u>		Attached <input type="checkbox"/>	
Date: <u>7/25/16</u>	Phone: <u>817-583-8730</u>	<b>Remediation per O.C.D. Rules &amp; Guidelines</b>	

**SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 9/1/16**

\* Attach Additional Sheets If Necessary

200-3804