Submit 1 Copy To Appropriate District Office	State of New Me			Form C-103
<u> [Astrict I</u> – (575) 393-6161	Energy, Minerals and Natu	ral Resources	WELL ARING	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH CONCERNATION	DIMOTONI	WELL API NO. 30-015-23237	
811 S. First St., Artesia, NM 88210	ia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	MO Rio Brazos Rd. Aztec. NM 87410		STATE FEE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	/505	6. State Oil & Gas Le	ease No.
87505			L-122	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name Penasco IW Shallow 8. Well Number	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other		3	
2. Name of Operator			9. OGRID Number	
Yates Petroleum Corporation			025575	
3. Address of Operator			10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210			Penasco Draw; SA-Yeso	
4. Well Location Unit Letter N:	330 feet from the South	line and2	2310 feet from the	West line
Section 31		nge 25E	NMPM Eddy	County
11. Elevation (Show whether DR. RKB, RT, GR, etc.) 3643'GR				
\$	3043	GK	<u> </u>	
12. Check A	Appropriate Box to Indicate N	ature of Notice,	Report or Other Dat	ta
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WO				
TEMPORARILY ABANDON				ND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	ТЈОВ 🗌	
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM OTHER:	П	OTHER:		П
13. Describe proposed or comp	leted operations. (Clearly state all p	pertinent details, and		
of starting any proposed wo proposed completion or rec	ork). SEE RULE 19.15.7.14 NMAC ompletion.	C. For Multiple Con	npletions: Attach wellb	ore diagram of
Yates Petroleum Corporation plans to plug and abandon this well as follows:				
MIRU all safety equipment as needed. NU BOP.				
2. Set a CIBP at 2623'. Spot a 100 sx Class "C" cement plug from 1223'-2623' and tag. Spot a 90 sx Class "C" cement plug from 1223'				
up to surface. This will fill the entire wellbore up from the CIBP to the surface. WOC and tag plug.				
3. Cut off wellhead, install marker a	ind clean up location as per regulate	·d.		
Wellbore schematics attached			- NA	OIL CONSERVATION
	Approved for plugging of Liability under bond is re			ARTESIA DISTRICT
	of C-103. (Subsequent Re	port of Well Plugging)		JUL 19 2016
	which may be found at C Forms, www.cmnrd.state			30L 1 9 7010
			_	DECETVEN
				RECEIVED
S. ADam	D: D 1 D	,	_	
Spud Date:	Rig Release Da	ite:		
WELL MUST BE	PLUDGED BY 7/2	12/2017	Roswell	(1, tage
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
Thereby certify that the information	h	st of my knowledge	cand ballet. Agr	ifer area)
11:			\mathcal{U}	
SIGNATURE (L'XIII) HE	TITLE Regi	ılatory Reporting Sı	upervisor DATE <u>Ju</u>	ıl <u>y 19, 2016</u>
Type or print name Tina Hue	rta E-mail address: tinah	@yatespetroleum.co	om PHONE:57:	5-748-4168
For State Use Only	5 man address. than	wymesponoromani.et	<u> </u>	2 1 10 1 1 00
11/1	1. 1 a. n.	14.44	inch or los	11011
APPROVED BY: full Conditions of Approval (if any):	TITLE COMPL	IANEC OFF	EER DATE 7/22	12016



