

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

AUG 02 2016

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

**NAB 1621754389** **260737**

<b>OPERATOR</b> <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report	
Name of Company: BOPCO, L.P.	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Barney BEF Federal #001	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-26799	

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	1	22S	30E	660	South	2445	East	Eddy

Latitude 32.415680° Longitude -103.833531°

NATURE OF RELEASE

Type of Release	Crude Oil and Produced Water	Volume of Release	46 bbl PW 16 bbl Oil	Volume Recovered	5 bbl PW 5 bbl Oil
Source of Release	Poly Flow Line	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	7/29/2016 10 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher/Heather Patterson (NMOCD), Shelly Tucker (BLM)		
By Whom?	Amy Ruth	Date and Hour	7/29/2016 5:54 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		
If a Watercourse was Impacted, Describe Fully.* N/A					
Describe Cause of Problem and Remedial Action Taken.* Poly flow line rupture, possibly due to paraffin plug. Line was repaired.					
Describe Area Affected and Cleanup Action Taken.* Leak affected approximately 6,098 sq. ft. of pasture immediately west of the well and battery location. Standing fluids were recovered. Over-sprayed areas and vegetation were washed with Micro-blaze and saturated surface soils were scraped up and stockpiled on plastic.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amy C. Ruth		Signed By:  Approved by Environmental Specialist:	
Title: EHS Remediation Specialist		Approval Date: 8/2/16	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com		Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 4/8/16	
Date: 8/2/2016 Phone: 432-661-0571		Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-3815