NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs. NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

AUG 18 2016

Form C-141 Revised August 8, 2011

Submin FCO Was inpropriate District Office in accordance with 19.15.29 NMAC.

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and	Corrective Action
--------------------------	-------------------

DAB.	1623	2505	3 D			OPERA'	ΓOR	🛛 Initi	al Report	Final Report	
Name of Co	ame of Company Oxy Permian Ltd. //1/9/0 Contact Casey Summers										
Address 6 Desta Drive, Midland, TX 79705						Telephone No. (575) 513-8289					
Facility Name Federal 12 #001 South CTB						Facility Type Battery					
Surface Owner BLM Mineral Owner						API No. 30-015-26742					
Johnson Date Junioral Owner At 110, 30-013-20/42											
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the	Nonh	th/South Line Feet from the East/West Line County					
	.,	226	3.5						n a		
M	12	228	31E	Eddy County, NM							
Latitude N 32.40031° Longitude W 103.73792°											
NATURE OF RELEASE											
Time of Pala	ora Oilo	nd Droducad s	valae	INAI	UKE			il Voluma l	Pacayarad	7 bbls	
Type of Release Oil and Produced water					Volume of Release 2 bbls oil. 12 bbls produced water Volume Recovered 7 bbls						
Source of Re	lease Pui	np failure cau	sed the tar	rk to spill over			Date and Hour of Occurrence Date and Hour of Discovery				
				<u> </u>		08/05/2010				-	
Was Immedia	ate Notice (If YES, To		NIVOGD (D1 14	
				No Not Re	equired	Mike Brate	cher, Heather Patt	erson- NMOCD; S	helly Tucke	t- BLM	
By Whom?			nat, Inc.				Tour 08/05/201				
Was a Water	course Read		Yes 🗵	1 No		If YES, Vo	olume Impacting t	the Watercourse.			
			J 165 🗠								
If a Watercou	irse was Im	pacted, Descr	ibe Fully.	•							
Describe Cau	se of Probl	em and Reme	dial Actio	n Taken.*				WW.X.4.4.4			
				ak 2 bbls of oil an	id 12 b	bls of produce	d water. A vacuu	m truck recovered	7 bbls of flu	tids and the pump	
was restored	DUCK TO WO	rking conditio	m.								
Describe Are	a Affected	and Cleanup	Action Tal	кеп.*							
		•									
				n location inside t	he bern	n of the batter;	y. Remediation w	vill be completed in	accordance	with a plan	
approved by	both NMO	CD and the B	LM.								
1 hereby certi	fy that the	information o	iven shove	is true and comn	lete to	the best of my	knowledge and u	inderstand that pur	sugnt to NM	OCD rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
tederal, state.	, or local la	ws and/or regi	ujanons.				OIL CON	SERVATION	DIVICIO	781	
1	-	//	<u> </u>		ļ		OIL CON	SERVATION .	DIVISIO	<u> </u>	
Signature:	M	/ \			Ì		G! 15	4// 1	/ .		
Approved by Environmental Specialist:								<u></u>			
Printed Name: Casey Summers											
Tida: NM	Cariename	ntal Advisor			1	Approval Da	''' 21121)	6 Emiliar	Date: N	/A	
Title: NM	LIVITORITE	indi Auvisur				Approvai Da	ic. 011011	Expiration	Date: / V		
E-mail Addre	ess: Case	v_Summers@	oxy.com			Conditions o	Approvals = -				
Remediation per O.C.D. Rules & Guidpanæacd								l 🛄			
Date: 9-18-10 Phone: (575) 513-8289 SUBMIT REMEDIATION PROPOSAL NO											
Attach Addi	tional She	ets If Neces	sary	**************************************		LATER TH	IAN:	4116		100 2021	
										2RP-383"	