Name of Company     Oxy Permian Ltd.     Contact     Casey Summers       Address     6 Desta Drive, Midland, TX 79705     Telephone No.     (575) 513-8289       Facility Name     SDS 11 Federal #1 SWD     Facility Type     SWD	t Office in 19 NMAC.	
Santa Fe, NM 87305     Release Notification and Corrective Action     NAB   \u03c6 22 \u23c8 32 \u23c8   7   OPERATOR   Initial Report   Fin     Name of Company   Oxy Permian Ltd.   Contact   Casey Summers     Address   6 Desta Drive, Midland, TX 79705   Telephone No.   (575) 513-8289     Facility Name   SDS 11 Federal #1 SWD   Facility Type   SWD	al Report	
NAB1422832817OPERATORInitial ReportFinName of CompanyOxy Permian Ltd.ContactCasey SummersAddress6 Desta Drive, Midland, TX 79705Telephone No.(575) 513-8289Facility NameSDS 11 Federal #1 SWDFacility TypeSWD	al Report	
Name of Company     Oxy Permian Ltd.     Contact     Casey Summers       Address     6 Desta Drive, Midland, TX 79705     Telephone No.     (575) 513-8289       Facility Name     SDS 11 Federal #1 SWD     Facility Type     SWD	al Report	
Address 6 Desta Drive, Midland, TX 79705 Telephone No. (575) 513-8289   Facility Name SDS 11 Federal #1 SWD Facility Type SWD	······	
Facility Name     SDS 11 Federal #1 SWD     Facility Type     SWD		
Surface Owner BLM Mineral Owner API No. 30-015-27627	j	
LOCATION OF RELEASE		
Unit Letter Section Township Range Feet from the Nonh/South Line Feet from the East/West Line County		
F 11 24S 31E Eddy		
Latitude <u>N 32.23328°</u> Longitude <u>W 103.75060°</u>	V	
NATURE OF RELEASE		
Type of Release Oil Volume of Release 10 bbls Volume Recovered 10 bbls		
Source of Release     Gun barrel surge     Date and Hour of Occurrence     Date and Hour of Discovery       08/08/16     08/08/16     08/08/16     08/08/16     08/08/16		
Was Immediate Notice Given? If YES, To Whom? X Yes No Not Required Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom? Kathy Purvis @ BBC International Inc. Date and Hour 08/09/2016 @ 12:04 pm		
Was a Watercourse Reached? If YES, Volume Impacting the Watercourse.		
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* A gun barrel surge caused 10 bbls of oil to leak inside the lined containment on location. A vacuum truck recovered all free-standing fluid.		
Describe Area Affected and Cleanup Action Taken.*		
The affected area is approximately 80' x 4'inside the lined containment on location. Remediation was completed by removing the contaminated material and replacing it with clean material.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rule		
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may enda public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of like		
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, huma	n health	
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any of federal, state, or local laws and/or regulations.	ncr	
OIL CONSERVATION DIVISION		
Signature:		
Printed Name: Casey Summers Approved by Environmental Specialist:		
Title: NM Environmental Advisor Approval Date: 8 23/16 Expiration Date: N/A		
E-mail Address: Casey Summers@oxy.com		
Date: 8-22-16 Phone: (575) 513-8289		
Attach Additional Sheets If Necessary 2PP-383		

.

## ARTESIA DISTRICT

## NM OIL CONSERVATION