Form 3160-5 (August 2007)

## **UNITED STATES**

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS DO
Do not use this form for proposals to drill or to re-enter-enter-enter-enter-enter-enter-enter-enter-enter-enter-enter-enter-en ad Field Office Serial No.

abandoned wel	I. Use form 3160-3 (APD) for	such propodal (	Arte	6. If Indian, Allottee of S1a	Tribe	Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.		
Type of Well     Gas Well				8. Well Name and No. BARNSDALL FEDERAL 1		
2. Name of Operator Contact: EMILY FOLLIS APACHE CORPORATION E-Mail: Emily.Follis@apachecorp.com				9. API Well No. 30-015-29146-00-S1		
3a. Address 303 VETERANS AIRPARK LA MIDLAND, TX 79705	thone No. (include area code) 432-818-1801		10. Field and Pool, or Exploratory E EMPIRE			
4. Location of Well (Footage, Sec., T.			11. County or Parish, and State			
Sec 27 T17S R29E NWNE 33			EDDY COUNTY, NM			
12. CHECK APPE	ROPRIATE BOX(ES) TO IND	ICATE NATURE OF N	NOTICE, R	EPORT, OR OTHE	R DA	TA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize	□ Deepen	☐ Product	ion (Start/Resume)	<b>□</b> ′	Water Shut-Off
	☐ Alter Casing	☐ Fracture Treat	□ Reclam	lamation		Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	□ Recomp	olete		Other
☐ Final Abandonment Notice	Change Plans	Plug and Abandon	□ Tempor	rarily Abandon		
	☐ Convert to Injection	□ Plug Back	□ Water I	r Disposal		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  APACHE WOULD LIKE TO REQUEST THE FOLLOWING TO T.A. WELL:  1. Set CIBP within 50' of the existing top perf to isolate the existing Yeso perfs.  2. Top CIPB with 30 ft. of cement.  3. Perform MIT to confirm casing integrity, BLM will be notified for the witness SIDEMATTACHED FOR  4. Within 90 days Apache will submit a Sundry for uphole Recompletion in the CONFITTIONS OF APPROVAL specific perfs and Completion procedures.						
Accepted for record - NMOCD NM OIL CONSERVATION NM OIL CONSERVATION						
14. I hereby certify that the foregoing is  Com Name (Printed/Typed) EMILY FO	Electronic Submission #345813 For APACHE COR nmitted to AFMSS for processing	PORATION, sent to the C by PRISCILLA PEREZ or	Carlsbad	n System (16PP1821SE)	ARTE	SIA DISTRICT 17 2016
CMILT I OLLIG		TALL NEGOL	THE REGULATORY ANALYST		DECENTER	
Signature (Electronic S	Date 07/26/20	Pate 07/26/2016 RECEIVED				
	THIS SPACE FOR FE	DERAL OR STATE	OFFICE U	SE		
Approved By (BLM Approver Not l Conditions of approval, if any, are attached certify that the applicant holds legal or equ	t lease		PETROLEUM ENGINEER		Date 08/12/2016	
which would entitle the applicant to condu	<u> </u>	Office Carlsbac		<u> </u>		6.1 1.1
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a crime for tatements or representations as to any s	or any person knowingly and matter within its jurisdiction.	willfully to m	ake to any department or	agency	of the United

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
  - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
  - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
  - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
  - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
  - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

## Barnsdall Federal 1

- 1. Well is approved to be TA/SI for a period of 90 days or until 11/11/2016
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 11/11/2016
- 4. Contact BLM 24 Hrs. prior to setting of plugs so as it may be witnessed.