Submit One Copy To Appropriate District Office District I ARTESIA DISTRICTENERGY, Minerals and Natural Resources 1625 N. French Dr., Hobbs, M88240 District II CCD 1 2 2016	Form C-103 Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 812 S. First St., Artesia, NM 88210	WELL API NO. 30-015-35676
District III 1000 Rio Brazos Rd., Aztec, NM 87410 South St. Francis Dr. Santa Fe, NM 87505	 5. Indicate Type of Lease STATE FEE □ 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name State 2
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 004
2. Name of Operator TLT SWD, LLC	9. OGRID Number 287481
3. Address of Operator	10. Pool name or Wildcat
PO Box 1906, Hobbs, NM 88241	Livingston Ridge; Delaware, South
4. Well Location	
Unit Letter K: 1980 feet from the South line and 1980 feet from the West line Section 2 Township 23S Range 31E NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB	
OTHER:	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE CONTINUE Agent	DATE _09/07/2016_
TYPE OR PRINT NAME _M.Y. (Merch) MerchantE-MAIL: _mymerch@penrocoil.com PHONE: _575-492-1236 For State Use Only	
APPROVED BY: Let I for TITLE comp Charles of Conditions of Approval (if any):	FFICEN DATE 9/14/16