Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NIMO CONSERVATION
ARTESIA DISTRICTOR

FORM APPROVED OMB NO 1004-0135 Expires: July 31, 2010

OCT 11 20165. Lease Serial No. NMLC060524 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals. RECEIVE 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side. 8. Well Name and No. POSEIDON 3 FEDERAL 20 1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other 9 API Well No. 2. Name of Operator Contact: TERRI STATHEM 30-015-38249 CIMAREX ENERGY COMPANY E-Mail: tstathem@cimarex.com 10. Field and Pool, or Exploratory LOCO HILLS; GLOREITA YESO 3b. Phone No. (include area code) 3a. Address 202 S. CHEYENNE AVE, STE 1000 Ph: 432-620-1936 TULSA, OK 74103 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State EDDY COUNTY, NM Sec 3 T17S R30E SWSW 330FSL 1180FWL 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ■ Water Shut-Off ☐ Acidize Deepen ☐ Production (Start/Resume) ☐ Notice of Intent ■ Well Integrity : ☐ Alter Casing ☐ Fracture Treat ☐ Reclamation Subsequent Report □ New Construction □ Recomplete Other Casing Repair ☐ Temporarily Abandon ☐ Final Abandonment Notice □ Change Plans Plug and Abandon □ Water Disposal □ Convert to Injection Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once following completion of the involved operations. If the operation results in a multiple completion of recompletion in a new line with testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Accepted as to plugging of the well hore. Liability under hond is reselved until Plug and abandon sink hole. Surface restoration is completed, 2-24-11 CALLED DUNCAN WHITLOCK BLM TO SET UP PLUGGING SINK HOLE ON 2-28-11. 2-27-11 MET JAMES RUTLEY BLM ON LOCATION WITH CMT TRUCK. FILLED RATHOLE AND MOUSEHOLE WITH 4 YDS GROUT MIX WITHIN 3' OF SURFACE. PUMPED 6 YDS GROUT MIX IN SINK HOLE. MEASURE TOC @ 44'. PUMPED SECOND LOAD OF GROUT MIX 10 YDS TOC 41'. PUMPED THIRD LOAD GROUT MIX 10 YDS TOC @ 40' 6"." PUMPED: FORTH LOAD GROUT MIX 10 YDS TOC 39', PUMPED FIFTH LOAD GROUT MIX 10 YDS TOC 37' 4" WOC 4 HRS. TAG TOC @ 37' 3" 3-01-11 MEET JAMES RUTLEY ON LOC. CHECK SINK HOLE DEPTH, STILL AT 37'3". PUMP 10 YDS GROUT MIX. UP TO 36'. PUMP 10 YDS GROUT MIX. UP TO 34'. PUMP 10 YDS GROUT MIX UP TO 32' 4": PUMP 10 YDS GROUT MIX. UP TO 31' 6". WELDER CUT CAP OFF 20" CONDUCTOR PIPE. MEASURE SURFACE HOLE @ 176'. PUMP 10 YDS GROUT MIX IN CONDUCTOR AND CHECK TOC @ 103'. PUMP 9 YDS GROUT MIX TO FILL SURFACE HOLE TO 14. I hereby certify that the foregoing is true and correct Electronic Submission #351726 verified by the BLM Well Information System
For CIMAREX ENERGY COMPANY, sent to the Carlsbad Committed to AFMSS for processing by DEBORAH MCKINNEY on 09/19/2016 () TERRI STATHEM MANAGER REGULATORY COMPLIANCE Name (Printed/Typed) Signature (Electronic Submission) 09/19/2016 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Pccebled to I lecond Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or

Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or Agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction:

certify that the applicant holds legal or equitable title to those rights in the subject lease which would enough the applicant to conduct operations thereon.

Office

## Additional data for EC transaction #351726 that would not fit on the form

## 32. Additional remarks, continued

BOTTOM OF CELLAR. CUT 20" CONDUCTOR PIPE OFF 4" ABOVE BOTTOM OF CELLAR. WELD CAP ON CONDUCTOR PIPE. WELD 2" PIPE WITH WELL NAME PLATE IN MIDDLE OF CONDUCTOR PIPE. NAME PLATE 2" ABOVE GL. PUMP 1 YRD GROUT MIX LEFT ON TRUCK IN SINK HOLE. PUMP 10 YDS GROUT MIX IN SINK HOLE AND MEASURE TOP @ 30' 2". JAMES RUTLEY APPROVED. 3-02-11 BLM REQUESTED 50 YDS READY MIX W/ 3/4" ROCK FOR SINK HOLE - BLM INDICATED OK TO PUMP WITHOUT BLM ON LOCATION. PUMPED 10 YDS READY MIX TOC @ 27' 4". PUMPED 10 YDS READY MIX TOC @ 26' 6". PUMPED 10 YDS READY MIX TOC @ 24' 3". PUMPED 10 YDS READY MIX TOC @ 23'. BLM NOT ON LOCATION TO WITNESS. CONTACTED BLM - D WHITLOCK - CEMENT PUMPED. FILL VOID AREA WITH READY MIX THAT STARTS AROUND 17' FROM TOP AND GOES BACK TO THE EAST. BUT CAN'T SEE HOW FAR BACK IT GOES. PULLED CELLAR BOARDS OUT AND FILLED CELLAR WITH CALICHE TO BOTTOM OF WELL SEE HOW FAR BACK IT GOES. PULLED CELLAR BOARDS OUT AND FILLED CELLAR WITH CALICHE TO BOTTOM OF MARKER. PUT T-POST AROUND CELLAR WITH FLAGING TAPE.

3-03-11 CONTACTED BLM WITH CMT PLAN. TOC @ 23'. PUMPED 10 YDS 3/4" READY MIX. TOC @ 22' 1".

PUMPED 10 YDS 3/4" READY MIX. TOC @ 20' 8". PUMPED 10 YDS 3/4" READY MIX. TOC @ 19' 2". PUMPED 10 YDS 3/4" READY MIX. TOC @ 17' 2".

PUMPED 10 YDS 3/4" READY MIX. TOC @ 14' 11". BLM NOT ON LOCATION. CALLED BLM - CMT ABOVE VOID AREA. SPOKE W/ JIM AMOS FOR APPROVAL TO FILL WITH CALICHE. J AMOS TO BE ON LOCATION 3-4-11.

3-4-11 JIM AMOS ON LOC. PICTURES TAKEN OF SINK HOLE AND LOCATION. J AMOS APPROVED FILL SINK HOLE. REMOVE FENCE, FILL SINK HOLE WITH CALICHE FROM LOC PAD WITHIN 5' OF TOP OF HOLE. FILL LAST 4' WITH FILL DIRT AND PACK IN WITH DOZER. ADDED 3' MORE FILL DIRT AND PACK IN PLACE. INSTALL FENCE.