

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCT 12 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB11028728258

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. 260737	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV RR 006H	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No. 3001540580	

LOCATION OF RELEASE

Unit Letter D	Section 21	Township 25S	Range 30E	Feet from the 125	North/South Line	Feet from the 400	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	----------------------	------------------	----------------------	----------------	----------------

Latitude: 32.122643 Longitude: 103.893491

NATURE OF RELEASE

Type of Release: Crude Oil/ Produced Water	Volume of Release: 13 barrels oil and 25 barrels PW	Volume Recovered: 10 barrels oil and 15 barrels PW
Source of Release: Tee connection failed on wellhead.	Date and Hour of Occurrence: 10-10-16 @ 10:00am	Date and Hour of Discovery: 10-10-16 @ 10:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Jim Amos BLM	
By Whom? Bradley Blevins	Date and Hour: 10-10-16 @ 12:09pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A tee connection failed on the wellhead releasing oil and produced water to the well pad, a light mist to pasture area. A vacuum truck was called to the location and was able to recover 25 barrels of oil and PW mix. The connection was replaced and the well was put back online

Describe Area Affected and Cleanup Action Taken.*

An initial response crew will be dispatched to the location to conduct an initial scrape of the location and sampling event. The failed connection was replaced and the well was put back online.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 10/13/16	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines	
Date: 10/12/16 Phone: 432-214-3704	Attached <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 11/13/16

22P-3937