

OCT 19 2016

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Supplied to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

**NAB1629556325**

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU 261	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-34877
------------------------	------------------------	----------------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/ <u>South Line</u>	Feet from the	<u>East</u> /West Line	County
J	21	24S	30E		1980	1880		Eddy

Latitude: 32.20171 Longitude: 103.88377

### NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 20 barrels	Volume Recovered: 2 barrels
Source of Release: Failed Gasket on Heater Treater	Date and Hour of Occurrence: 10-18-16 @ 1:00pm	Date and Hour of Discovery: 10-18-16 @ 1:25pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Lease operator reported a release at the PLU 261 due to a failed heater treater gasket. The fluid was contained inside an earth berm around production equipment. A vacuum truck was called to the location and was able to recover 2 barrels of oil from the ground surface.

Describe Area Affected and Cleanup Action Taken.\*

A vacuum truck was called to the location and was able to recover 2 barrels of oil from the ground surface.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bradley Blevins		Approved by Environmental Specialist: <u>[Signature]</u>	
Title: Assistant Remediation Foreman		Approval Date: <u>10/19/16</u>	Expiration Date: <u>N/A</u>
E-mail Address: bblevins@basspet.com		Conditions of Approval:	
Date: <u>10/19/2016</u> Phone: 432-214-3704		<b>Remediation per O.C.D. Rules &amp; Guidelines</b> <b>SUBMIT REMEDIATION PROPOSAL NO</b> <b>LATER THAN: <u>11/30/16</u></b>	

\* Attach Additional Sheets If Necessary

Attached ☐

2RP-3A47