Submit 3 Copies To Appropriate District State of New Mexico	
	Form C-103
Office District I Energy, Minerals and Natural Resources	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
	30-005-63247
District II 1301 W. Grand Ave., Artesia, NM §8200BBSOK GONSERVATION DIVISION	5. Indicate Type of Lease
1000 Pio Prazos Pd. Aztec NM 87410	STATE 🛛 FEE 🗌
District IV NOV 0.92010 Santa Fe, NM 8/505	6. State Oil & Gas Lease No.
1220 S. St. Flancis Dr., Santa Fe, INM	. 25891
87505	
SUNDRY NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Willow Serie on #222 State
PROPOSALS.)	Willow Springs "33" State 8. Well Number
1. Type of Well: Oil Well 🔲 Gas Well 🛛 Other	8. Well Number 1
2. Name of Operator	9. OGRID Number
Reliance Energy, INC	149441 /
3. Address of Operator	10. Pool name or Wildcat
300 N Marienfield Suite 1100 Midland TX 79701	Pecos Slope Abo
4. Well Location	**************************************
	660feet from the West line
Section 33 Township 4S Range 25E	NMPM County - Chavez
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
11. Elevation (Show whether DR, KKB, KT, OK, etc., 3,581' GR	
	() () () () () () () () () () () () () (
	· ·
12. Check Appropriate Box to Indicate Nature of Notice, F	leport or Other Data
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON	
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🗌 CASING/CEMEN	ГЈОВ
	_
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Atta	ch wellbore diagram of proposed completion
or recompletion.	
9-19-16 Notified OCD of move in and rig up.	· 1
9-20-16 Set 5-1/2" CIBP @ 3515' on wireline. RIH tbg, tag, circulate well w/10# salt g	el mud. Spot 25 sx @ 3515'-3268'.
9-21-16 Tag top of cement at 3302'. Spot 25 sx @ 3069'-2822'. Perf & sqz 40 sx @ 18	
	$07 - 1707$, WOC_2 , 13270 , 1076 , $EE110$, 1
	09 -1707 . WOC. Tag @ 1098 . Fell &
sqz 40 sx @ 1502'-1341'. WOC.	
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU.	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU. Appreved ior plugging Appreved ior plugging (intriliv under bend in 1, intriliv under bend in 0, i C 103 (Subsequen 1, intriliv and be iound in C 103 (Subsequen torrai, mercented	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU. Appreved ior plugging Appreved ior plugging (intriliv under bend in 1, intriliv under bend in 0, i C 103 (Subsequen 1, intriliv and be iound in C 103 (Subsequen torrai, mercented	ulate 30 sx @ 60' to surface.
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circle RDMOWSU. Apprendent for plugging and the square for the square f	ulate 30 sx @ 60' to surface. of well bore only retrained pending receipt ARTESIA DISTRICT Report of Well Plugg TOM art OCD Web Page under at OCD Web Page state.nm.uslocd. NOV 1 6 2016 RECEIVED
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU. Appreved ior plugging Appreved ior plugging (intriliv under bend in 1, intriliv under bend in 0, i C 103 (Subsequen 1, intriliv and be iound in C 103 (Subsequen torrai, mercented	ulate 30 sx @ 60' to surface. of well bore only retrained pending receipt ARTESIA DISTRICT Report of Well Plugg TOM art OCD Web Page under at OCD Web Page state.nm.uslocd. NOV 1 6 2016 RECEIVED
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circle RDMOWSU. Apprendent for plugging and the square for the square f	ulate 30 sx @ 60' to surface. of well bore only retrained pending receipt ARTESIA DISTRICT Report of Well Plugg TOM art OCD Web Page under at OCD Web Page state.nm.uslocd. NOV 1 6 2016 RECEIVED
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circle RDMOWSU. Approved for pluggink Approved for pluggink Approved for pluggink Privation and the proved for pluggink Spud Date: Rig Release Date: Interformation above is true and complete to the best of my knowledge	ulate 30 sx @ 60' to surface. Stwell bore only, reciained pending receipt ARTESIA DISTRICT Report of Web Page under at OCD Web Page under NOV 1 6 2016 RECEIVED ARTESIA DISTRICT NOV 1 6 2016 RECEIVED
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circle RDMOWSU. Apprendent for plugging and the square for the square f	ulate 30 sx @ 60' to surface. of well bore only retrained pending receipt ARTESIA DISTRICT Report of Well Plugg TOM art OCD Web Page under at OCD Web Page state.nm.uslocd. NOV 1 6 2016 RECEIVED
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU. Apprened ior plugging Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Intel for plugging Apprened ior plugging TITLE_Engineering Tech	ulate 30 sx @ 60' to surface. If will bore only, retrained pending receipt retrained pending receipt ARTESIA DISTRICT NOV 1 6 2016 RECEIVED and belief. DATE <u>11/1/2016</u>
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU. Apprened iot plugging Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Jule Title Engineering Tech Type or print name Traci Coursey E-mail address: tcoursey@reimid.co	ulate 30 sx @ 60' to surface. If will bore only, retrained pending receipt retrained vell pluger ARTESIA DISTRICT Report of Web Page under at OCD Web Page under NOV 1 6 2016 RECEIVED and belief. DATE 11/1/2016
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU. Approved for plugeting Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Image: plugeting Type or print name Traci Coursey E-mail address: toursey@reimid.co For State Use Only Image: plugeting <	ulate 30 sx @ 60' to surface. of well bore only. of well bore only. retrained pending receipt ARTESIA DISTRICT Report of Well plugs THM OIL CONSERVATION ARTESIA DISTRICT NOV 1 6 2016 state.nm.uslocd. RECEIVED and belief. DATE 11/1/2016 m PHONE: 432-683-4816
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU. Approved for plugeting Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Image: plugeting Type or print name Traci Coursey E-mail address: toursey@reimid.co For State Use Only Image: plugeting <	ulate 30 sx @ 60' to surface. of well bore only. of well bore only. retrained pending receipt ARTESIA DISTRICT Report of Well plugs THM OIL CONSERVATION ARTESIA DISTRICT NOV 1 6 2016 state.nm.uslocd. RECEIVED and belief. DATE 11/1/2016 m PHONE: 432-683-4816
sqz 40 sx @ 1502'-1341'. WOC. 9-22-16 Tag @ 1313'. Perf & sqz 40 sx @ 792'-631'. WOC & tag @ 621'. Perf & circ RDMOWSU. Apprended iot plugging Spud Date: I hereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Jac Title Engineering Tech Type or print name Traci Coursey E-mail address: tcoursey@reimid.co	ulate 30 sx @ 60' to surface. of well bore only. of well bore only. retrained pending receipt ARTESIA DISTRICT Report of Well plugs THM OIL CONSERVATION ARTESIA DISTRICT NOV 1 6 2016 state.nm.uslocd. RECEIVED and belief. DATE 11/1/2016 m PHONE: 432-683-4816

-