

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 26 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	Chevron USA 4323	Contact	Josepha DeLeon
Address	6301 Deauville Blvd, Midland, TX 79706	Telephone No.	575-263-0424
Facility Name	Nereid 1 Federal No. 1H	Facility Type:	Oil Well

Surface Owner	BLM	Mineral Owner		API No.	30-005-29145-00-S1
---------------	-----	---------------	--	---------	--------------------

LOCATION OF RELEASE

Unit Letter	Section 1	Township 15S	Range 31E	Feet from the 660	North/South Line South	Feet from the 100	East/West Line East	County Chavez
-------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release: Oil & Water	Volume of Release 36 bbl of oil and 53 bbl of water	Volume Recovered 36 bbl of oil and 53 bbl of water
Source of Release: Heater Treater	Date and Hour of Occurrence 11/13/2016 08:00 AM	Date and Hour of Discovery 11/13/2016 08:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson, NMOCD and Harley Davis, BLM	
By Whom? Josepha DeLeon	Date and Hour 11/14/2016 07:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Not Applicable

Describe Cause of Problem and Remedial Action Taken.*



Heater treater.

Spill was into the secondary containment and all 89 barrels of fluid were recovered.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was called to the location and was able to recover 89 barrels of the fluid from secondary metal, plastic lined containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Josepha DeLeon	Approved by Environmental Specialist: 		
Title: HES Compliance Support - Environmental	Approval Date: 11/29/16	Expiration Date: N/A	
E-mail Address: jdx@chevron.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>	
Date: 11/22/2016	Phone: 575-263-0424		

* Attach Additional Sheets If Necessary

2RD-4019