

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

NOV 29 2016

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1633449255

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	WPX Energy Inc/RKI	Contact	Karolina Blaney
Address	5315 Buena Vista Dr.	Telephone No.	970 589 0743
Facility Name	RDX 17-2	Facility Type	Well Pad

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-36464
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	17	26S	30E	330	FSL	790	FEL	Eddy

Latitude: 32.030564 N Longitude: -103.8912511 W

NATURE OF RELEASE

Type of Release: Produced Water and Oil	Volume of Release: 10 Bbls	Volume Recovered: 5 Bbls
Source of Release: Wellhead	Date and Hour of Occurrence 11/2/2016	Date and Hour of Discovery 11/2/2016 - 10:30 hrs MT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NMOCD Heather Patterson & Michael Bratcher, BLM Shelly Tucker	
By Whom? Karolina Blaney	Date and Hour: 11/10/16- 17:00 hrs MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\* N/A

Describe Cause of Problem and Remedial Action Taken.\*

This spill was caused by mechanical failure. A T connection on a 4" poly line failed which resulted in a produced water spill; approximately 10 bbls was spilled with 5 bbls recovered. The spill was contained within the pipeline ROW and the well pad area.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area was mapped. The impacted area within the pad's perimeter was scraped off and stored on location pending disposal. The area within the pipeline ROW was mixed with a bioremediation product. The impacted areas will be sampled for BTEX, TPH, and chlorides in accordance with NM OCD Guidelines for Remediation of Leaks, Spills, and Releases. Further remediation will be based on the delineation results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Karolina Blaney</i>	OIL CONSERVATION DIVISION	
Printed Name: Karolina Blaney	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: 11/30/16	Expiration Date: N/A
E-mail Address: Karolina.blaney@wpxenergy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 11/16/2016	Phone: 970-589-0743	

\* Attach Additional Sheets If Necessary

2RP 4000