Form 3160-5 (September 2001)

UNITED STATES OCD-ARTESIA DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires January 31, 200

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or re enter an

Expires January 31, 2004

5. Lease Serial No.

NM-25865

abandoned well. Use Form 3160-3 (APD) for such proposals.	o, ii indian	, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side		r CA/Agreement, Name and/or No.
1. Type of Well	RECEIVED	
Y Oil Well Gas Well Other		me and No.
2. Name of Operator	U-MATEON Eng TX	(Federal #1
Yates Petroleum Corporation 9. API V		
3a. Address 3b. Phone No. (include are		-24191
		nd Pool, or Exploratory Area
		Draw Upper Penn, North
		or Parish, State
		ounty, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE OF ACTION		
Acidize Deepen	Production (Start/Resum	Water Shut-Off
	<u></u>	
X Notice of Intent Alter Casing Fracture Treat	Reclamation	Well Integrity
Casing Repair New Construction	Recomplete	Other
Subsequent Report . Change Plans X Plug and Abandon	Temporarily Abandon	
	W/w Discoul	
Final Abandonment Notice Convert to Injection Plug Back	Water Disposal	
Yates Petroleum Corporation plans to plug and abandon this well as follows: 1. Rig up all safety equipment as needed. TOH with tubing and both RBP's at 7600' and 7833' and packer. 2. Set 1st 5-1/2" CIBP at 8938' and the 2nd at 7446' with 35' cement on top of both CIBP's. 3. Circulate hole with 9.5# mud. 4. Perforate casing at 5276'. RIH with tubing and packer to +/-5100' and set a 100' cement plug (30 sx) in and out of casing. 5. Perforate casing at 3506'. RIH with tubing and packer to +/-3300' and set a 100' cement plug (30 sx) in and out of casing. 6. Perforate casing at 1133'. RIH with tubing and packer to +/-950' and set a 100' cement plug (40 sx) in and out of casing. Tag plug. 7. Perforate casing at 325'. RIH with tubing and packer to +/-150' and set a 100' cement plug (35 sx) in and out of casing. Tag plug. 8. Perforate casing at 60' and circulate cement (20 sx) in and out of casing to surface 9. Cut off wellhead and install marker and clean up location as per regulated. NOTE: Yates Petroleum Corporation will use steel pits and no earth pits		
14. I hereby certify that the foregoing is true and correct		
Name (Printed/Typed) Tina Huerta Title Regulatory Compliance Supervisor		
NEW CONTRACTOR OF THE PROPERTY		
	arch 13, 2006	
THIS SPACE FOR FEDERAL OR STA		
Approved by EPRE SGD.) DAVID & CLASS STEEDING BY EMOUNTED Date MAR 2 1 2008		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certity that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willbully to make to any department or agency of the United		
States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction VIII III		



