Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMLC065478B

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee of	r Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM70945X	
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. EMPIRE ABO UNIT 004C	
2. Name of Operator APACHE CORP	SON orp.com	9. API Well No. 30-015-00918				
3a. Address 303 VETERANS AIRPARK LANE SUITE 1000 Ph: 432.81			. (include area code) 8.1142		10. Field and Pool or Exploratory Area EMPIRE; ABO (22040)	
4. Location of Well (Footage, Sec., T			11. County or Parish, State			
Sec 17 T18S R27E 2314FSL			EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
■ Notice of Intent	☐ Acidize	☐ Dee	□ Deepen		tion (Start/Resume)	■ Water Shut-Off
_	☐ Alter Casing	☐ Alter Casing ☐ Hydraulic Fracturing		☐ Reclamation		☐ Well Integrity
☐ Subsequent Report	Casing Repair	☐ New	☐ New Construction		plete	Other
☐ Final Abandonment Notice	□ Change Plans	Change Plans		▼ Temporarily Abandon		
	☐ Convert to Injection	Plug	□ Plug Back		Disposal	
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Req following completion of the involved operations. If the operation results in a multiple completion or recomplete testing has been completed. Final Abandonment Notices must be filed only after all requirements, including red determined that the site is ready for final inspection. Apache would like to perform the following work. Please see attachments. Production Casing: 4-1/2? 9.5# @ 5,600? Producing Interval: 5,316-458? Objective: Isolate open perfs and TA wellbore. Well being evaluated for recompletion pote				mpletion in a ing reclamatio	new interval, a Form 316 on, have been countered.	
Procedure: 1. POOH with rods and tbg 2. Scan tbg and mark junk pip 3. Set CIBP @ 5,285? and du	MOCD RE SEE ATTACHE 2/13/14 CONDITIONS (E ATTACHED NDITIONS OF	FOR APPROVAL		
14. I hereby certify that the foregoing is Name (Printed/Typed) ISABEL H	Electronic Submission #3 For APA Committed to AFMSS for p	CHE CORP,	sent to the Carls DEBORAH MCKI	bad	2/13/2016 ()	
Signature (Electronic S	Submission)		Date 11/21/20	016		
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE	
Approved By James a. Como			Title 🗘	Title SAGT 2-7-1		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condition	Office C	FO				
Title 8 U.S.C Section 1001 and Title 43	U.S.C. Section 1212, make it a c	rime for any pe	erson knowingly and	willfully to m	ake to any department or	agency of the United

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #358550 that would not fit on the form

- 32. Additional remarks, continued
- 4. Fill casing with fluid and pressure test to 500 psi5. Record the test on a chart and submit for approval

Apache Corp. Actual LEASE/UNIT: **Empire Abo Unit** DATE: Nov. 18, 2016 WELL: S-4 BY: **HJG** 30-015-00918 API NUMBER: **COUNTY: Eddy** LEGAL DESCRIPTION: Sec 17, T18S, R27E STATE: New Mexico FIELD: Empire (BP) Spud: 4/29/61 KB = 3441'Rig Release: 5/23/61 GL =11" 8-5/8" 24# Set @ 1525' CMT 955 SX CIRC SURF 4-1/2" 9.5# Set @ 5600' CMT W/ 850 SX CIRC SURF 7-7/8" ABO (6/61) Perf: 5316-22, 82-5402, 46-58' (2 SPF) 6/61: Az 3/64: Frac w/48,426 gal lease crude, 24K# SD, 2K# Adomite Mark II, 5K# glass beads **CIBP** @ 5505 w/ 5' of CMT on top ABO (6/61) Perf: 5535-40' (2 SPF) 6/61: Az Formation Tops: Queen -Grayburg -TD = 5602'San Andres - 1190 **PBTD** = 5500° Glorieta -Abo - 5279

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.