
BUR SUNDRY N Do not use this f abandoned well.	UNITED STATES PARTMENT OF THE INTERIOR EAU OF LAND MANAGEMENT IOTICES AND REPORTS ON W form for proposals to drill or to Use Form 3160-3 (APD) for suc T IN TRIPLICATE – Other instructions on	o re-enter an ch proposais.	CT F C 17 5. Lease Serial No. NMNM27279 6. If Indian, Allottee c	ement, Name and/or No.	
2. Name of Operator CHEVRON USA INC			9. API Wen No. 30-015-25843		
3a. Address 6301 DEAUVILLE BLVD RM N3002 MIDLAND, TX 79705 ATTN LI	3b. Phone No. EE ROARK 432-687-727	10 Field and Pool or N/A	10 Field and Pool or Exploratory Area N/A		
4. Location of Well (Footage, Sec., T., SEC 30, T185, R30E 2130' FNL & 1980 FEL	R.M or Survey Description)	11 Country or Parish EDDY CO., NM	11 Country or Parish, State EDDY CO., NM		
12 CHEC	CK THE APPROPRIATE BOX(ES) TO IND	ICATE NATURE OF	NOTICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION		TYPE (OF ACTION		
Notice of Intent		ven [ure Treat [Construction [Production (Start/Resume) Reclamation Recomplete	Water Shut-Off Well Integrity Other	
Subsequent Report		and Abandon	Temporarily Abandon		
Final Abandonment Notice	Convert to Injection Plug peration Clearly state all pertinent details, in	Back	Water Disposal		
following completion of the involv testing has been completed Final determined that the site is ready fo 1 NOTIFY BLM 24 HRS BEFORE (2. SET CIBP@7050' AND SPOT 25 3 CIRCULATE WELLBORE WITH 4. PERF & SQUEEZE 175SX OF C 5. PERF & SQUEEZE 55SX OF CL 6. PERF & SQUEEZE 55SX OF CL 7 PERF & SQUEEZE 115SX OF C	OPERATIONS SX ON TOP MLF LASS "C" CEMENT FROM 4,118'-3,400 ASS "C" CEMENT FROM 2,150'-1,950' ASS "C" CEMENT FROM 1,665'-1,465' LASS "C" CEMENT FROM 453'-SURFA VELLHEAD, INSTALL DRY HOLE MARK	nultiple completion of er all requirements, ir WOC&TAG. (BOI WOC&TAG. (SHO WOC&TAG. (YATE VEC. VERIFY CEME KER AND TURN OV	recompletion in a new interva icluding reclamation, have bee NES SPRING/DELAWARE) E) ES/SALT) ENT TO SURFACE. (SHOE/ /ER FOR REMEDIATION.	I. a Form 3160-4 must be filed once n completed and the operator has	
ALL FLUIDS WILL BE IN CLOSED	SYSTEM. S90'	(Tos@ 5	40)		
		SEE ATTAC CONDITION	HED FOR IS OF APPROVA	cepted for record	
14 I hereby certify that the foregoing is t	rue and correct Name (Printed/Typed)			Ned CD	
M. LEE ROARK		Title PROJECT	MANAGER	cep into B.	
Signature 11 fer	Kinck	Date 01/25/2017		R.E	
/	THIS SPACE FOR FEDE	RAL OR STAT			
	d Approval of this notice does not warrant or o itle to those rights in the subject lease which w		ng	Date 2/27/17	
entitle the applicant to conduct operations Title 18 U.S.C. Section 1001 and Title 43		erson knowingly and w	villfully to make to any departme	nt or agency of the United States any false.	
mentious of manualent statements of repre	semations as to any matter within its jurisdictio	M1			

.



CURRENT

ł

	J.S.A. Inc. Wellbore DI		
Lease: OEU EUNICE FMT	Well No.: ELLIOTT FEDERAL 2 2	Field: SANTO NI	NO
Location: 2130FNL1980FEL	Sec.: N/A	Bik:	Survey: N/A
County: Eddy St.: New Mexico	Refno: IM4763	API: 300152584	3 Cost Center: UCRI40210
Section: E030	Township: 30		Range: S018
Current Status: ACTIVE		Dead Man Anch	ors Test Date: NONE
Directions:			
2544 1422 711 0		0.875 (7/8 in) I Wellbore Hole Cement (behin Unknown 13.37 Drift @(10-403 Cement (behin Wellbore Hole J-55 8.625 OE	d Casing) @(10-2100) OD-12 2500 @(403-2100))/ 24 00# Round Short 8 097 ID 7 972
4977			8 in) D x 25 Rod @(42-3267)
6764		J-55 2875 OE ID 2347 Drift J-55 2875 OE ID 2347 Drift J-55 2875 OE ID 2347 Drift ID 2347 Drift	4 in.) D x 25 Rod @(3267-6992) D/ 6 50# T&C External Upset 2 441 @(10-7004) D/ 6 50# T&C External Upset 2 441 @(7004-7008) D/ 6 50# T&C External Upset 2 441 @(7008-7072) (Catcher 2 875 @(7072-7075)
7070		ID 2347 Drift 1 500 (11/2 in 0 875 (7/8 in.) per rod) @(715 Rod Pump (Ins	D/ 6 50# T&C External Upset 2 441 @(7075-7170)) K x 25 Sinker Bar @(6992-7192) D x 4 Rod Sub - Rod Guides-Molded (3 32-7196) sent) (NON-SERIALIZED) - 125-R H BM a = 1.25) @(7196)
7377		J-55 2 875 OI 2 347 Drift - In Seat Nipple/Sh @(7235)	0/ 6 50# T&C External Upset 2 441 ID ternal Plastic Ctg-TK-99 ioe - Heavy Duty (2 875) Mechanical Type D/ 6.50# T&C External Upset 2 441
7683		ID 2347 Drift Sand Separato Perforations @ J-55 2875 Of ID 2347 Drift	@(7236-7238) or @(7238-7257)
7989		Bridge Plug (U Perforations @ Producing Inte Cement (behin Wellbore Hole	nknown Type) 5 500 @(7360-7364) (8021-8193) rval (Completion) @(7109-8193) d Casing) @(5957-8296) OD-7 8750 @(2100-8296) D' 17 00# Round Short 4 892 ID 4 767
Ground Elevation (MSL): 3471.	00 Spud Date: 11/27/1	Plug - Cement	@(8263-8296) mpl. Date: 01/01/1800

Chevron U.S.A.	Inc.	Wellbore	Diagram	:	ELLIOTT F 2

Ground Elevation (MSL): 3471.00	Spud Date: 11/27/1987	Compl. Date: 01/01/1800
Well Depth Datum: Kelly Bushing	Elevation (MSL): 3481.00	Correction Factor: 10.00
Last Updated by: keli	Date: 05/29/2015	

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Below Ground Level Cap (Lesser Prairie-Chicken Habitat)</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:

From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted