Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-AR	TESTA
OCD-AR	ILMA

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Expires: January 31, 2

5. Lease Serial No.
NMLC064490

SUNDF	۲Y	NC	TICES	AND	REF	20	RTS	ON	WELLS	
			_						_	

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

abandoned wel	II. Use form 3160-3 (API	D) for such p	oroposals.		o. It main, rinoide o	THE Nume		
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.							
1. Type of Well ☐ Oil Well ☑ Gas Well ☐ Oth		8. Well Name and No. HACKBERRY HILLS FEDERAL 4						
2. Name of Operator READ & STEVENS	Contact: E-Mail: kbarajas@			9. API Well No. 30-015-10805				
3a. Address P. O. BOX 1518 ROSWELL, NM 88202		3b. Phone No Ph: 575-62	. (include area code) 24-3760	ı	10. Field and Pool or Exploratory Area HACKBERRY HILLS			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, S	State		
Sec 22 T22S R26E 2310FNL			EDDY COUNTY	′, NM				
12. CHECK THE AI	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA		
TYPE OF SUBMISSION			TYPE OF	ACTION				
Notice of Intent ■	☐ Acidize	□ Dee	pen	☐ Product	tion (Start/Resume)	☐ Water Shut-Off		
_	☐ Alter Casing	☐ Hyd	Hydraulic Fracturing Recla		ation	☐ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	_	v Construction	☐ Recomp	plete	☑ Other Workover Operations		
☐ Final Abandonment Notice	☐ Change Plans	·	g and Abandon	_	rarily Abandon	Workover Operations		
	☐ Convert to Injection	Plug	g Back	☐ Water I	Disposal			
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate dural If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed entermined that the site is ready for final inspection. Read & Stevens, Inc.'s objective is to perforate the Delaware from 4750'-4800'. There is no cmt behind pipe. Set CIBP at 9000' w/35' cmt on top. Pull bond tool CCL-GR to assess TOC in 5 1/2" csg (TOC 8885'-9100'. Set CIBP at 5500' w/35' cmt on top. Perforate at 5100' and pump cmt. Perforate the Delaware w/2 SPJ from 4750'-4800'. Acidize w/3000 to 5000 gals 15% NeFe w/ball sealers. Swab and test. If swab test is successful, fracture w/100,000# 16/30 sand in 30# x-linked gel.								
Accepted for record. NMOCD DENIED Workover Febil-Mah 14, 2017 Es#370774 done W/o approval.								
14. I hereby certify that the foregoing is	Electronic Submission #	D & STEVENS	, sent to the Carl	sbad				
Name (Printed/Typed) RORY MC	CMINN	i	Title PRESID	DENT				
Signature (Electronic S	Submission)		Date 02/16/20	017				
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE			
Approved By	Swarty_		Title 7	PET	-	Date 4/4/2017		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu-	iitable title to those rights in the		Office C.	FO				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to ma	ake to any department or	agency of the United		