Form 3160-5 (June 2015)

(Instructions on page 2),

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Offi **OCD** Artesia

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 5. Lease Serial No. NM-032626 6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit of CA/A	7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well ✓ Oil Well ☐ Gas Well ☐ Other				8. Well Name and	8. Well Name and No. TELEDYNE 12 FEDERAL NO. 1	
2. Name of Operator ROCKCLIFF OPERATING NEW MEXICO, LLC				9. API Well No. 30)-015-33930	
			de area code)	10. Field and Pool	10. Field and Pool or Exploratory Area LOVING; DELAWARE EAST	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)				11. Country or Parish, State		
SEC 12 T 23S R 28E 990 FSL/990 FWL				EDDY COUNT	EDDY COUNTY, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA						
TYPE OF SUBMISSION	TYPE OF ACTION					
✓ Notice of Intent	Acidize Alter Casing	Deepen Hydraulic		Production (Start/Resun Reclamation	ne) Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Const	. =	Recomplete Temporarily Abandon	Other	
Final Abandonment Notice	Convert to Injection	Plug Back	, <u> </u>	Water Disposal		
completed. Final Abandonment Nois ready for final inspection.) THIS IS NOTIFICATION THAT CANYON FORMATION. PROPOSED PROCEDURE: MIRU PULLING UNIT. UNSEASET CIBP AT 4,890'. TEST CANU FRAC HEAD ON TUBING. WITH 35,000 GAL 20# GEL AN RUN PRODUCTION TUBING.	T AND POOH WITH PUM ASING TO 750PSI. PERFI ESTABLISH INJECTION ID 70,000# OF 30/50 SAN INSTALL PUMP AND RO	All requirements, included in NEW MEXICO, LL. MP. RELEASE TACORATE BRUSHY CONTROL BRUSHY CONTROL BRUSHY CONTROL BRUSHY CONTROL BRUSH SWEET BRUSH SWEET BRUSH WEET BRUSH WEET BRUSH SWEET BRUSH SWEET BRUSH WEET BRUSH B	C INTENDS TO F C NU BOP AND I CANYON BETWE IONS WITH 20BE VAB AND FLOW ILL TO PRODUC	have been completed a RECOMPLETE THE S POOH WITH TUBING IEN 4,790-4,820'. RIF BLS OF ACID AND FI BACK WELL. POOH TION. ESTIMATED I	m 3160-4 must be filed once testing has been not the operator has detennined that the site SUBJECT WELL IN THE BRUSHY S. RIH WITH BIT AND SCRAPER. H WITH PACKER AND FRAC STRING. RESHWATER. FRAC PARDUE ZONE WITH FRAC STRING AND PACKER. DURATION: 7 DAYS NM OIL CONSERVATION.	
BLM BOND #: B009790	ted for record - NMC	oco SI	EE ATTACI		ARTESIA DISTRICT	
Accel	Appl 101	U	אוטווווטאכ	S OF APPRO	JVAL WAY 3 0 2011	
					RECEIVED	
14. I hereby certify that the foregoing is MICHAL A. WEESNER	true and correct. Name (Pri	inted/Typed) Title	OPERATIONS A	ANALYST		
Signature Stake	Dieson	Date		04/1	9/2017	
THE SPACE FOR FEDERAL OR STATE OFICE USE						
Approved by C. Nimmer			Title Petrol	eum Engineer	Date S/25/2017	
Conditions of approval, if any, are attack certify that the applicant holds legal or e which would entitle the applicant to con	quitable title to those rights		Office C.	rlsbad Fie	ld Office	
Title 18 U.S.C Section 1001 and Title 43 any false, fictitious or fraudulent statement				willfully to make to an	y department or agency of the United States	

Rup 6-1-17

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plug back operations shall commence within <u>ninety (90)</u> days from this approval. If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date work was completed.** If plugging back to a new zone submit a Completion Report, form 3160-4 with the Subsequent Report.
- 7. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.