OCD-ARTESIA

Form 3160-5

	DEPARTMENT OF THE INTERIOR					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2					5. Lease Serial No. NMLC064490			
					6. If Indian, Allottee or Tribe Name			
					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well					8. Well Name and No. HACKBERRY HILLS FEDERAL 4			
Ø Oil Well					9. API Well No.			
READ & STEVENS E-Mail: kbarajas@read-stevens.com					30-015-10805			
3a. Address P. O. BOX 1518 ROSWELL, NM 88202	3b. Phone No. (include area code) Ph: 575-624-3760			10. Field and Pool or Exploratory Area HAPPY VALLEY; DELAWARE				
4. Location of Well (Footage, Sec., T	n)	11. County or Parish, State						
Sec 22 T22S R26E 2310FNL				EDDY COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE	E OF NOTICE,	REPORT, OR O	OTHER	DATA	
TYPE OF SUBMISSION	TYPE OF ACTION							
☐ Notice of Intent	☐ Acidize	☐ Dee	☐ Deepen		☐ Production (Start/Resume)		Water Shut-Off	
☐ Alter Casing		☐ Hydraulic Fracturing		ng 🔲 Reclama	☐ Reclamation		Well Integrity	
Subsequent Report ☐ Casing Repair		☐ New Construction			Recomplete		Other Jorkover Operation	
☐ Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection		☐ Plug and Abandon☐ Plug Back		☐ Temporarily Abandon ☐ Water Disposal		omerer operation	
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f 3/15/2017: TIH. Set RBP #2 at 4523'. Pump 190 sxs Class H2O. Max press 955 psi, ave 3/17/2017: TIH. Tag and dril sand to top of RBP #2 at 4704 3/18/2017: TIH. Tag sand at clean out to top of fish at 482′. 3/20/2017: Ran CBL-CCL-GF 4657', unloader, SN at 4646', 3/22/2017: TIH. Tag at 4802 Previously perforated from 47 scheduled for 4/4/2017.	d operations. If the operation rebandonment Notices must be filtinal inspection. at 4704'. Dump 2 sxs sass C Neat flollowed w/190 erage press 350 psi, max if cmt retainer and cmt froid 4'. Circ well clean. TOH. 4675' and wash dwn to 43'. Circ wellbore clean. TR-ND log from 4803' to 38 2 7/8" workstring. Swab 2 7/8" workstring. Swab 5'. TIH w/perf guns and 60'-4810' 2 JSPF. Has de 19 2 JWJ-E C	nd dwn tbg or sxs Class C v rate 3 bpm, av m 4516'-4660 SDFN. 704'. Releas OH. Tag at 4 well rec 23 bb perforate from oubled to 4 JS	e completion or requirements, incomplete the complete the	recompletion in a recluding reclamation #2. Set cmt ret Displace w/24 t .5 bpm. WOC. 31'. Clean out ag sand at 4719 ow Set I pkr at (2 JSPF).	ainer oblis of and of an Arte	3160-4 m ted and th	ERVATION STRICT	
14. I hereby certify that the foregoing is	s true and correct. Electronic Submission # For REA	374953 verifie D & STEVENS	d by the BLM t	Carlsbad	•			
Name (Printed/Typed) KELLY BA	Committed to AFMSS for	processing by		CKINNEY on 05/ ORT PREPARI				
Traine(Trained Typed) TREET Dr								
Signature (Electronic	Submission)				FOR RECO	<u>IRD</u>		
	THIS SPACE FO	OR FEDERA	L OR STAT	EOFFICE U	SE			
Approved By		Title	MAY	16,2016		Date		
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to conduct the applicant the ap		Office R	HALL DE LA	UD MANACEME	NT			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crit States any false, fictitious or fraudulent statements or representations as to							y of the United	
Sand any raise, mentions of maduatent	our of representations as	ung manci w	in a suit suict	1011.			4	

Additional data for EC transaction #374953 that would not fit on the form

32. Additional remarks, continued

4/4/2017: Frac w/62,880# of 20/40 Cool Set sand, 1069 bbls of 18# Borate gel pad. Displace w/30 bbls 18# Borate gel. Max rate 21 bpm, average rate 20 bpm, max press 4883 psi, average press 2505 psi, ISIP 831 pis, 5 min SI 546 psi, 10 min 573 psi, 15 min SI 575 psi. Leave well SI overnight for sand to set up.
4/5/2017: Tbg 450 psi, csg 350 psi. Swab 89 bbls fluid.
4/6/2017: Tbg 50 psi, csg 250 psi. Swab 286 bbls fluid.
4/7/2017 - 4/11/2017: Flowback and monitor well.

Report continued on attachment.

HACKBERRY HILLS FEDERAL #4 NMLC064490 API #30-015-10805

April 17, 2017: MI. 2 stage compressor. Plumb in lines. Erect 640 - 365 - 144 Lufkin PU.

April 18, 2017: Prep to run production string.

April 19, 2017: SICP - 120#. Blow well dwn to steel pit. RIH w/2 7/8" x 31' BPMA, 2 7/8" x 4' perf'd sub, 2 7/8" OD seating nipple, 4 jnts 2 7/8" tbg, 2 7/8" x 5 1/2" TAC and 145 jnts 2 7/8" tbg. Tag PBTD at 4798'. Pull up and lay down one jnt of tbg. ND BOP. Set TAC with 12,000# tension. NUWH. Receive and rack 7/8" rods. Install rod couplings on rods. RIH w/ 1 1/4" x 20 gas anchor, 2 1/2" x 1 3/4" x 24 pump and 152 - 7/8" rods. EOT @ 4740'. SN @ 4704'. TAC @ 4579'.

April 21, 2017: RIH w/2 1/2" x 1 3/4" x 24' pump, 186 - 7/8" rods, 7/8" x 8' x 6' x 4' pony rods and 1 1/4" x 26' polished steel rod. Seat and space pump. Hang well on. RU reverse unit. Load tubing with 5 bbls 2% KCL water. Pressure up to 500# w/downhole pump. Held okay. RD reverse unit. RDMOSU. MI and set 108 KV generator. Set and run power line from panel box to 30 HP electric prime mover, then from panel box to generator. Set propane and plumb in to generator. Balance unit by removing 2 counter weights. MI and set 3 phase separator. Plumb in WH.

April 22, 2017: Lay 2 7/8" flowline from WH to separator and plumb in at both ends. Plumb in oil dump line to oil tank. Plumb in wtr dump line to wtr tank and run gas line from separator to meter run. Well is producing at report time.

