		OCD-ARTI	ESIA						
Form 3160-5 (August 2007) DH B	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No.								
SUNDRY Do not use th abandoned we		* NM05432801 or Tribe Name							
SUBMIT IN TRI	PLICATE - Other instructio	ns on reverse side. M/	AY 1120	7. If Unit or CA/Agro	eement, Name and/or No. 5432803				
 Type of Well Oil Well Gas Well Gas Well 	her: INJECTION	I I I I I I I I I I I I I I I I I I I	RECEIVER	8. Well Name and No HUDSON FEDE					
2. Name of Operator BOPCO LP	Contact: TR E-Mail: tjcherry@bass	ACIE J CHERRY pet.com		9. API Well No. 30-015-21052					
3a. Address P O BOX 2760 MIDLAND, TX 79702	 Phone No. (include area code h: 432-683-2277)	10. Field and Pool, or Exploratory 50443 DELAWARE; SWD QUAHADA PLOGE; DELAWARE, SE						
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)		11. County or Parish, and State						
Sec 1 T23S R30E Mer NMP \$	SENW 1830FNL 1980FWL∽	~	EDDY COUNTY, NM						
12. CHECK APP	ROPRIATE BOX(ES) TO IN	NDICATE NATURE OF 1	NOTICE, RI	EPORT, OR OTHE	ER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION								
Notice of Intent	Acidize	Deepen	—	ion (Start/Resume)	□ Water Shut-Off				
Subsequent Report	 Alter Casing Casing Repair 	Fracture Treat Reclam New Construction Recom			Well Integrity Other				
Final Abandonment Notice	Change Plans	Plug and Abandon	Recomp Tempor	arily Abandon					
	Convert to Injection	Plug Back	U Vater D	-					
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f BOPCO, LP respectfully subm disposal well to an Observatio The Hudson Federal #1 will be the Delaware formation due to obtained by monitoring the su submitted to the BLM by Sund justification and details of this The subject was drilled and co downhole commingle of the B authority was granted Septem	d operations. If the operation results bandonment Notices shall be filed or inal inspection.) nits this sundry notice of inter on/Monitoring well. e one of seven (7) wells to be	in a multiple completion or reconny after all requirements, includent to convert the reference used for monitoring press	ompletion in a r ding reclamation d saltwater sure changes	Hew interval, a Form 314 h, have been completed, Hew COST HUTHORIT. CARLED N S IN S IN A LED N	50-4 shall be filed once and the operator has INJUERTON SWP PEPMIT				
14. I hereby certify that the foregoing is	Electronic Submission #341		Il Information						
Name (Printed/Typed) TRACIE J	I CHERRY	Title REGUL	ATORY AN	ALYST	, 				
Signature (Electronic	Submission)	Date 06/03/2	2016						
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE US	6E					
Approved By		Title			Date				
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to cond	uitable title to those rights in the sub								
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a crim statements or representations as to a	ne for any person knowingly and ny matter within its jurisdiction.	l willfully to ma	ke to any department of	r agency of the United				

*

2

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #341022 that would not fit on the form

32. Additional remarks, continued

converted to disposal in November 2000 and began disposing in the Delaware through perforations 4040' - 4825'. The attached wellbore diagram shows the perforated intervals, casing detail and formation tops. Top of cement on the 7-7/8" was 7000' during initial completion. The casing was perforated at 5100? and cement squeezed to 3560' behind casing during conversion to SWD. TOC determined by CBL. The 16" & 10-3/4" casing strings are cemented to surface. The last successful MIT was performed 10/21/2015. Results submitted to BLM via sundry notice.

CURRENT WELLBORE DIAGRAM

**

1

Lease:	HUDSON FEDER	RAL			Well No.	: 1			
	QUAHADA RIDGE, S							······································	
Location:	1830' FNL & 1980' F\	NL, SEC 1	, T23S	S, R30	0E				
County:	EDDY	St: NM						API:	30-015-21052
			-						
								KB:	3319
Converted	to SWD - 2/2/2001							GL:	3298
								Spud Date:	2/25/1974
						_0	KB	(RR)	5/17/1974
Surface Csg.						21	GL	Compl. Date:	8/8/1974
Size:	16"							Lat:	32.33605
Wt	65#							Long:	
Grd	H-40					492'	16" Csg		
Set @:	492'						· ·		
Sxs cmt:	650					3560'	TOC		
Circ:	Ŷ					3781'	10 3/4"	Csg	
TOC:	SURF								
Hole Size:	20"	-				3993'	EOT / PKF	,	PERFS:
						4040'	Top Perf	N	4040 - 4060'
1st Intermed	ista Cen		_	_		4825'	Btm Perf		4070 - 4080'
Size:	10 3/4"			_		4025	Dunren		4089 - 4099'
Wt	40.5# 45#								4130 - 4160'
Grd	J-55		\sim	\geq		5050'	Cmt Ret		4212 - 4242'
Set @:	3781'	- XX		\sim		5100'	Perf		4342 - 4362'
Sxs Cmt:	1950	9 ,80	The state			5165'	35' of cmt		4390 - 4430'
	Y	-	ALCAL REFE	Contraction of the					۱ I
Circ:		•			动	5200'	CIBP		4453 - 4493'
TOC:	SURF				35	5273' - 5	405'		4497 - 4507'
Hole Size:	12 1/4"					Cmt			4525 - 4545'
		20.1277							4561 - 4591'
Production C	÷					6720'	Top Cmt		4640 - 4650'
Size:	7 5/8"								4693 - 4723'
Wt	29.7# 33#								4805 - 4825'
Grd	S-95 N-80	-	nie wienie ik	and the second		74051			
Set @:	11790'			1211		7135'	35' of cmt		
Sxs Cmt:	600	-	\geq	\leq		7170'	CIBP		
Circ:	<u>Y</u>			1					
TOC:	7000'/3560' (Sqz fron	ຸ 5100') 📕	=	=		7201' - 7			
Hole Size:	9 1/2"		-	=		7285' - 7	'286'	7285' - Btm Cmt	
			[2:14				
Liner:						7380'	Top Cmt		
Size:	<u>5 1/2"</u>		=	=		7510' - 7	'517'		
Wt	17#	-							
Grd	<u>N-80</u>								
Set @:	11503' - 14325'	•							
Sxs Cmt:	275	-				10865'	35' of cmt		
Circ:	Y		\geq	\leq		10900'	CIBP		
TOC:	11790'		-	=		10915' -	10930'		
Hole Size:	6 1/2"								
						11015'	35' of cmt		
Tubing Data			\triangleright	<		11050'	CIBP		PERFS:
2-7/8" 6.4# J55	Seal Tite		=	=		11086' -	11098'		13844 - 13856'
2-7/8" x 7-5/8" I									13870 - 13875'
	• • • • • • • • • • • • • • • • • • •	•				11503'	Top 5 1/2'	Liner	14171 - 14177'
Formation toos	per completion filed 08/1	5/74				11790'	7 5/8"	Csg / Btm Cmt	14243 - 14248'
Delaware	3796				A left		· -· -		14229 - 14237'
Bone Spring	7676		- -			12989 -	12995'	Updated:	
Wolfcamp	10988					13844 -		Author:	
Atoka	12802					10044 -	1 7207	Engr:	ezg JBB
Morrow	13724					14325'	Btm 5 1/2"		<u> </u>
	10/27		and a second	-33		020	0 an 0 nZ		

Order of the Authorized Officer BOPCO/XTO Hudson - 01, API 3001521052 T23S-R30E, Sec 01, 1830FNL & 1980FEL May 03, 2017

Records indicate no disposal volume injected since 02/2015.

The New Mexico Bureau of Land Management (BLM) Policy guideline limits total idle well status to five years. With sufficient documentation and justification via subsequent sundry reporting the AO may authorize renewal on a year-to-year, case-by-case basis.

Operator's designation of Monitoring Well status (MW) indicates the well is a service well for "Delaware Formation Observation and Monitoring". BLM accepts conversion from a Delaware WDW to a Shut-In Delaware Formation Observation/Monitoring Well.

05/03/2017 - Beginning 02/2015 until 02/03/2018 (the BLM designated renewal date) SI status accepted for record with this attached order of authorized officer. pswartz

To extend SI compliance beyond the BLM designated renewal date, submit a subsequent sundry listing:

- 1. Provide BLM with an (when available) electronic copy (Adobe Acrobat Document) of a cement bond log record from Packer depth or below_to the top of cement with 0psig casing pressure. Attach the CBL to a <u>pswartz@blm.gov</u> email.
- 2. Provide a witnessed recent MIT record (taken in the last year) of the tubing/casing annulus.
 - i) The minimum MIT pressure should be 500 psig for 30 minutes or 300 psig for 60 minutes, with a minimum 200 psig differential between tubing and casing pressure (at test time) but no more than 70% of casing burst pressure as described by Onshore Order 2.III.B.1.h. (The tubing or reservoir pressure may need reduction).
 - ii) Verify that all annular casing vents are open to the surface atmosphere during this pressure test.
 - iii) Document the pressure test on a one hour full rotation chart recorder (calibrated within the last 6 months) registering within 35 to 75 per cent of its full range. Greater than 10% pressure leakoff viewed as a failed MIT. Less than 10% pressure leakoff will be evaluated site specifically and may restrict status approval.
- 3. Maintain the annulus full of packer fluid at atmospheric pressure. Installation of equipment that will display a continuous open-air packer fluid level above the tubing/casing annulus vent is required.
- 4. Notify the BLM's authorized officer ("Paul R. Swartz" <<u>pswartz@blm.gov></u>, cell phone 575-200-7902) to arrange for approval of the annular monitoring system.

- 5. Loss of packer fluid above five barrels per month indicates a developing problem. Submit a NOI plan of correction compliance for BLM approval.
- 6. Submit dated reports of each taken stabilized inactive shut-in wellhead and annulus pressure, fluid level, and tubing psig from no more than 20-30 feet above the injection packer on a request for renewal subsequent sundry.
- 7. Report operator's reasoning and conclusions drawn from the monitoring information.
- 8. If you do not comply as noted, you shall be issued an Incident of Noncompliance (INC) in accordance with 43 CFR 3163.1(a). Failure to comply with the INC may result in assessments as outline in 43 CFR 3163.1, and may also incur civil penalties (43CFR 3163.2). All self-certified corrections must be postmark no later than the next business day after the prescribed time frame for correction.
- 9. Section 109(d)(1) of the Federal Oil and Gas Royalty Management Act of 1982, as implemented by the applicable provisions of the operating regulations at Title 43 CFR 3163.2(f)(1), provides that any person who "knowingly or willfully" prepares, maintains, or submits false, inaccurate, or misleading reports, notices, affidavits, records, data, or other written information required by this part shall be liable for civil penalty of up to \$25,000 per violation for each day such violation continues, not to exceed a maximum of 20 days.
- 10. A person contesting a decision shall request a State Director review of the Written Order. This request must be filed within 20 working days of receipt of the Notice with the appropriate State Director (see 43 CFR 3165.3). The State Director review decision may be appealed to the Interior Board of Land Appeals, 801 North Quincy Street, Suite 300, Arlington, VA 22203 (see 43 CFR 3165.4). Contact the above listed Bureau of Land Management office for further information.