NM OIL CONSERVATION

ARTESIA DISTRICT

Form 3160-5 (June 2015)

UNITED STATES
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELESE VERY Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM39635 /	
					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.	
Type of Well ☐ Oil Well ☐ Gas Well ☒ Oth	D-ARTES	-ARTESIA 8. Well Name and No. MIMOSA FEDERA		AL SWD 3Y /		
2. Name of Operator Contact: TINA HUERTA EOG Y RESOURCES, INC. E-Mail: tina_huerta@eogresources.com				9. API Well No. 30-015-29123		
3a. Address 3b. Phone N. 104 SOUTH FOURTH STREET Ph: 575-74 ARTESIA, NM 88210 Fx: 575-74					10. Field and Pool or Exploratory Area WILDCAT; DEVONIAN	
4. Location of Well (Footage, Sec., T	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	11. County or Parish, State			
Sec 4 T20S R24E SESE 635F			EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES) T	O INDICAT	E NATURE OI	FNOTICE	E, REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent ■ Notice of Intent Notice of Inten	☐ Acidize	□ Deepen		☐ Production (Start/Resume)		■ Water Shut-Off
_	☐ Alter Casing	☐ Hydra	ulic Fracturing	☐ Reclar	nation	☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	☐ New Construction		☐ Recon	nplete	☐ Other
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon		☐ Tempe	□ Temporarily Abandon	
	☐ Convert to Injection	tion 🛛 Plug Back		☐ Water Disposal		
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the oper determined that the site is ready for final inspection. EOG Y Resources, Inc. plans to plug back and add additional Devonian perforations: 1. MIRU all safety equipment as needed. 2. Release the packer and POOH with tubing. 3. RIH with GR/JB to 11,070 ft.						LIKE
4. Set a 7 inch CIBP at 11,05 5. Tag top of CIBP and spot reset if necessary. 6. Set packer at 9000 ft. Cor 7. If well has not lost significa 8. Perforate Devonian 9832 f 9. Set the packer at 9780 ft.	0 ft. 100 sx Class H cement on to the control of t	exceed 1800		for reç		bg & 10,500
14. I hereby certify that the foregoing is	Electronic Submission #38	SOURCES. IN	C., sent to the (Carlsbad	•	
Name (Printed/Typed) TINA HUERTA			Title REGUL	ATORY S	PECIALISTODO	WED
Signature (Electronic Submission)			Date 07/19/20	017	APPRU	AED
	THIS SPACE FOR	R FEDERA	OR STATE	OFFICE	JSE	
Approved By			Title TPET		PRSwart	Date 07/19/17
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office		BUREAU OF LAND N	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to		

Additional data for EC transaction #381756 that would not fit on the form

32. Additional remarks, continued

10. Pump 10,000g HCl acid with 240 ball sealers and flush acid with 65 bbls.

11. POOH with work string and set a nickel plated packer and 3-1/2 inch plastic coated tubing at 9044 ft. Hydro test back in the hole.

12. Load backside with packer fluid and test. Contact NMOCD to witness test.

13. Rig down and move out rig.

Wellbore schematics attached



