Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMLC065478B

SUNDRY NOTICES AND REPORTS ON WELLS

Down to a 400	NOTICES AND INC.	1(10 014 11L			1411120000 11 03		
Do not use this form for proposals to drill or to re-erteria abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM70945X		
1. Type of Well ☑ Gas Well ☐ Other					8. Well Name and No. EMPIRE ABO UNIT 018A		
2. Name of Operator Contact: ISABEL HUDSON APACHE CORP E-Mail: Isabel.Hudson@apachecorp.com					9. API Well No. 30-015-00706		
3a. Address 303 VETERANS AIRPARK LANE SUITE 1000 MIDLAND, TX 79705 3b. Phone No. (include area code) Ph: 432.818.1142					10. Field and Pool or Exploratory Area EMPIRE; ABO (22040)		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 1 T18S R27E 2310FNL 1980FWL					. EDDY COUNTY, TX		
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE, I	REPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize ☐ D		eepen		on (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing ☐ Hyd		raulic Fracturing 🔲 Reclam		tion	☐ Well Integrity	
Subsequent Report	☐ Casing Repair ☐ Ne		Construction	☐ Recompl	ete		
☐ Final Abandonment Notice	☐ Change Plans ☐ Plu		and Abandon	☐ Temporarily Abandon		workover Operations	
	☐ Convert to Injection ☐ Plus		Back	□ Water Disposal			
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Apache has performed the following work: O1/03/2017 MIRUSU & Rev unit & kill well. POOH w/ pump & rods, MIRU Empire Services. POOH tbg. Prep							
to RIH w/CMT retainer & hydro	otest tbg.	ump & rous, r	niko Empire Sei	rvices. POOF	• ,	CONSERVATION	
01/04/2017 Kill well. PU 4.5? CMT retainer on 2-3/8? J-55 tbg. Hydrotest all TBG. Set retainer @ ARTESIA DISTRICT 5542?. Load CSG & test to 500# for 15 mins. Prep to squeeze perfs.							
01/05/2017 MIRU Par 5 Services. Test lines. Pump 700 sks C+. Prep to finish Abo squeeze.							
01/06/2017 SD due to weather. Prep to finish ABO squeeze.					. R	EGEIMED	
was casing lested offer squenges							
14. I hereby certify that the foregoing is Name (<i>Printed/Typed</i>) ISABEL F	Electronic Submission # For AP Committed to AFMSS for	ACHE CORP,	Sent to the Carlsi DEBORAH MCKI	bad /	14/29/17/1		
			[[Odrott	D FOR MECO		
Signature (Electronic S			Date 0/17/2				
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	E	100	
Approved By			Title	A	9 2017		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to condu	iitable title to those rights in the		Office	BUREAU OF	FIAND ANACHER BAUFINDEN E		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to mak		ngency of the United	
Instructions on page 2) ** OPERA1	OR-SUBMITTED ** O	PERATOR-	SUBMITTED *	* OPERATO	SUBMITTED	**	

Additional data for EC transaction #363990 that would not fit on the form

32. Additional remarks, continued

01/09/2017 MIRU Par 5 Services. Start pumping CMT. Pumped 2 BBLS CMT into formation.

01/10/2017 Tag up on CR @ 5542?. Do CR. WO CMT

01/11/2017 Tag up on CMT @ 5550?. Drill out solid CMT from 5550? ? 5917?. CIRC hole clean. Prep to DO CMT to PBTD.

01/12/2017 Break CIRC. DO solid CMT from 5917? ? 6040?. Fell through to PBTD @ 6051?. Circ hole clean w/ 2% KCL. MIRU Renegade WL Services. RIH w/ 3-1/8? perf guns & perf Upper Abo @ 5626?-30?, 5654?-62?, 5698?-704?, 5750?-56?, 5860?-70?, 5891?-94?, 5902?-06?, 5968?-75?, 5992?-6018?, 3 SPF, 60 degree phasing 222 holes. POOH w/ perf guns & RDMO Renegade WL Services. Prep to RIH w/ TBG & PKR. Acidize Upper Abo.

01/13/2017 RIH w 4.5? PKR on 2-3/8? J-55 TBG. Set PKR @ 5544? & test to 500#. MIRU Cudd Energy Services. Titrate acid to 15.3% Acidize Upper Abo from 5626? ? 6018? w/ 2,300 gals 15% HCL @ 5.0 BPM, 1396#. Drop 2500# of rock salt w/ 42 BBLS of 10# brine in 2 stage @ 5.0 BPM, 1403#. RDMO Cudd Energy Services. SI for 1 hr. Release PKR & wash salt from 5981? to PBTD @ 6051? POOH w/tbg & pkr. Prep to RIH w/ production equip.