

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <u>30-015-24531</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <u>LH 2392</u>
7. Lease Name or Unit Agreement Name <u>NM STATE DL</u>
8. Well Number <u>1</u>
9. OGRID Number <u>138987</u>
10. Pool name or Wildcat <u>HERRADURA DELAWARE</u>

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	
2. Name of Operator <u>Buckeye Disposal LLC</u>	
3. Address of Operator <u>P.O. Box 2724 Lubbock TX 79408</u>	
4. Well Location Unit Letter <u>F</u> : <u>1973</u> feet from the <u>NORTH</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>36</u> Township <u>22 S</u> Range <u>27 E</u> NMPM <u>Edgely</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3075</u>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1 Set Blanking plug 1875 bore in lockset packer
- 2 Test tubing for possible hole
- 3 Set pulling unit up
- 4 Release on all tool joint tubing
- 5 Replace damaged tubing
- 6 Run tubing back in hole
- 7 Test tubing & casing
- 8 Put back in service

NM OIL CONSERVATION NM OIL CONSERVATION  
ARTESIA DISTRICT ARTESIA DISTRICT

OCT 24 2017

RECEIVED

RECEIVED

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Jim Sayre

TITLE MANAGER

DATE 10-24-17

Type or print name

JIM SAYRE

E-mail address:

jim@the-standard-energy.com

PHONE: 575-361-5072

For State Use Only

APPROVED BY:

Richard Innes

TITLE COMPLIANCE OFFICER

DATE 10/25/17

Conditions of Approval (if any):

CONTACT ME TO WITNESS MIT TEST BEFORE WELL CAN BE PUT BACK INTO SERVICE.