Submit 1 Copy Office	To Appropriate Distri		State of New Mexico			Form C-103	
District I (575	<u>x1</u> -(575) 393-6161 Energy, Minerals and Natural Resources			tural Resources	Revised July 18, 2013 WELL API NO.		
<u>District II</u> – (57			CONSEDVATIO		30-015-020		
	CIII - (373) 748-1285 OIL CONSERVATION DIVISION . First St., Artesia, NM 88210 01L CONSERVATION DIVISION ct III - (505) 334-6178 1220 South St. Francis Dr.				5. Indicate Type of Lease		
1000 Rio Brazo	000 Rio Brazos Rd., Aztec, NM 87410					TE S FEE SEASE NO.	
1220 S. St. Francis Dr., Santa Fe, NM					B-11595	a Gas Lease No.	
87505 SUNDRY NOTICES AND REPORTS ON WELLS					7. Lease N	ame or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						Gulf State	
PROPOSALS.)					000	8. Well Number	
1. Type of Well: Oil Well Gas Well OtherNM OIL CONSERVATION					002	9. OGRID Number	
2. Name of Operator Breitburn Operating LP ARTESIA DISTRICT					9. OGRID 370080		
3. Address of Operator 011 3 1 2017						10. Pool name or Wildcat	
1111 Bagby Street, Suite 1600 Houston, TX 77002					Artesia; Qu	een-Grayburg/San Andres	
4. Well Location							
Unit Letter <u>O</u> : <u>990</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>East</u> line							
Sec	tion <u>23</u>		Township <u>18S</u>	Range 28 <u>E</u>	NMPM	Eddy County	
		11. Elevati	1	OR, RKB, RT, GR, etc	c.)		
GR 3494'							
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A							
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A V PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB							
CLOSED-LOOP SYSTEM							
OTHER: OTHER: OTHER: OTHER: OTHER: OTHER:							
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of							
proposed completion or recompletion.							
10/19-10/20/2017: Prepare well for plugging. MIRUPU, unseat pump, POOH and LD ³ /4" rods and pump. NDWH, NU BOP, POOH							
and LD 2 3/8" tubing. Close well in. SD.							
10/20-10/21/017: RDPUMO.							
10/26-10/27/2017: Set 1 anchor, MIRUPU and plugging equipment. NDWH, NU BOP, RUWL and RIH w/ 5.5" gauge ring to 2720'.							
POOH, RIH and set 5.5" CIBP at 2720'. Pick up 2 3/8" tubing, tag CIBP at 2720'. Close well in and SION 10/27-10/28/2017: Circulate hole w/ 50 bbls 9.5# mud, spot 25 sks Class C cement from 2720' – 2468'. WOC. Tag TOC at 2444'.							
Pull up to 2160', spot 25 sks C cement from 2160' $-$ 1908'. POOH w/ tubing and perforate at 490'. Set packer at 100'. Squeeze 45							
sks C cen	nent with no retur	ns out of surface.	Displace TOC to 35	0', WOC to tag. Clo	se well in and S	SDFWE.	
10/30-10/31/2017: RIH and tag TOC at 360'. NMOCD OK'd and said to set a 100' plug to surface. Wait on vacuum truck to catch							
displaced fluid. Spot 10 sks C cement from 100' to surface. No fall back. Well is plugged. RDMO.							
	10/28/1958		7		······································		
Spud Date:	10/20/1956		Rig Release	Date:			
	<u> </u>			L			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE TITLE: Agent DATE: 10/31/2017							
Type or print name Shelly Doescher E-mail address shelly_doescher@yahoo.com PHONE: 505-320-5682							
APPROVED BY: TITLE STATT Mgr DATE 10-31-17							
Conditions of Approval (if any):							