Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

OCD Artesia

FORM APPROVED OMB No 1004-0137 Expires: July 31, 2010

5. Lease Serial No. NM 015068

6. If Indian, Allottee or Tribe Name

## Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well 8. Well Name and No. MCKEE WILSON #001 Oil Well Gas Well Other 2. Name of Operator WS OIL AND GAS OPERATING, LLC 9. API Well No 30-015-03499 10. Field and Pool or Exploratory Area 3a. Address P.O. BOX 5375 MIDLAND, TX 79704 61020; TURKEY TRACK SR Q GB SA 432-242-4965 4. Location of Well (Footage, Sec., T.R.M., or Survey Description) 11. Country or Parish, State EDDY, NM 2310 FNL 1980 FWL; UL F SEC34 T18S R29E 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Decpen Production (Start Resume) Water Shut-Off Notice of Intent Well Integrity Reclamation After Casing Fracture freat Casing Repair New Construction \_\_\_ Recomplete Other Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Water Disposal Final Abandonment Notice Convert to Injection Plug Back 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 2/11/2016 MIRU RELIABLE RIG # 3. POOH WITH PUMP AND RODS, SHOP PUMP, RODS OK, WORK TO UNPACK WELLHEAD, REPLACED WELLHEAD DUE TO CORRISION, RUST AND AGE. NU BOP. TALLIED OUT OF THE HOLE WITH 2-3/8" TUBING, SWISDON.

2/12/2016

HSM WITH CREW. RE: PINCH POINTS AND HAND PLACEMENT. RIH WITH BIT. TAGGED 2112'. POOH LAYING DOWN TUBING. PU 2-3/8" YELLOW BAND TUBING TAGGED SAM E PLACE. MIRU DOUBLE R KILL TRUCK AND VAC TRUCK. BREAK CIRCULATION, PUMP AND ROTATED DOWN TO 2419'. PUMPED TOTAL 230 BBLS FW. RD SWIVEL. PU INTO CASED HOLE. SDOWE.

NM OIL CONSERVATION

ARTESIA DISTRICT

OCT **16** 2017

SEE ATTACHED

Accepted for record - NMOCD

RECEIVED

14. I hereby certify that the foregoing is true and correct. Name (Printed Typed)			
CARIE STOKER	Title REGULAT	ORY AFFAIRS COORDINATOR	
Signature Carie Slocker	Date 02/24/2016	6 ACCEPTED FOR RECORD	
THIS SPACE FOR FEDE	RAL OR STA	TE OFFICE USE	
Approved by	little	OCT - 3 2017	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or e that the applicant holds legal or equitable title to those rights in the subject lease which we entitle the applicant to conduct operations thereon.	ertify	BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any falso fictitious or fraudulent statements or representations as to any matter within its jurisdiction

2/15/16

HSM WITH CREW. RE: PPE AND TRIP HAZARDS. FINISHED POOH WITH OLD BIT. RIH WITH NEW

BIT. TAGGED FILL @ 2112', RU SWIVEL AND CIRCULATED 15' BRIDGE TO SURFACE. CONTINUED

RIH, TAGGED FILL @ 2540', CLEANED DOWN TO 2572'. POOH WITH BIT. RIH WITH 2-3/8" TUBING AND

BHA TO 2536'. ND BOP. NU WELLHEAD. PREP FOR RODS RIH WITH PUMP AND RODS. SPACED

OUT RODS. HANG WELL ON. LOADED TUBING WITH 8 BBLS WATER. PRESSURED PUMP TO 500 PSI.

3 STROKES. CLEANED WELLHEAD AND LOCATION. RDMO.