Office District 1 – (575) 393-6161	State of New Mexico	Form C-10
	Energy, Minerals and Natural Reso	urces Revised July 18, 201
1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283		WELL API NO. 30-015-39405
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVIS	ION 5. Indicate Type of Lease
<u>District III</u> - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	$STATE \square FEE \square$
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK	
PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number 1
1. Type of Well: Oil Well 🛛	Gas Well 🗌 Other	
2. Name of Operator		9. OGRID Number
COG Operating, LLC		229137 10. Pool name or Wildcat
3. Address of Operator 600 W. Illinois Ave, Midland, T	X 79701	Atoka; Glorieta-Yeso
4. Well Location		Atoka, Gioricia-Teso
	• EAE fact from the S 1	no and 200 fact from the W/ line
	: 545 feet from the S li	
Section 6	Township <b>19S</b> Range <b>26E</b> 11. Elevation (Show whether DR, RKB, RT	
"没有理想是我们在这一种	<b>3387'</b>	, ON, EIC.J
	· · · · · · · · · · · · · · · · · · ·	
12 Check	Appropriate Box to Indicate Nature of	Notice Report or Other Data
	repropriate Dox to indicate rature of	rouee, report of other Data
NOTICE OF I	NTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		DIAL WORK
		ENCE DRILLING OPNS.
PULL OR ALTER CASING		G/CEMENT JOB
DOWNHOLE COMMINGLE		
OTHER:		к Г
13. Describe proposed or com	pleted operations. (Clearly state all pertinent	details and give pertinent dates including estimated d
		aptano, and give pertinent dates, merdanig estimated a
		ultiple Completions: Attach wellbore diagram of
of starting any proposed w proposed completion or re		ultiple Completions: Attach wellbore diagram of
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP @ d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP ( d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotte potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP ( d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotter potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP ( d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotter potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP ( d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP @ d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme <b>NM OIL CONSERVAT</b> ARTESIA DISTRICT
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off.	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP @ d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme NM OIL CONSERVAT
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off.	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP @ d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme <b>NM OIL CONSERVAT</b> ARTESIA DISTRICT NOV <b>2 0</b> 2017
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off.	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP ( d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotter potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme <b>NM OIL CONSERVAT</b> ARTESIA DISTRICT
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off. pud Date:	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da Rig Release Date:	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP ( d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme NM OIL CONSERVAT ARTESIA DISTRICT NOV 2 0 2017 RECEIVED
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off. pud Date:	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP ( d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme NM OIL CONSERVAT ARTESIA DISTRICT NOV 2 0 2017 RECEIVED
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off. pud Date:	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da Rig Release Date:	Illar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP ( d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme NM OIL CONSERVAT ARTESIA DISTRICT NOV 2 0 2017 RECEIVED knowledge and belief.
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off. pud Date:	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da Rig Release Date:	Illar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP @ d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme NM OIL CONSERVATI ARTESIA DISTRICT NOV 2 0 2017 RECEIVED knowledge and belief.
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off.  pud Date: hereby certify that the information IGNATURE	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da Rig Release Date:	Illar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP @ d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme NM OIL CONSERVATI ARTESIA DISTRICT NOV 2 0 2017 RECEIVED knowledge and belief.
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off. pud Date: hereby certify that the information IGNATURE ype or print name Kanica	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da Rig Release Date:	Illar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP @ d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme NM OIL CONSERVAT ARTESIA DISTRICT NOV 2 0 2017 RECEIVED knowledge and belief.
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off.  pud Date: hereby certify that the information IGNATURE	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da Rig Release Date:	Illar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP @ d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme NM OIL CONSERVAT ARTESIA DISTRICT NOV 2 0 2017 RECEIVED knowledge and belief.
proposed completion or re 11/02/17 MIRU plugging equ 3060'. Circulated hole w/ MI WOC. Tagged plug @ 2900'. 25 sx class C cmt @ 1323-117 Spotted 30 sx class C cmt @ welder. Dug out cellar. Cut o Cleaned location, moved off. pud Date: hereby certify that the information IGNATURE ype or print name Kanica	completion. ipment. ND wellhead, NU BOP. Dug out ce .F. Pressure tested csg, held 500 psi. Spotted Spotted 25 sx cmt @ 2488-2335'. Perf'd csg 70'.WOC. 11/06/17 Tagged plug @ 1185'. S 160' & circulated to surface. Rigged down a ff well head. Welded on "Above Ground Da Rig Release Date:	ultiple Completions: Attach wellbore diagram of llar, RIH w/ 7" CIBP to 3087'. 11/03/17 Set CIBP @ d 25 sx class C cmt w/2% CACL @ 3060-2910'. g @ 1275'. Pressured up on perfs to 600 psi. Spotted potted 80 sx class C cmt @ 950-491'. ND BOP. and moved off. 11/11/17 Moved in backhoe and ry Hole Marker''. Backfilled cellar. Cut off deadme NM OIL CONSERVATI ARTESIA DISTRICT NOV 2 0 2017 RECEIVED