Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED

OMB NO. 1004-0137 Expires: January 31, 201
5. Lease Serial No. NMNM108027

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

abandoned wel	6. If Indian, Allottee or Tribe Name							
Subsequent Report	ment, Name and/or No.							
· ·								
2. Name of Operator	Contact: AB		·		D-S1			
600 W ILLINOIS AVENUE)					
	., R., M., or Survey Description)			11. County or Parish, State				
Sec 3 T26S R25E NWSW 198	BOFSL 660FWL			EDDY COUNTY, NM				
12. CHECK THE AF	PPROPRIATE BOX(ES) TO	INDICATE NATURE C	F NOTICE,	REPORT, OR OTH	ER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION							
✓ Notice of Intent	☐ Acidize	idize		tion (Start/Resume)	☐ Water Shut-Off			
	☐ Alter Casing	☐ Hydraulic Fracturing ☐ Re		ation	■ Well Integrity			
☐ Subsequent Report	□ Casing Repair	■ New Construction	Recomp	plete	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon ☐ Temp		rarily Abandon				
	☐ Convert to Injection	☐ Plug Back	imated starting date of any proposed work and approximate duration thereof. In and measured and true vertical depths of all pertinent markers and zones. If BLM/BIA. Required subsequent reports must be filed within 30 days observed to the completion of the comple					
determined that the site is ready for fi 1. Set 7" CIBP @ 7400'. Circu 2. 7" CIBP @ 5450-5300'. Circu 5450-5300'.	inal inspection. late hole w/ mud laden fluid. culate hole w/ mud laden flui	Spot 25 sx cmt @ 7400-7 d. Pressure test csg. Spot	'250 '. 7 	" High Kar. 30 35	at Potential" io' 1/2			
		NM OIL CONSI	ERVATIO	N CACTACL	IED EOD			
00	11-27-17			CLL ATTAUL	ובט דטול			
Accepted for	record - NMOCD '	NOV 2 2	2017	CONDITIONS	S OF APPROVA			
Co	Electronic Submission #385 For COG OPE ommitted to AFMSS for proce	ssing by JAMES AMOS on	09/14/2017 (1	n System RECLAI 17JA0165SE)				
Signature (Electronic S	Submission)	Date 08/18/2	2017					
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE U	SE				
Conditions of approval, if any, are attached		warrant or	,	16T	11-16-17 Date			
which would entitle the applicant to condu	ct operations thereon.	Office Z		aka to any department on	aganay of the United			
States any false, fictitious or fraudulent s	statements or representations as to a	ne for any person knowingly and any matter within its jurisdiction	i williumy to m	ake to any department or	agency of the Onited			

WELL NAME: Yellowstone 3 Federal #3

STATE: New Mexico API NO: 30-015-39823

8326

TD:

FIELD: Cottonwood Bone Spring

COUNTY: Eddy SPUD DATE: 2/20/2012 PBTD: 8308

LSE#: NM-108027

LOCATION: 1980' FSL & 660' FWL Sec. 3 T26S-R25E

FORMATION:

ELEVATION: 3,684' GL (+12') ' KB

6. Perf & Sqz 55 sx cmt @ 100'-Surface. 13 3/8" J55 54.5# STC Set @ 420' cmt: 500 sx TOC: Surface 5. Perf & Sqz 55 sx cmt @ 470-370', WOC & Tag. (Shoe)

TOC @ 600'

9 5/8" N80 40# LTC

Set @ 1609'

cmt: lead 700 sx, tail 200 sx TOC. Surface

4. Perf & Sqz 55 sx cmt @ 1660-1560', WOC & Tag. (Shoe)

Q DV Tool @ 3,040

3. Spot 25 sx cmt @ 3090-2990', WOC & Tag.

2. $7^{\rm tr}$ CIBP $\widehat{a_{\rm s}}$ 5450-5300'. Circulate hole w/ mud faden fluid. Pressure test esg. Spot 25 sx emt (a: 5450-5300).

Perf Avalon 5583'-5874'

1. Set 7" CIBP @ 7400'. Circulate hole w/ mud laden fluid. Spot 25 sx cmt @: 7400-7250'.

Per' 2nii 25 7460'-7524

Perf 3rd BS 7941-8254 7" P110 26# LTC Set @ 8320

TD:83261

PBTD 8308

CMt. 1st stage" 1360 sx. 2nd stage 490 sx

100 @ 800

32.0699768 -104.3898697



111111111111111111111111111111111111111	WELL NAME: Yellowstone 3 F	Federal #3	FIELD:	Cattonwood Bon	e Spring	LSE#:	NM-108027					
	STATE: New Mexico		COUNTY:	Eddy		LOCATION:	1980' FSL &	660' FWL S	ec. 3 T26S-R25E			
Ciec to Sur	API NO: 30-015-39823		SPUD DATE:	2/20/2012		FORMATION:						
FC @ 420 65'	TD: 8326'		РВТО:	8308'		ELEVATION:	EVATION: 3,684' GL (+12') ' KB					
13.375" @ 420'			RECORD					CEMENT & F				
	CSG OD	GRADE TH		TOP	ВТМ	# JTS	BIT SIZE	DEPTH	sx	WT.	TOC	
12/4"	Surt 13 375" Intermediate 9.625"	J-55 ST		D.	420' • 1609'		17.500° 12.250°	Lead	500 700	14 8 ppg	Surf Surf	
111111111111111111111111111111111111111	Intermediate 9.625"	NBO LT	C 40.0#	0	1609.	53	12.250	Tail	200		Sur	
TOC @ 800 CBC	Prod 7,000"	P-110 LT	rC 26 0#	0	8320	185	8.750"	1st stage	1360	14.2 ppg	800	
			1	1				2nd stage	490	Ì		
			1									
Circ to Sui	ב		1]]								
Circ 7034		J-55 8r	rd 4 7#	0'		1		L		1		
50 @ 1500	Remarks: 4/5/2012 Perl 3rd BS 794	1' 8254'										
FC @ 1,569'	4/9/2012 Frac 3rd BS w/ 4		+ 161 000# 20/40 wh	nite								
	Perf 2nd BS 745											
	Frac 2nd BS w/	,3395bbls 20# Borate mix	x + 86,000# 20/40 whi	ite								
	Perf Avaion 558	3'-5874'										
834	Frac Avaion w/	4,365bbls 20# Borate mis	× + 178,000# 20/40 wh	nite			CAPACITIES		(bbl/ft)	(ft/bbl)	(cf/f	
) · Y		,					TBG: 2.375 CSG 7 in		.00387 .01554	258 65 64.34	021 087	
		/a	= (4	かさん			030 1 111	20#	.51354	04.04	-	
		(/ 5	-a (7	50°			VOLUME BI	ETWEEN	(bbl/ft)	(ft/bbl)	(cf/	
							TBG+CSG	2.375x7	.01006	99.37	055	
							TBG+CSG					
	1						CSGEHOLE					
	130 (800 CBL)	_	(yn 2 (yn 2 (yn 3				TBGsHOLE TBGsHOLE					
	1000	73.160	1 1	3 8 8		PERFORATIO						
Bim Ryl-Wrap @	770	UEN	7"	- 0 0		DATE	ТОР	MTS	ZONE	STATUS	SF	
(4)	4 > 1					4/5/2012	8253	8254	3rd Bone Springs	Open	4	
7/3/		,				4/5/2012	8134	8135	3rd Bone Springs	Open	} 4	
100 200 54	7	- Class	./ >	787		4/5/2012	5082	8083	3rd Bone Spr-ngs	Oper.	4	
DAC		Chel 19	779	00,		4/5/2012 4/5/2012	8018' 7941	8019' 7942'	3rd Bone Springs 3rd Bone Springs	Open	4	
10 NOV TOOL @ 3,040						4/9/2012	7522	7524	2nd Bone Springs	Open	2	
DNC. 123	لي ا	`				4/9/2012	7493	7495	2nd Bone Springs	Open	,	
	7	Brish	. (:	3714		4/9/2012	7450	7452	2nd Bone Springs	Open	l	
		D. W. C.	7 71 -	30		4/9/2012	5872	5874	Avalor	Open	2	
						4/9/2012	5824	5826	Avalon	Open	2	
		70	C	CED		4/9/2012 4/9/2012	5785' 5712'	5787' 5714'	Avaion	Open		
		15 5	4	Y 0 2		4/9/2012	5664	5666	Avaion	Open		
						4/9/2012	5583	5585	Avalor	Open		
								}	Ì			
									İ	Ì		
							1		ì			
EOT @ 5,475						Ì		1	1			
Perl Avaior: 5583-5874]			
	<u> </u>					7	}			1		
1			SRC WI%:				1				i	
			LOGS:				<u> </u>	<u> </u>		<u> </u>	<u></u>	
			LANDMAN:			GEOLOGIST:	ODS BEDE	OPMANCE				
						TOBOLAR GO	ID	Drift	Collapse	Burst*	Tens	
			Material				(in)	(in)	(psi)	(psi)	(tb:	
			13 375" J-55	STC 54 5#			8 097	7 972	370	2.950	253	
										İ		
			7' P-110 LTC	26#			4 000	3 575	0,350	7,780	212.	
Perl 2rd BS 7450175241			2 3751 J-55 86	r: 4 7#			995	1 1 90-	8 100	700	71	
	•		200 303 80	0 T (N] aa3	1,90	3 100	.700	(' '	
			1				1	1				
Perl 3rd BS 7941-6254	~		· Safety Facto	Net Included			<u>L</u>			L		
°C@3.223 8318	_											
7' @ 8325'		2.0699768		PREPARED BY:				OFFICE:				
TD:6326' PBTD:8308'	-10	04.3898697			3/29/2012			FAX				
アコ・レ じゅんど				Undated:	4(18/2012							

Updated: 4/18/2012

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Henryetta Price Environmental Protection Specialist 575-234-5951

Shelly Tucker Environmental Protection Specialist 575-234-5979

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612