

Submit 3 Copies
to Appropriate
District Office
DISTRICT I
1625 N. French Drive, Hobbs, NM 88240

DISTRICT II
1301 Grand, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, New Mexico 87505

Form C-103
Revised 1-1-89

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-25454
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator STRATA PRODUCTION COMPANY		6. State Oil & Gas Lease No. E-5229
3. Address of Operator P.O. BOX 1030, ROSWELL, NEW MEXICO 88202-1030		7. Lease Name or Unit Agreement Name Forty Niner Ridge
4. Well Location Unit Letter F : 2310' Feet From The North Line and 1980 Feet From The West Line Section 16 Township 23 South Range 30 East NMPM Eddy County		8. Well No. #3
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3124' GR		9. Pool Name or Wildcat Forty Niner Ridge Delaware

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <u>Recompletion</u> <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103

Circ hole clean. Drop rabbit. TOH w/work string. Sting out of hanger at 6099.5'. Rev out & pull 10 stnds. SISD. WOC. TOH w/work string. PU GIH w/4 3/4" bit, bit-sub & 4 collars. Clean out top of liner hanger. TOH & LD 60 jnts 2 7/8" work string. SISD. TIH. Circ hole clean w/2% KCL & spot 7 1/2"% acid at 7360'. TOH w/tbg. RU Schlumberger and prep to perf lower "L" zone. TIH w/guns. Had misfire on guns. SISD. PU and GIH w/3 1/8" pkr. Set pkr at 7273'. Acidize. Had fair ball action. RU swab. Swab. SISD. Waiting on frac crew. Rel pkr and TOH w/tools and tbg. PU 5 1/2" pkr. Set pkr @ 6060'. Flange up. WO crew. Flow well back on 1/8" choke. Lay flow line to frac tanks and leave flowing to tanks overnight. SD. Rel pkr and TOH w/tools.

RECEIVED
APR 14 2006
OCD-ARTECOIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly M. Britt TITLE Production Records DATE 04/13/06
TYPE OR PRINT NAME Kelly M. Britt TELEPHONE NO. 505-622-1127 Ext 15

(This space for State Use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

FOR RECORDS ONLY

DATE

APR 14 2006