Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT NMOCD

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM100558

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2					6. If Indian, Allottee or Tribe Name		
					7. If Unit or CA/Agre	eement, Name and/or No.	
	TAIL EIGHTE - Other ma	a a caons on	page 2				
1. Type of Well ☐ Other ☐ Other					8. Well Name and No. TUCKER DRAW 9-4 FED COM 3H		
Name of Operator Contact: CRYSTAL FULTON RKI EXPLORATION & PROD LLC E-Mail: crystal.fulton@wpxenergy.com					9. API Well No. 30-015-44486		
3a. Address 3500 ONE WILLIAMS CENTE TULSA, OK 74172	3b. Phone No Ph: 539-57	(include area code) 3-0218		10. Field and Pool or Exploratory Area PURPLE SAGE;WOLFCAMP(GAS			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 16 T26S R30E 250FNL 1413FEL					EDDY COUNTY, NM		
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TÝPE OF ACTION						
Notice of Intent	☐ Acidize	☐ Dee	☐ Deepen		ion (Start/Resume)	☐ Water Shut-Off	
M Notice of Intent	☐ Alter Casing	☐ Hyd	☐ Hydraulic Fracturing		ation	■ Well Integrity	
☐ Subsequent Report	□ Casing Repair	□ Nev	v Construction	□ Recomplete		Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug	☐ Plug and Abandon		arily Abandon		
	☐ Convert to Injection	□ Plug	g Back		Disposal		
ATTN: CHRIS WALLS & JENI RKI EXPLORATION & PRODI WELL. Attached is our planned proce Chris Walls.	UCTION, LLC REQUEST	gram, and a (ERVATION! STRICT 2018	
14. I hereby certify that the foregoing is Name (Printed/Typed) CRYSTAL	Electronic Submission # For RKI EXPLO Committed to AFMSS for	405962 verifie RATION & PR	DD LLC, sent to t / JENNIFER SANG	I Information he Carlsbad HEZ on 02/	28/2018 ()		
Name (11mew Typeu) GR 131AL	FOLION		THE PERIM	AP	PROVED	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Signature (Electronic S			Date 02/27/20			7 1	
	THIS SPACE FO	OR FEDERA	AL OR STATE	OFFICE	SE DONO	la IX	
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conductive the applicant to c	uitable title to those rights in that operations thereon.	e subject lease	Title Office	/UARLS	LAND MAJAGEME BAD FIEUD OFFICE		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	s to any matter w	erson knowingly and rithin its jurisdiction.	willfully to m	ake to any department o	or agency of the United	
(Instructions on page 2) ** OPERA	OR-SUBMITTED ** C	PERATOR-	SUBMITTED *	* OPERAT	TOR-SUBMITTED	o ** //	



RKI Exploration & Production, LLC Tucker Draw 9-4 Fed Com 3H

Drilling Program Eddy County, NM

February 19, 2018

9-5/8" x 7" Remedial Squeeze

Objective: The objective is to remediate the TOC behind the 7" casing to at least 200-ft above the 9-5/8" casing shoe.

API #: 30-015-44486

Procedure


- 1. Notify BLM at least 4 hours prior to upcoming cement job.
- 2. MIRU Par Five Equipment
- 3. Record pressure on 7" casing and 9-5/8" x 7" annulus. Bleed off pressure on 9-5/8" x 7" annulus if any.
- 4. Tie into 2-1/16" 5K inlet valve on wellhead to pump down 9-5/8" x 7" annulus.
- 5. Test cement lines to 3,000 psi.
- 6. Establish injection rates at 2, 3, and 4 bpm with 50 bbls of freshwater. Record pressures at each rate.
 - a. Do not exceed 2,000 psi while pumping cement job. Set pump kick out at 2,000 psi.
 - b. Discuss with drilling superintendent/engineer if additional pressure is needed.
- 7. Pump 441 sx, 150 bbls of 35/65 Poz C with additives, mixed @ 12.9 ppg & 1.91 ft³/sk
- 8. Displace cement with 3 bbls of freshwater
 - a. Treat freshwater with corrosion inhibitor to protect casing
- 9. Open other 2-1/16" 5K inlet valve to 9-5/8" x 7" annulus and monitor to see if well is on vacuum.
 - a. Close both valves and shut well in if well is on a vacuum while monitoring
- 10. Record pump rates and pressures. Send data to engineer to be entered into Openwells.

Tucker Draw Fed Com 9-4-3H



Wellbore Diagram

Wolfcamp Lower A Eddy County, NM API #: 30-015-44486 Rig Release Date: 01/19/2018



Date Prepared:

2/9/2018