District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-101 May 27, 2004

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit to appropriate District Office

to appropriate District Office

☐ AMENDED REPORT

APPI	LICAT	ION FO			LL. RE-	ENTER.	DEEPE	N. PLUGBA	CK. O	RAD	D A ZONE
			Operator Name: O PRODUCI O BOX 103	NG COMPA	ANY	,		² OGRID Number	0178	391	
							ΕΙΛ≟Ŭ	30 -	:r		
	'Property Code										
1705	562	3	V	ORTEC "	22"		ut 1881	Α.		We	II No. 1
Proposed Pool 1 BONE SPRING 94473									osed Pool 2	2	
Pierce	Cres	, U) 3185	•	En 57	⁷ Surface	Location					
UL or lot no.	Section 22	Township 24S	Range 29E	Lot Idn	Feet fro 33		h South line OUTH	Feet from the 330 *	East^Ve EAST		County EDDY
	,	·	* Propos	ed Bottom	Hole Loca	tion If Diffe	ent From	Surface			
UL or let no.	Section 22	Township 24S	Range 29E	Let Ida	Feet fro	_	たSouth line OUTH	Feet from the 1650*	East/We WEST		County EDDY
			·			ll Informa			 		
" Work"	Type Code		Well Type Code O	•	r: Cable ROTA	e/Rotary RY	'	' Lease Type Code P		¹⁹ Grou	and Level Elevation
N/O	lultiple)		"Proposed Depth 0797 TVD76	53	"For	mation PRTNG	PAT	"Contractor	WH		Spud Date PPROVED
Depth to Grou	ndunia G	REATER ' ESS THA	THAN 50'	Distance fro	in nearest fres	L	6 mi SV				SOUTHWEST
Ein Liner:			Is thick Clay	Pit Volume:	: <u>18M</u> bbls		lling Alether		T V Lik		SOUTHWEST
Close	d-Loop Sys	tem 🗌 .		·				Banc X Diesel-C	il-based [ا (مون	Nie []
			21	Proposed	Casing a	nd Cemer	it Progra	<u>m</u>			
Hole S	ize		inę Size	Casing we	ight/foot	Setting	Depth	Sacks of Co	ment		Estimated TOC
26"	1 11			Conduct		40		Redi-mix			ace.
12½"	2	13 3		48# 40#		550 2900		350 Sx.		Surf Surf	
	7 7/8"	5½"		17#				3' 900 Sx.			' from surfa
			this application is am, if any. Use as				a on the pre	sent productive zone	and propo	sed new	r productive zone.
	nowout pro	veilion progr	and, it any. Oscial	zennonar snecr	.3 11 110003321.	•					
İ											
			SEE	ATTACH	ED SHEE	T FOR DE	TAILS				
ļ											
		•									
								•			
			given above is true				OIL C	ONSERVAT	ION D	IVISI	ON
			certify that the cuidelines 💹 a g			Approved by					
an (attached)				\bigcirc			<u> </u>	BRYAN G. A. DISTRICT II	KKAN'	l OGI 9	77 2
Printed name:	Joe T	. Janica	JoeT.	Car	ica	Title: .					
Title: Ager			1			Approval Da	e: APR	2 4 2006 E	xpiration D	ate: A	PR 2 4 2007
E-mail Addres	ss:joeja	anicaeva	alornet.co	m				· 			
Date: 04/2	Date: 04/21/06 Phone: 505-391-8503				Conditions of Approval Attached						

State of New Mexico

DISTRICT I 1625 N. FRENCH DR., HOBBS, NM 88240

Energy, Minerals and Natural Resources Department

DISTRICT II

1301 W. GRAND AVENUE, ARTESIA, NM 88210

OIL CONSERVATION DIVISION 1220 SOUTH ST. FRANCIS DR. Santa Fe, New Mexico 87505

Form C-102 Revised October 12, 2005 Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 DISTRICT IV WELL LOCATION AND ACREAGE DEDICATION PLAT □ AMENDED REPORT 1220 S. ST. FRANCIS DR., SANTA FE, NM 87505 Pool Code API Number Pool Name 1647 EasT PIERCE CROSSING-BONE SPRING Property Code Property Name Well Number VORTEC 22 OGRID No. Operator Name Elevation POGO PRODUCING COMPANY 017891 2917 Surface Location UL or lot No. Lot Idn Feet from the North/South line Feet from the East/West line County Section Township Range Р 22 24-S 29-E 330 SOUTH 330 **EAST** EDDY Bottom Hole Location If Different From Surface UL or lot No. Section Lot Idn Feet from the North/South line Feet from the East/West line County Township Range N 22 24-S 29-E 660 SOUTH 1650 **WEST EDDY Dedicated Acres** Joint or Infill Consolidation Code 120 NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION OPERATOR CERTIFICATION I hereby certify that the information herein is true and complete to the best of my knowledge and belief, and that this my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location or has a right to drill this well at this location pursuant to a contract with an owner of such mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. Signature Date 04/21/06 Joe T. Janica Printed Name Agent:

GEODETIC COORDINATES NAD 27 NME SURFACE HOLE LOCATION Y=435376.2 N X=614141.7 E BOTTOM HOLE LOCATION Y=435703.0 N LAT. = 32°11'47.14" N X=610825.0 E LONG. = 103°57'51.63" W PROJECT AREA FEE 1650 GRID AZ. GRID. DIST. _ S.

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

APRIL 18, 2006

 $E_{I}^{H_{ij}}$ REV: 4/21/06 Date Surveyed English Signature & Soal of Surveyor

Professional Surveyor

06.11.0672

Certificate Na. GARY EIDSON Management of the Property of

12641

POGO PRODUCING COMPANY VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

- 1. Drill 26" hole to 40'. Set 40' of 20" conductor pipe and cement to surface with Redi-mix.
- 2. Drill 17½" hole to 550', drill surface hole with fresh water. Run and set 550' of 13 3/8" 48# H-40 ST&C casing. Cement with 150 Sx. of 35/65/6 Class "C" POZ/GEL, tail in with 200 Sx. of Class "C" cement + 2% CaCl, + ½# Flocele/Sx., circulate cement to surface.
- 3. Drill 12½ "hole with brine water to a depth of 2900'. Run and set 2900' of 9 5/8" 40# J-55 ST&C casing. Cement with 800 Sx. of 35/65/6 POZ/GEL Class "C" cement + 5% Salt, tail in with 200 Sx. of Class "C" cement + 2% CaCl, + ½# Flocele/Sx. circulate cement to surface, volumes may be changed after fluid caliper is run.
- 4. Drill 8½" hole to 8200'. run logs and set a cement plug for kick off point at 7225', drill 8½" hole through curve to 7730'. Reduce hole to 7 7/8 and drill to 7 7/8" and drill to 10,797'. Run and set 10,800'± of 5½" 17# N-80 BTC & LT&C casing. Cement with 900 Sx. of Class "H" Premium Plus cement + additives, mixed at 15.7 PPG, estimate top of cement 2900' from surface.

MITCHELL ENGINEERING PROGRAMS

AFE VORTEC 22 # 1H.xls


COPYRIGHT 1880 MITCHELL ENGINEERING, PO BOX 1492. GOLDEN. CO, 80402. USA (303) 273 3744

LONG'S METHOD OF SURVEY COMPUTATION


ORLIC	UE CIRCUL	AH AHC	INTERPO	LAHON		_	DISTANCE TA	ABLE
Γ	Q.	MD OF	INTERPOL	ATION DEPTH	l,(feet)		STATION A	STATION B
F	#N/A	TVD CO	TVD COORDINATE OF THE DEPTH (feet)					
H	#N/A			OF DEPTH (fe	•			
⊢				OF DEPTH (%	•			
L	#N/A	E/W CO	OHUMATE	-	•		0.00	ft
				3 D DISTANCE BI	ETWEEN STATION	A AND STATION B		π
TABLE	ABLE OF SURVEY STATIONS Celculator =							
STA	AMD	INCL	AZIM	MD	TVD	Ne/S-	E+M-	DLS
		deq	deg	<u> </u>		h	ft.	des/100FT
	TIE POINT =>	0	0	7225.00	7225.00	0.00	0.00	
2	100	12	275.711	7325.00	7324.27	1.04	-10.38	12,00
3	100	24	275.711	7425.00	7419.20	4.11	-4 1.07	12.00
4.1	100	36	275.711	7525.00	7505.65	9.07	-90.74	12.00
- 5	100	48	275.711	7625.00	7579.83	15.72	-157.19	12.00
6	100	60	275.711	7725.00	7638,50	23.75	-237. <u>55</u>	12.00
7	100	72	275.711	7825.00	7679,10	32.83	-328.28	12.00
В	100	84	275.711	7925.00	7699.85	42.54	-425.43	12.00
9	50	91	275.711	7975.00	7702.03	47.51	-475.11	14.00
10	100	91	275.7 <u>11</u>	8075.00	7700.28	57.48	-574.60	0.00
11	100	91_	275.711	8175.00	7698,54	67,41	-674.09	0.00
12	100	91	275.711	8275.00	7696.79	77.36	-773.57	0.00
13	100	91	275.711	8375.00	7695.05	87.31	-873.06	0.00
14	100	91	275,711	8475.00	7 693 .30	97,20	-972.55	0.00
15	100	91	275.711	8575.00	7691.58	107.20	-1072.04	0.00
16	100	91	275.711	8675.00	7689.81	117.15	-1171.53	0.00
17]	100	91	275,711	6775.00	7688.07	127.10	-1271.02	0.00
18	100	91	275.711	8875,00	7686.32	137.05	-1370.50	0.00
19	100	91	275.711	8975.00	7684.58	147.00	-1469.99	0.00
20	100	91	275.711	9075.00	7882.63	156.95	-1569.46	0.00
21	100	91	275.711	9175.0D	7581.09	166.90	-1668.97	0,00
22	100	91	275.711	9275.00	7679.34	176.85	-1768.46	0.00
23	100	91	275.711	9375.00	7877.60	186.79	-1867.95	0.00_
24	100	91	275.711	9475.00	7675.85	196.74	-1967.44	0.00
25	100	91	275.711	9575.00	7674.10	206,69	-2086.92	0.00
26	100	91	275.711	9675.00	7872.36	215.84	-2166.41	0.00
27	100	91	275.711	9775. <u>00</u>	7670,81	228.59	-2265.90	0.00
28	100	91_	275.711	9875.00	7668.87	236,54	-2385.39	0.00
29	100	91	275.711	9975.00	7667.12	246,49	-2464.88	0.00
30_	100	91	275.711	10075.00	7665.38	258.44	-2564,37	0.00
31	100	91	275.711	10175.00	7663.63	286.39	-2663,86	0.00
32	100	91	275.711	10275.00	7661.89	276.33	-2763.34	0.00
33	100	91	275.711	10375.00	7660.14	286,28	-2862.83	0.00
34	100	91	275.711	10475.00	7658.40	296,23	-2962.32	0.00
35	100	91	275,711	10575.00	7656.65	306.18	-3061.81	0.00
38	100	91	275.711	10675.00	7654.91	316.13	-3161.30	0.00
37	100	91	275.711	10775.00	7653.16	326.08	-3260.79	0.00
38	22	91	275,711	10797.00	7652.78	328.27	-3262.68	0.00

VORTEC 22 # 1 WELL GROUPINGS


Sec 22, T-24-S, R-29-E, Eddy County, New Mexico



Well Name	Legal Location in 22	Depth and Strata	Current Prod Zone
VORTEC 22 # 1	330 FSL & 330 FEL	TD= 8200', HORIZONTAL	PROPOSED
Harroun 22 # 1	660 FNL & 660 FWL	TD= 5360' LCC sand	Delaware Production
Harroun 22 # 2	330 FNL & 1980 FEL	TD= 5500 LCC sand	Delaware Production
Harroun 22 # 3 H	660 FNL & 330 FEL	TD= 10864 Hrz 1st Bone Sd	1st Bone Production
Jackal 22 Fed # 1	990 FSL & 230 FWL	NOT DRILLED	NOT DRILLED
Jackal 22 Fed # 2	1710 FSL & 630 FWL	TD= 5450 G-3,LCC	Delaware Production
Riverbend Fed # 1	1650 FNL & 1650 FWL	TD= 5500 G-3	Delaware Production
Riverbend Fed # 5	2310 FNL & 860 FEL	TD= 5420 G-6,G-3, LCC	Delaware Production
Riverbend Fed # 9	1650 FNL & 330 FWL	TD= 7900 1st Bone Sd.	Delaware Production
	2310 FSL & 1750 FWL	NOT DRILLED	NOT DRILLED
Riverbend 22 Fd # 13	1650 FSL & 2310 FEL	NOT DRILLED	NOT DRILLED




VICINITY MAP




SCALE: 1" = 2 MILES

SEC. <u>22</u> IW	P. <u>24-5</u> RGE. <u>29-E</u>
SURVEY	N.M.P.M.
COUNTYEDE	OY STATE NEW MEXICO
DESCRIPTION_3	330' FSL & 330' FEL
ELEVATION	2917'
OPERATOR	POGO PRODUCING COMPANY
LEASE	VORTEC 22





LOCATION VERIFICATION MAP



SCALE: 1" = 2000'

CONTOUR INTERVAL: PIERCE CANYON, N.M. - 10'

SEC. 22 TWP. 24-S RGE. 29-E
SURVEYN.M.P.M.
COUNTY EDDY STATE NEW MEXICO
DESCRIPTION 330' FSL & 330' FEL
ELEVATION 2917'
POGO PRODUCING OPERATOR COMPANY
LEASE VORTEC 22
U.S.G.S. TOPOGRAPHIC MAP PIERCE CANYON, N.M.




PROVIDING SURVEYING SERVICES
SINCE 1946
JOHN WEST SURVEYING COMPANY
412 N. DAL PASO
HOBBS, N.M. 88240
(806) 393-3117

BLOWOUT PREVENTER SYSTEM

3000 PSI

Fill Line

Flow Line



To Pit

Bleed Line to Pit

Adjustible Choke

Choke Line

POGO PRODUCING COMPANY
VORTEC "22" # 1
UNIT "P" SECTION 22
T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

This well and its anticipated facility are not expected to have Hydrogen Sulfide releases. However, there may be Hydrogen Sulfide production in the nearby area. There are no private Residences in the area but a contingency plan has been orchestrated. Pogo Producing Company will have a Company Representative living on location through out the drilling of this well. An un-manned H2S safety trailer and monitoring equipment will also be station on location during the drilling operation below the Surface Casing depth of ± 550 ft. until the completion of the subject well at ± 10,700 ft.

VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

TABLE OF CONTENS

COVER PAGE AND REASONING	page 1
GENERAL EMERGENCY PLAN	page 3
EMERGENCY PROCEDURE FOR UNCONTROLLED RELEASES OF H2S	page 3-4
EMERGENCY NUMBERS AND	page 4-5
PRODUCTION OF THE GENERAL RADIUS OF EXPOSURE (ROE)	page 6
PUBLIC EVACUATION PLAN	page 6-7
PROCEDURE FOR IGNITING AN UNCONTROLLABLE CONDITION:	
PRECEDURE FOR IGNITION	page 7
REQUIRED EMERGENCY EQUIPMENT	page 8
USING SELF CONTAINED BREATHING AIR EQUIPMENT (SCBA)	page 9
RESCUE & FIRST AID FOR VICTIMS OF HYDROGEN SULFIDE (H2S) POISONING	page 9-10
H2S TOXIC EFFECTS	page 11
H2S PHYSICAL EFFECTS	page 11
LOCATION MAP	page 12-13

VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

General H2S Emergency Actions:

- 1. All personnel will immediately evacuate to an up-wind and if possible up-hill "safe area"
- 2. If for any reason a person must enter the hazardous area, they must wear a SCBA (Self Contained Breathing Apparatus)
- 3. Always use the "buddy system"
- 4. Isolate the well/problem if possible
- 5. Account for all personnel
- 6. Display the proper colors warning all unsuspection personnel of the danger at hand.
- 7. Contact the Company personnel as soon as possible if not at the location. (use the enclosed call list as instructed

At this point the company representative will evaluate the situation and coordinate the necessary duties to bring the situation under control, and if necessary, the notification of the emergency response agencies and nearby residents.

EMERGENCY PROCEDURES FOR AN UNCONTROLLABLE RELEASE OF H2S

- 1. All personnel will don the self contained breathing apparatus.
- 2. Remove all personnel to the "safe area". (always use the buddy system).
- 3. Contact company personnel if not on location.
- 4. Set in motion the steps to protect and or remove the general public to an upwind "safe area". Maintain strict security & safety procedures while dealing with the source.
- 5. No entry to any unauthorized personnel.
- Notify the appropriate agencies: City Police-City Street (s)
 State Police- State Rd
 County Sheriff County Rd.
- 7. Call the NMOCD

VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

If at this time the supervising person determines the release of H2S cannot be contained to the site location and the general public is in harms way he will take the necessary steps to protect the workers and the public.

EMERGENCY CALL LIST: (Start and continue until ONE of these people have been contacted)

	OFFICE	MOBILE	HOME
POGO Producing Co.	432 685 8100		
Richard Wright	432 685 8140	432 556 7595	432 699 7108
Barrett Smith	432 685 8141	432 425 0149	432 520 7337
Rex Jasper	432 685 8143	432 631 0127	432 694 1839
Donny Davis	pgr 432 563 6944	432 556 5927	432 570 9555
Jerry Cooper	432 685 8101		432 697 4629
EMERGENCY RESPONSE N	IUMBERS:		
State Police: State Police:	Eddy County Lea County	-	505 748 9718 505 392 5588
Sheriff Sheriff	Eddy County Lea County		505 746 2701
Emergency Medical Ser (Ambulance)	Eddy County Lea County	Eunice	911 or 505 746 2701 911 or 505 394 3258
Emergency Response	Eddy County SERC Lea County		505 476 9620
Artesia Police Dept Artesia Fire Dept			505 746 5001 505 746 5001

VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

Carlsbad Police Dept Carlsbad Fire Dept		505 885 2111 505 885 3125
Loco Hills Police Dept		505 677 2349
Jal Police Dept Jal Fire Dept Jal ambulance		505 395 2501 505 395 2221 505 395 2221
Eunice Police Dept Eunice Fire Dept Eunice Ambulance		505 394 0112 505 394 3258 505 394 3258
Hobbs Police Dept		
NMOCD	District 1 (Lea, Roosevelt, Curry) District 2 (Eddy Chavez)	505 393 6161 505 748 1283
Lea County Information		505 393 8203
Callaway Safety	Lea/Eddy County	505 392 2973
BJ Services	Artesia Hobbs	505 746 3140 505 392 5556
Halliburton	Artesia Hobbs	1 800 523 2482 1 800 523 2482
Wild Well Control	Midland Mobile	432 550 6202 432 553 1166

VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

PROTECTION OF THE GENERAL PUBLIC (ROE):

- 100 ppm at any public area (any place not associated with this site)
- 500 ppm at any public road (any road which the general public may travel)
- 100 ppm radius of ¼ mile in New Mexico will be assumed if there is insufficient data to do the calculations, and there is a reasonable expectation that H2S could be present in concentrations greater than 100 ppm in the gas mixture

CALCULATIONS FOR THE 100 PPM (ROE) "Pasquill-Gifford equation"

X = [(1.589) (mole fraction) (Q - volume in std cu ft)] to the power of (0.6258)

CALCULATION FOR THE 500 PPM ROE:

X = [(.4546) (mole fraction) (Q - volume in std cu ft)] to the power of (0.6258)

Example:

If a well/facility has been determined to have 150 / 500 ppm H2S in the gas mixture and the well/facility is producing at a gas rate of 100 MCFPD then:

150 ppm X = [(1.589) (.00015) (100,000 cfd)] to the power of (.6258) X = 7 ft

500 ppm X = [(.4546) (.0005) (100,000 cfd)] to the power of (.6258) \times X = 3.3 ft.

(These calculations will be forwarded to the appropriate District NMOCD office when Applicable)

PUBLIC EVACUATION PLAN:

- 1. Notification of the emergency response agencies of the hazardous condition and implement evacuation procedures.
- A trained person in H2S safety, shall monitor with detection equipment the H2S concentration, wind and area exposure (ROE). This person will determine the outer perimeter of the hazardous area. The extent of the evacuation area will be determined from the data being collected. Monitoring shall continue until the situation has been resolved. (All monitoring equipment shall be UL approved, for use in class 1

VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

groups A,B,C &D, Division 1, hazardous locations. All monitor will have a minimum capability of measuring H2S, oxygen, and flammable values).

- Law enforcement shall be notified to set up necessary barriers and maintain such for the duration of the situation as well as aid in the evacuation procedure.
- The company supervising personnel shall stay in communication with all agencies through out the duration of the situation and inform such agencies when the situation has been contained and the effected area(s) is safe to enter.

PROCEDURE FOR IGNITING AN UNCONTROLABLE CONDITION:

- 1. Human life and/or property are in danger
- 2. There is no hope of bringing the situation under control with the prevailing conditions at the site.

INSTRUCTION FOR IGNITION:

- 1. Two people are required. They must be equipped with positive pressure, self contained breathing apparatus and a "D" ring style full body, OSHA approved safety harness. Non flammable rope will be attached.
- 2. One of the people will be qualified safety person who will test the atmosphere for H2S, Oxygen & LFL. The other person will be the company supervisor; he is responsible for igniting the well.
- 3. Ignite up wind from a distance no closer than necessary. Make sure that where you
 ignite from has the maximum escape avenue available. A 25 mm flare gun shall be used,
 with a ± 500 ft. range to ignite the gas.
- 4. Prior to ignition, make a final check for combustible gases.
- 5. Following ignition, continue with the emergency actions & procedures as before.

VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

REQUIRED EMERGENCY EQUIPMENT:

1. Breathing apparatus:

- ➤ Rescue Packs (SCBA) 1 unit shall be placed at each breathing area, 2 shall be stored in the safety trailer.
- ➤ Work/Escape packs 4 packs shall be stored on the rig floor with sufficient air hose not to restrict work activity.
- ➤ Emergency Escape Packs 4 packs shall be stored in the doghouse for emergency evacuation.

• 2. Signage & Flagging:

- > One color code condition sign will be placed at the entrance to the site reflection the possible conditions at the site.
- > A colored condition flag will be on display, reflecting the condition at the site at the time.
- 3. Briefing Area: two perpendicular areas will be designated by signs and readily accessible.
- 4. Wind Socks: Two wind socks will be placed in strategic locations, visible from all angles.
- 5. H2S detectors and alarms: The stationary detector with thre sensors will be placed in the upper dog house if equipped, set to visually alarm @ 10 ppm and audible @ 14 ppm. Calibrate a minimum of every 30 days ora as needed. The sensors will be placed in the following places: (Gas sample tubes will be stored in the safety trailer)
 - Rig Floor
 - > Bell Nipple
 - > End of Flow line or where well bore fluid are being discharged.

• 6. Auxiliary Rescue Equipment:

- > Stretcher
- > Two OSHA full body harness
- > 100 ft 5/8 inch OSHA approved rope

POGO PRODUCING COMPANY VORTEC "22" # 1

UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

- > 1-20# class ABC fire extinguisher
- > Communication via cell phones on location and vehicles on location.

USING SELF CONTAINED BREATHING AIR EQUIPMENT (SCBA):

- (SCBA) SHOULD BE WORN WHEN ANY OF THE FOLLOWING ARE PERFORMED:
 - > Working near the top or on top of a tank
 - > Disconnecting any line where H2S can reasonably be expected
 - > Sampling air in the area to determine if toxic concentrations of H2S exist.
 - > Working in areas where over 10 ppm on H2S has been detected.
 - > At any teim there is a doubt as the level of H2S in the area.
- All personnel shall be trained in the use of SCBA prior to working in a potentially hazardous locaton.
- Facial hair and standard eyeglasses are not allowed with SCBA.
- Contact lenses are never allowed with SCBA.
- Air quality shall be continuously be checked during the entire operation.
- After each use, the SCBA unit shall be cleaned, disinfected, serviced and inspected
- All SCBA shall be inspected monthly.

RESCUE AND FIRST AID FOR VICTIMS OF HYDROGEN SULFIDE (H2S) POISONING:

- Do not panic
- Remain Calm & think
- Get on the breathing apparatus

POGO PRODUCING COMPANY VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

- Remove the victim to the safe breathing area as quickly as possible. Up wind an uphill from source or cross wind to achieve upwind.
- Notify emergency response personnel.
- Provide artificial respiration and or CPR, as necessary
- Remove all contaminated clothing to avoid further exposure.
- A minimum of two personnel on location shall be trained in CPR and First Aid.

VORTEC "22" # 1 UNIT "P" SECTION 22 T24S-R29E EDDY CO. NM

HYDROGEN SULFIDE CONTINGENCY PLAN FOR DRILLING/WORKOVER/FACILITY

HYDROGEN SULFIDE TOXIC EFFECTS

H2S is extremely toxic. The acceptable ceiling for eight hours of exposure is 10 ppm, which is .001% by volume. H2S is approximately 20% heavier than air (Sp. Gr= 1.19)(Air = 1) and colorless. It forms an explosive mixture with air between 4.3% and 46%. By volume hydrogen sulfide is almost as toxic as hydrogen cyanide and is 5-6 times more toxic than carbon monoxide.

Various Gases

COMMON NAME	CHEMICAL ABBREV.	SPECIFIC GRVTY.	THRESHOLD LIMITS	HAZARDOUS LIMITS	LETHAL CONCENTRATIONS
Hydrogen Sulfide	H2S	1.19	10ppm 15 ppm	100 ppm/hr	600 ppm
Hydrogen Cyanide	HCN	0.94	10 ppm	150 ppm/hr	300 ppm
Sulfur Dioxide	SO2	2.21	2 ppm	N/A	1000 ppm
Chlorine	CL2	2.45	1 ppm	4 ppm/hr	1000 ppm
Carbon Monoxide	CO	0.97	50 ppm	400 ppm/hr	1000 ppm
Carbon Dioxide	CO2	1.52	5000 ppm	5%	10%
Methane	CH4	0.55	90,000	Combustible @ 5%	N/A

Threshold limit: Concentrations at which it is believed that all workers may be repeatedly

exposed, day after day without adverse effects.

Hazardous Limit: Concentrations that may cause death

Lethal

Concentrations: Concentrations that will cause death with short term exposure

Threshold limit -

10 ppm: NIOSH guide to chemical hazards

PHYSICAL EFFECTS OF HYDROGEN SULFIDE:

CONCENTRATION		PHYSICAL EFFECTS
.001%	10 PPM	Obvious and unpleasant odor. Safe for 8 hr exposure
.005%	50 ppm	Can cause some flu like symptoms and can cause pneumonia
.01%	100 ppm	Kills the sense of smell in 3-15 minutes. May irritate the eyes and throat.
.02%	200 ppm	Kills the sense of smell rapidly. Severly irritates the eyes and throat. Severe flu like symptoms after 4 or more ours. May cause lung damage and or death.
.06%	600 ppm	Loss of consciousness quickly, death will result if not rescued promptly.