BU						FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM14468 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					<ol> <li>If Unit or CA/Agreement, Name and/or No. SRM1173</li> </ol>		
1. Type of Well □ Oil Well ⊠ Gas Well □ Other					8. Well Name and No. GRYNBERG 11 FED COM 4		
2. Name of Operator CIMAREX ENERGY COMPANY OF CO-Mail: DEYLER@MILAGRO-RES.COM					9. API Well No. 30-015-34197-00-S1		
3a. Address         3b. Phone No. (inc           202 S CHEYENNE AVE SUITE 1000         Ph: 432-687-30           TULSA, OK 74103.4346         Ph: 432-687-30					10. Field and Pool or Exploratory Area WHITE CITY-WOLFCAMP		
4. Location of Well (Footage, Sec., T. Sec 11 T25S R26E NWNW 88			11. County or Parish, State EDDY COUNTY, NM				
12. CHECK THE AF	PROPRIATE BOX(ES)	) TO INDICAT	E NATURE OI	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
<ul> <li>Notice of Intent</li> <li>Subsequent Report</li> <li>Final Abandonment Notice</li> <li>13. Describe Proposed or Completed Op</li> </ul>	$\Box$ Casing Repair $\Box$ Ne		aulic Fracturing Construction and Abandon Back	<ul> <li>Production (Start/Resume)</li> <li>Reclamation</li> <li>Recomplete</li> <li>Temporarily Abandon</li> <li>Water Disposal</li> </ul>		Water Shut-Off Well Integrity Other	
Attach the Bond under which the woo following completion of the involved testing has been completed. Final A determined that the site is ready for 1 1) SET 5-1/2" CIBP @ 11,150 2) PUMP 45 SXS.CMT. @ 10 3) PUMP 35 SXS.CMT. @ 10 3) PUMP 30 SXS.CMT. @ 5, 6) CUT X PULL 5-1/2" CSG. 7) PUMP 45 SXS.CMT. @ 5, 6) CUT X PULL 5-1/2" CSG. 7) PUMP 45 SXS.CMT. @ 2, 8) PUMP 55 SXS.CMT. @ 2, 8) PUMP 55 SXS.CMT. @ 1, 9) MIX X CIRC. TO SURF. 10 10) DIG OUT X CUT OFF WE HOLE MARKER. DURING THIS PROCEDURE	bandonment Notices must be f final inspection. )'; PUMP 25 SXS.CMT. ( ),448'- <del>10,162'</del> (T/ATOKA 618'-8,438' (T/WFCP.); V 471'-7,301' (5-1/2"DV TC 484'-5,334' (T/B.S.). @ +/-2,615' (5-1/2"CSG. 999'-1,879' (T/DLWR.). 00 SXS.CMT. @ 271'-3'. :LLHEAD 3' B.G.L.; WEL	@ 11,150'-10,9 ,T/STWN.). WOC X TAG CI DOL); WOC X T STUB,9-5/8"CS _D ON STEEL E CLOSED-LC	50'; CIRC. WEL 930 AT. PLUG. AG CMT. PLUG G.SHOE); WOO PLATE TO CSG	L. G. Perf C X TAG. SS. X INSTA	CONDITION CONDITION attempt tos attempt t	S OF APPROV	
14. I hereby certify that the foregoing Co Name (Printed/Typed) DAVID A	Electronic Submission For CIMAREX El mmitted to AFMSS for pro	NERGY COMPA	NY OF CO. sent	on 04/11/201	bau		
			Data 04/00/	2019			
Signature (Electronic	Date 04/09/2		USE				
Approved By	ed Approval of this notice de	oes not warrant or	1	epo. Al		4-28-72 Date	
certify that the applicant holds legal or e which would entitle the applicant to cond	quitable fille to those rights in	the subject lease	Office	1-1-	. 17		

## Additional data for EC transaction #410883 that would not fit on the form

## 32. Additional remarks, continued

THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.

Cimarex Energy Co. of Colorado Grynberg 11 Federal #4 CIMAREX KB 19' above GL 880' FNL & 1270' FWL Sec 11, T-25-S, R-26-E, Eddy Co., NM API # 30-015-34192 7-04/9/2018 S. Gengler 17/2" hok 13-3/8", 48# H-40 csg @ 221' cmtd w/ 230 sx, cmt circ 🖌 12kg hab Del 1939 9-5/8" 40# J-55 csg @ 2675' cmtd w/ 780 sx, cmt circ 🥢 BS 5409 Calc. TOC @ 3800 WL 8528 Cisco-CH 9980 363 its 2-7/8" 6.5# L-80 Tbg St. 10212 DV Tool @ 7386' 200 Store No Ga. 1st Store No Ga. cmtd w/ 1215 sx 8 3/4" hile At 103 98 6C 8880 MR 10360 2-3/8" Landing Nipple w/ 1.812" Baker F nipple Halliburton RTTS pkr @ 11172' Morrow perfs (11215' - 11222') Composite BP @ 11362' Morrow perfs (11398' - 11403') Morrow perfs (11449' - 11456') CIBP @ 11516' **f** 35' cmt. Morrow perfs (11530' - 11534') CIBP @ 11540' + 35' cm) Morrow perfs (11544' - 11550') PBTD @ 12136 5 1/2" 17# P-110 @ 12081' cmtd w/ 1030 sx TD @ 12081

Cimarex Energy Co. of Colorado Grynberg 11 Federal #4 CIMAREX KB 19' above GL 880' FNL & 1270' FWL Sec. 11, T-25-S, R-26-E, Eddy Co., NM API # 30-015-34198 7 04/9/2018 S. Gengler CIPC. 100 545 @ 271'-3' T/ DLWR. ~ 1,939 13-3/8", 48# H-40 csg @ 221' cmtd w/ 230 sx. cmt circ TIB.5. -5,409' M.L.F. Pump 55 5×5. @ 1,999 - 1,879 - TAG T/W.C. ~ 8,528 T/STWH. ~ 10, 212' M.L.F. - Pump 45 SXS @2,735'-2,615'- 7HG 9-5/8", 40# J-55 csg @ 2675' T/ATOKA, ~ 10,398' CECTAR cmtd w/ 780 sx, cmt circ HER SP CUT X PULL 51/2 "CSG. @+1-2,675" Calc. TOC @ 3800' M.L.F. Pump 25 \$x5.@5,484-5,334' A CEST M.L.F. Pump 30 5x5. @7,471-7,301-776-DV Tool @ 7386 cmtd w/ 1215 sx M.L.F. Pump 35 5×5. @8,618'-8,438'- 746 Starty M.L.F. Pump 455x5. @10,448-10,162! Con Se - Pump 25 5×5. @ 11,150'-19950' M.L.F. -SET 51/2"CIBP @ 11,150 Morrow perfs (11215' - 11222') Composite BP @ 11362' Morrow perfs (11398' - 11403') Morrow perfs (11449' - 11456') CIBP @ 11516 Morrow perfs (11530' - 11534') CIBP @ 11540' Morrow perfs (11544' - 11550') PBTD @ 12136' 5 1/2" 17# P-110 @ 12081' cmtd w/ 1030 sx TD @ 12081' XE 04/09/18

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.** 

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.