(June 2015)	UNITED STATES	S OCD	ATTER I	ORM APPROVED	
D] B	EPARTMENT OF THE I	NTERIOR	0	MB NO. 1004-0137 ires: January 31, 2018	
OLINIDDV		INIAI	7 2019 5. Lease Serial	No.	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-onter- abandoned well. Use form 3160-3 (APD) for such propos			6. If Indian, All	ottee or Tribe Name	
	TRIPLICATE - Other inst		the first of the second s	/Agreement, Name and/or N	
1. Type of Well		a dealons on page 2		1.	
Oil Well 🛛 Gas Well 🗋 Oth 2. Name of Operator		,	8. Well Name an MARQUARI	id No. DT 1	
CHEVRON USA INCORPORA	Contact: ATED E-Mail: nglann@ch	NICK GLANN nevron.com		9. API Well No. 30-015-22674-00-C1	
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706		3b. Phone No. (include area code) Ph: 661-599-5062	WHITE CIT	10. Field and Pool or Exploratory Area WHITE CITY-PENN (GAS) WHITE CITY-WOLFCAMP	
4. Location of Well (Footage, Sec., T.	., R., M., or Survey Description,)		11. County or Parish, State EDDY COUNTY, NM	
Sec 1 T25S R26E SENW 165	0FNL 1650FWL		EDDY COU		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	□ Acidize	Deepen	Production (Start/Resum	e) 🗖 Water Shut-Of	
Subsequent Report	□ Alter Casing	Hydraulic Fracturing	□ Reclamation	□ Well Integrity	
	Casing Repair	New Construction	□ Recomplete	□ Other	
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon		
 Describe Proposed or Completed Open If the proposal is to deepen directional 	Convert to Injection	Plug Back	U Water Disposal		
following completion of the involved testing has been completed. Final Aba determined that the site is ready for fir 9-5/8" 36# @ 2150' w/ TOC @ TOC @ 9336' ? Did root Chevron respectfully requests to 1. Notify BLM 24 hrs. prior to st	nal inspection.	- main and an requirements, menual	ng reclamation, have been comple	eted and the operator has	
Chevron respectfully requests f	o abandon this well as fo	llows:	(liner) Lee Pacific Caci	h set of pert	
2. MIRU, NU BOPE, pull compl	etion	09. Accepted for m	Sela	x, w/35 cmt	
3. Set CIBP (a) 9550', circulate	42 bbls water & spot 312	bble MIE processes test	7-	+ 25 sk, on C	
 Set CIBP @ 9550', circulate for 10 minutes Spot 35 sx CL C cmt f/ 9550' 	42 bbls water & spot 312	bbls MLF, pressure test casir	ng t/ 500 psi		
 Set CIBP @ 9550', circulate for 10 minutes Spot 35 sx CL C cmt f/ 9550' Spot 30 sx CL C cmt f/ 8621' 	42 bbls water & spot 312 t/ 9236' (CIBP & TOL). V t/ 8471' (Wolfcamp)	NOC & tag.	ng t/ 500 psi SEE ATTACH		
 Set CIBP @ 9550', circulate for 10 minutes Spot 35 sx CL C cmt f/ 9550' 	42 bbls water & spot 312 t/ 9236' (CIBP & TOL). V t/ 8471' (Wolfcamp)	NOC & tag.	SEE ATTACH	ED FOR	
 Set CIBP @ 9550', circulate for 10 minutes Spot 35 sx CL C cmt f/ 9550' Spot 30 sx CL C cmt f/ 8621' Spot 30 sx CL C cmt f/ 6550' 	42 bbls water & spot 312 t/ 9236' (CIBP & TOL). V t/ 8471' (Wolfcamp). t/ 6400' (Old squeeze pe	NOC & tag. rfs).	SEE ATTACH	ED FOR	
 Set CIBP @ 9550', circulate for 10 minutes Spot 35 sx CL C cmt f/ 9550' Spot 30 sx CL C cmt f/ 8621' Spot 30 sx CL C cmt f/ 6550' 14. 1 hereby certify that the foregoing is the f	42 bbls water & spot 312 t / 9236' (CIBP & TOL). V t / 8471' (Wolfcamp). t / 6400' (Old squeeze pe rue and correct. Electronic Submission #41 For CHEVRON US nitted to AFMSS for proces	NOC & tag. rfs).	SEE ATTACH CONDITION	ED FOR	
 Set CIBP @ 9550', circulate for 10 minutes Spot 35 sx CL C cmt f/ 9550' Spot 30 sx CL C cmt f/ 8621' Spot 30 sx CL C cmt f/ 6550' 	42 bbls water & spot 312 t / 9236' (CIBP & TOL). V t / 8471' (Wolfcamp). t / 6400' (Old squeeze pe rue and correct. Electronic Submission #41 For CHEVRON US nitted to AFMSS for proces	NOC & tag. rfs). 11559 verified by the BLM Well SA INCORPORATED, sent to th ssing by PRISCILLA PEREZ on	SEE ATTACH CONDITION	HED FOR S OF APPROVA	
 Set CIBP @ 9550', circulate for 10 minutes Spot 35 sx CL C cmt f/ 9550' Spot 30 sx CL C cmt f/ 8621' Spot 30 sx CL C cmt f/ 6550' 14. 1 hereby certify that the foregoing is the f	42 bbls water & spot 312 t / 9236' (CIBP & TOL). V t / 8471' (Wolfcamp). t / 6400' (Old squeeze pe rue and correct. Electronic Submission #41 For CHEVRON US nitted to AFMSS for proces	WOC & tag. rfs). 11559 verified by the BLM Well SA INCORPORATED, sent to th ssing by PRISCILLA PEREZ on Title WELL AE	Information System e Carlsbad 04/13/2018 (18PP1520SE) BANDONMENT ENGINEEF	HED FOR S OF APPROVA	
 Set CIBP @ 9550', circulate for 10 minutes Spot 35 sx CL C cmt f/ 9550' Spot 30 sx CL C cmt f/ 8621' Spot 30 sx CL C cmt f/ 6550' 14. I hereby certify that the foregoing is the Name (Printed/Typed) NICK GLAN	42 bbls water & spot 312 t/ 9236' (CIBP & TOL). V t/ 8471' (Wolfcamp). t/ 6400' (Old squeeze pe rue and correct. Electronic Submission #41 For CHEVRON US nitted to AFMSS for proces IN	NOC & tag. Ifs). I1559 verified by the BLM Well SA INCORPORATED, sent to the ssing by PRISCILLA PEREZ on Title WELL AE Date 04/13/20	Information System e Carlsbad 04/13/2018 (18PP1520SE) BANDONMENT ENGINEEF	HED FOR S OF APPROVA	
3. Set CIBP @ 9550', circulate for 10 minutes 4. Spot 35 sx CL C cmt f/ 9550' 5. Spot 30 sx CL C cmt f/ 8621' 6. Spot 30 sx CL C cmt f/ 6550' 14. I hereby certify that the foregoing is th Comm Name (Printed/Typed) NICK GLAN Signature (Electronic Sul	42 bbls water & spot 312 t/ 9236' (CIBP & TOL). V t/ 8471' (Wolfcamp). t/ 6400' (Old squeeze pe rue and correct. Electronic Submission #41 For CHEVRON US nitted to AFMSS for proces IN	WOC & tag. rfs). 11559 verified by the BLM Well SA INCORPORATED, sent to th ssing by PRISCILLA PEREZ on Title WELL AE	Information System e Carlsbad 04/13/2018 (18PP1520SE) BANDONMENT ENGINEEF	HED FOR S OF APPROVA	
3. Set CIBP @ 9550', circulate for 10 minutes 4. Spot 35 sx CL C cmt f/ 9550' 5. Spot 30 sx CL C cmt f/ 8621' 6. Spot 30 sx CL C cmt f/ 6550' 14. I hereby certify that the foregoing is th Comm Name (Printed/Typed) NICK GLAN Signature (Electronic Sul	42 bbls water & spot 312 t / 9236' (CIBP & TOL). V t / 8471' (Wolfcamp). t / 6400' (Old squeeze pe rue and correct. Electronic Submission #41 For CHEVRON US nitted to AFMSS for process IN bmission) THIS SPACE FOR	NOC & tag. Ifs). I1559 verified by the BLM Well A INCORPORATED, sent to th asing by PRISCILLA PEREZ on Title WELL AE Date 04/13/20 R FEDERAL OR STATE O Title Sex	Information System e Carlsbad 04/13/2018 (18PP1520SE) BANDONMENT ENGINEEF	HED FOR S OF APPROVA	
3. Set CIBP @ 9550', circulate for 10 minutes 4. Spot 35 sx CL C cmt f/ 9550' 5. Spot 30 sx CL C cmt f/ 8621' 6. Spot 30 sx CL C cmt f/ 6550' 14. I hereby certify that the foregoing is th Comm Name (Printed/Typed) NICK GLAN Signature (Electronic Sul	42 bbls water & spot 312 t / 9236' (CIBP & TOL). V t / 8471' (Wolfcamp). t / 6400' (Old squeeze pe rue and correct. Electronic Submission #41 For CHEVRON US nitted to AFMSS for process IN THIS SPACE FOR Approval of this notice does not able title to those rights in the su operations thereon.	WOC & tag. Infs). I1559 verified by the BLM Well CA INCORPORATED, sent to the ssing by PRISCILLA PEREZ on Title WELL AE Date 04/13/20 R FEDERAL OR STATE O Title Server Date Office C	Information System e Carlsbad 04/13/2018 (18PP1520SE) BANDONMENT ENGINEEF	HED FOR S OF APPROVA	

Additional data for EC transaction #411559 that would not fit on the form

32. Additional remarks, continued

7. Perf @ 5846' and sqz 55 sx CL C cmt f/ 5846' t/ 5696' (Bone Springs). WOC & tag.
8. Perf @ 2200' and sqz 90 sx CL C cmt f/ 2200' t/ 1960' (Shoe, Delaware). WOC & tag.
9. Perf @ 400' and sqz 145 sx CL C cmt f/ 400' t/ surface (Fresh Water).
10. Cut off wellhead 3' below grade, Verify Cement To Surface, install required dry hole marker as per COA's, turn over to reclamation.


All cement plugs will be class "C" with a closed loop system used.

Add Aluq. Salado. ferf@ 19650, 602 Cont to 1150. wor Tag.

Add Spacer Plug. Perf@ 3800 Sti Crit to 3660. Tes


Marquardt Federal #1 Wellbore Diagram

<u>Current</u>



Marquardt Federal #1 Wellbore Diagram

Proposed



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement</u>: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

8. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.