Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
* CUNDRY A	15		5. Lease Serial No. NMNM91078				
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to reep arts bad Fie abandoned well. Use form 3160-3 (APD) for such proposals					6 If Indian, Allottee or Tribe Name		
	RIPLICATE - Other inst					ement, Name and/or No.	
1. Type of Well					8. Well Name and No. LONGVIEW FED		
Oil Well Gas Well Other Other Other Other	Contact:	CAITLIN O'HA	IR		9. API Well No. 30-015-38070-0		
RKI EXPLORATION & PROD 3a. Address	LLC E-Mail: caitlin.ohair		m include area code)	10. Field and Pool or	Exploratory Area	
3500 ONE WILLIAMS CENTE TULSA, OK 74172		Ph: 539-573	-3527		BRUSHY DRAV		
4. Location of Well (Footage, Sec., T.	, R., M., or Survey Description,)	11. County or I				
Sec 1 T23S R28E SESE Lot I		EDDY			COUNTY, NM		
12. CHECK THE AP	PROPRIATE BOX(ES)	TO INDICAT	E NATURE C	OF NOTICE,	REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	-		TYPE O	F ACTION			
Notice of Intent	□ Acidize	Deep	en	Product	ion (Start/Resume)	□ Water Shut-Off	
	□ Alter Casing	Hydra	ulic Fracturing	Reclam	ation	U Well Integrity	
□ Subsequent Report	Casing Repair	New	Construction	Recomp	olete	Other Workover Operations	
Final Abandonment Notice	Change Plans	_ •			arily Abandon		
13. Describe Proposed or Completed Ope	Convert to Injection	Plug		U Water I		a shake we	
following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi ATTN: MR. CHRIS WALLS, RKI EXPLORATION & PROD WELL TO PRODUCTION. THIS WILL DOWNHOLE COM	andonment Notices must be fil inal inspection. UCTION, LLC REQUEST	led only after all ro	Accepte	ding reclamatio	n, have been completed 9 - 18 • NMOCD @ 6,393', AND RE	TURN THE	
(ADMINISTRATIVE ORDER I ATTACHED ARE THE CURR	DHC-4377) AND THE BL	M ON 7/15/20	1.			RECEIVED	
						MAY 2 3 2018	
		1			Dis	TRICT II-ARTESIA O.C	
14. I hereby certify that the foregoing is	s true and correct.	the second se	but the DIMMA	all Informatio	n System		
14. I hereby certify that the foregoing is	Electronic Submission # For RKI EXPLO nmitted to AFMSS for proc	RATION & PRO	D LLC, sent to	the Carlsbad		UTLESIA O.C.	
	Electronic Submission # For RKI EXPLO nmitted to AFMSS for proc	RATION & PRO	D LLC, sent to	on 05/03/2018		UTESIA O.C.	
Con	Electronic Submission # For RKI EXPLO nmitted to AFMSS for proc D'HAIR	RATION & PRO	D LLC, sent to CILLA PEREZ	the Carlsbad on 05/03/2018 ITTER		CONTROLATION O.C	
Con Name (Printed/Typed) CAITLIN (Electronic Submission # For RKI EXPLO nmitted to AFMSS for proc D'HAIR	RATION & PRO	D LLC, sent to CILLA PEREZ of Title SUBM	o the Carlsbac on 05/03/2018 ITTER 2018	(18PP1566SE)	Contraction of the second	
Con Name (Printed/Typed) CAITLIN (Signature (Electronic S Approved By/S/	Electronic Submission # For RKI EXPLO nmitted to AFMSS for proc D'HAIR Submission) THIS SPACE FO	RATION & PRO essing by PRIS	D LLC, sent to CILLA PEREZ o Title SUBM Date 05/01/2	o the Carlsbac on 05/03/2018 ITTER 2018 COFFICE U	(18PP1566SE)	5/14/2018	
Con Name (Printed/Typed) CAITLIN (Signature (Electronic S	Electronic Submission # For RKI EXPLO nmitted to AFMSS for proc D'HAIR Submission) THIS SPACE FO Jonathon Shepa d. Approval of this notice doe uitable title to those rights in th	RATION & PRO essing by PRIS	D LLC, sent to CILLA PEREZ of Title SUBM Date 05/01/2	o the Carlsbac on 05/03/2018 ITTER 2018 COFFICE U	(18PP1566SE)	5/14/2018	

A. 18. 19.

Workover Procedure

Well:	Longview Feder	Longview Federal 1-44			New Mexico			
Area/Field:	Longview/Pinnacle			County:	Eddy			
API Number:	30-015-38070	•			Sect 1 T23S R29E			
WPX EU Number:	62431614			Location: Sect 1 T23S R29E AFE Number: WT47995				
Primary Objective								
Repair rod part, dri	Il out composite plug a	at 6,393', and return	well to production.					
Contact Informa	and successive a literature in which the literature in which the	Office	Cell	Email				
Prod. Engineer	Bailey Nett	539-573-2547	505-386-8974					
Prod. Foreman	Kipper Folmar		575-644-2008	kipper.folmar@wpxenergy.com				
WO Consultant	Mark Trent	575-885-1313	575-602-6221					
	Justin Warren	575-885-1313	701-421-7324					
C 0.450 / C 0.								
Prod Eng Lead	Steve Bernhardt	539-573-3548	918-671-0683	Contraction of the Contraction o				
Prod Eng Lead		539-573-3548 539-573-3496	918-671-0683 918-645-3688	Robert.GoodwinIII				
Prod Eng Lead	Steve Bernhardt			Contraction of the Contraction o	@wpxenergy.com	691' (MD)		
Prod Eng Lead Ops Manager	Steve Bernhardt	539-573-3496		Robert.GoodwinIII	@wpxenergy.com	691' (MD)		
Prod Eng Lead Ops Manager Well Data	Steve Bernhardt Bobby Goodwin	539-573-3496 STC @ 299'		Robert.GoodwinIII	@wpxenergy.com	691' (MD)		
Superintendent Prod Eng Lead Ops Manager Well Data Casing	Steve Bernhardt Bobby Goodwin 13-3/8" 54.5# J-55 9-5/8" 40# J-55 ST	539-573-3496 STC @ 299'	918-645-3688	Robert.GoodwinIII	@wpxenergy.com	691' (MD)		
Prod Eng Lead Ops Manager Well Data	Steve Bernhardt Bobby Goodwin 13-3/8" 54.5# J-55 9-5/8" 40# J-55 ST 5-1/2" 17# N-80 LT	539-573-3496 STC @ 299' C @ 5,715' C @ 7,737' (TOC ~	918-645-3688	Robert.GoodwinIII	@wpxenergy.com	691' (MD)		
Prod Eng Lead Ops Manager Well Data	Steve Bernhardt Bobby Goodwin 13-3/8" 54.5# J-55 9-5/8" 40# J-55 ST	539-573-3496 STC @ 299' C @ 5,715' C @ 7,737' (TOC ~	918-645-3688	Robert.GoodwinIII	@wpxenergy.com	691' (MD)		
Prod Eng Lead Ops Manager Well Data Casing Tubing	Steve Bernhardt Bobby Goodwin 13-3/8° 54.5# J-55 9-5/8° 40# J-55 ST 5-1/2° 17# N-80 LT 2-7/8° 6.5# L-80 Br	539-573-3496 STC @ 299' C @ 5,715' C @ 7,737' (TOC ~	918-645-3688	Robert.GoodwinIII(TD: 7,737' (MD)	@wpxenergy.com) PBTD: 7		Tensile (80%)	bbls/f
Prod Eng Lead Ops Manager Well Data Casing Tubing Casing & Tubing	Steve Bernhardt Bobby Goodwin 13-3/8" 54.5# J-55 9-5/8" 40# J-55 ST 5-1/2" 17# N-80 LT 2-7/8" 6.5# L-80 8r Data	539-573-3496 STC @ 299' C @ 5,715' C @ 7,737' (TOC ~ d EUE @ 6,350' ID	918-645-3688 125') Drift	Robert.Goodwinill(TD: 7,737' (MD)	@wpxenergy.com PBTD: 7 Burst (80%)	Tensile (100%)	Tensile (80%) 411.200	States of the local division of the local di
Prod Eng Lead Ops Manager Well Data Casing Tubing Casing & Tubing 13-3/8" 54.5# J-55	Steve Bernhardt Bobby Goodwin 13-3/8° 54.5# J-55 9-5/8° 40# J-55 ST 5-1/2° 17# N-80 LT 2-7/8° 6.5# L-80 Br Data LTC casing	539-573-3496 STC @ 299' C @ 5,715' C @ 7,737' (TOC ~ d EUE @ 6,350' ID 12.615	918-645-3688 125') Drift 12.459	Robert Goodwintli(TD: 7,737' (MD) Burst (100%) 2,740	2wpxenergy.com PBTD: 7 Burst (80%) 2,192	Tensile (100%) 514,000	Tensile (80%) 411,200 416.000	0.1545
Prod Eng Lead Ops Manager Well Data Casing Tubing Casing & Tubing 13-3/8" 54.5# J-55 9-5/8" 40# J-55 LT	Steve Bernhardt Bobby Goodwin 13-3/8° 54.5# J-55 9-5/8° 40# J-55 ST 5-1/2° 17# N-80 LT 2-7/8° 6.5# L-80 Br Data LTC casing 'C casing	539-573-3496 STC @ 299' C @ 5,715' C @ 7,737' (TOC ~ d EUE @ 6,350' ID 12.615 8.835	918-645-3688 125') Drift 12.459 8.6790	Burst (100%) 2,740 3,950	2wpxenergy.com PBTD: 7 Burst (80%) 2,192 3,160	Tensile (100%) 514,000 520,000	411,200 416,000	bbis/f
Prod Eng Lead Ops Manager Well Data Casing Tubing Casing & Tubing 13-3/8" 54.5# J-55	Steve Bernhardt Bobby Goodwin 13-3/8" 54.5# J-55 9-5/8" 40# J-55 ST 5-1/2" 17# N-80 LT 2-7/8" 6.5# L-80 8n Data LTC casing C casing 10 BTC casing	539-573-3496 STC @ 299' C @ 5,715' C @ 7,737' (TOC ~ d EUE @ 6,350' ID 12.615	918-645-3688 125') Drift 12.459	Robert Goodwintli(TD: 7,737' (MD) Burst (100%) 2,740	2wpxenergy.com PBTD: 7 Burst (80%) 2,192	Tensile (100%) 514,000	411,200	0.1545

VV F ALLEY LET'S I.

Hold pre job safety meeting and discuss current well conditions such as duration of shut in time, predicted/current pressures, and any nonroutine operational change of scope.

PROCEDURE

- 1) Follow all WPX safety and environmental requirements. Hold pre-job safety meeting before each operation.
- 2) MIRU pulling unit and equipment. Ensure pumping unit is properly secured. Kill well as necessary. Unhang rods from bridal. LD horse head. PU & Unseat pump. LD polished rod, stuffing box, and pony rods. POOH w/ rods & pump while laying down. Unflange WH. NU BOP's. Pressure test. MIRU tubing scanners. Unset TAC. Scan out of hole w/ tbg, TAC, SN, MAC, etc. LD "green" and "red" band tbg (>31% wall loss). LD any "blue" band only as directed by WPX Rep. RDMO tubing scanners. Send pump and TAC to shop for inspection and redressing.

* Procure additional 2-7/8 6.5# L-80 8rd EUE tbg as needed to replace any laydown joints. Procure additional rods and cplgs as needed to make up shortages.

- 3) RIH with milling BHA. Mill and cleanout composite plug at 6,393'.
- 4) RIH w/ tbg and BHA setup as specified in "Tubing Detail" below. Space out. Ensure well is dead, kill as necessary. ND BOP's. Set TAC w/~12-15,000 lbs tension. Flange up WH.

TUBING DETAIL						
Tubing and Packer detail	No. Jts	Length (ft)	Top Depth (ft			
KB		18.00'				
2-7/8" 6.4# L-80 8rd EUE tubing	174	5,602.80	18.00'			
2-7/8" L-80 Marker Sub		2.10"	5,620.80			
2-7/8" 6.4# L-80 8rd EUE tubing	2	64.40'	5,622.90'			
TAC		2.75'	5,687.30			
2-7/8" 6.4# L-80 8rd EUE tubing	17	547.40	5,690.05			
SN		1.10'	6,237.45			
2-7/8" L-80 Perf Sub		4.10'	6,238.55			
2-7/8" Mud Joint	2	64.40"	. 6,242.65			
Bull Plug		0.50°	6,307.05			
		EOT @	6,307.55			

* Projected detail, actual lengths may vary

5) RIH w/ rod string and pump as specified in "Rod String Detail" below. Seat pump. Space out rods accordingly. PU PR and stuffing box. NU PR to top rod and stuffing box to pumping tee. Load tbg and pressure test to ~500 psi. Long stroke pump to check pump action.


Туре	OD	Length	Rods	Туре
PR	1.250"	26'	··· ·	1-1/4" x 26' PR w/ 1-3/4" Liner
1"Rods	1.000"	16'	2	Norris 97 Pony Rods
1" Rods	1.000"	400"	16	Norris 97 Rods w FFSM couplings
7/8" Rods	0.875	2,125'	85	Norris 97 Rods w FFSM couplings
3/4" Rods	0.750*	3,475	139	Norris 97 Rods w FFSM couplings
1-1/2" Rods	1.500"	200'	8	API Grade C Sinker Bars
Lift Sub				Lift sub stabilizer
Insert Pump	1.750	24'	-	2 1/2 x 1 3/4 x 24 RXBC
GAC	1.000*	20'	-	Gas Anchor

detail, actual lengths may vary

3


6) Perform necessary pre-startup checks. Kick off unit. Stroke up pump and pressure tbg to ~500 psi. Hold for 5-10 mins. Bleed off. SD unit. If pump action and unit running good per WPX Rep, RDMO Pulling Unit and equipment. Clean location.

7) Notify foreman and engineer that work is completed so that well can be returned to production.



Date: 4/26/2018 Updated: BN CURRENT

Charles and the second



Date: 4/26/2018 Updated: BN CURRENT

New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

John H. Bemis Cabinet Secretary-Designate

Brett F. Woods, Ph.D. Deputy Cabinet Secretary JAMI BAILEY Division Director **Oil Conservation Divisi**



Administrative Order DHC-4377 Order Date: 5/21/2011 Application Reference Number: pTGW1110453722

RKI EXPLORATION & PRODUCTION, LLC 3817 NW EXPRESSWAY, SUITE 950 OKLAHOMA CITY, OK 73112

Attention: Ben Stone

Pool:

LONGVIEW 1 FEDERAL Well No. 044 API No: 30-015-38070 Unit P, Section 1, Township 23 South, Range 28 East, NMPM Eddy County, New Mexico UNDES. CULEBRA BLUFF; BONE SPRING, SOUTH Oil 15011 Names: HERRADURA BEND; DELAWARE, EAST Oil 30670

Reference is made to your recent application for an exception to 19.15.12.9A NMAC of the Division Rules and Regulations to permit the above-described well to commingle production from the subject pools in the wellbore.

It appearing that the subject well qualifies for approval for such exception pursuant to the provisions of 19.15.12.11A NMAC, and that reservoir damage or waste will not result from such downhole commingling, and correlative rights will not be violated thereby, you are hereby authorized to commingle the production as described above and any Division Order which authorized the dual completion or otherwise required separation of the zones is hereby placed in abevance.

In accordance with 19.15.12.11A.(6) NMAC, the production attributed to any commingled pool within the well shall not exceed the allowable applicable to that pool.

The production allocation percentages of oil and gas between these pools shall be supplied to the Division's Santa Fe office within 60 days following completion of this well or workover,

REMARKS: The operator shall notify the Division's district office upon implementation of commingling operations.

Oil Conservation Division * 1220 Sou	th St. Francis Drive
* Santa Fe, New Mexico	87505
Phone: (505) 476-3440 * Fax (505) 476-3462*	http://www.emnrd.state.nm.us



Administrative Order DHC-4377 RKI EXPLORATION & PRODUCTION, LLC 5/21/2011 Page 2 of 2

Pursuant to 19.15.12.11B NMAC, the commingling authority granted herein may be rescinded by the Division Director if conservation is not being best served by such commingling.

JAMT BAILEY

Director

JB/wvjj

cc: Oil Conservation Division – Artesia Bureau of Land Management - Carlsbad

		OCD.	ARTESL					
	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT					FORM APPROVED DM B No. 1004-0137 xpires: March 31, 2	007	
	NOTICES AND REPORTS ON WELLS			1	5. Lease Serial N NM-917	NO. 078		
Do not use th	Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					Allottee or Tribe M	Vame	
	IPLICATE- Other inst	ructions on rev	erse side	€.	7. If Unit or C	A/Agreement, N	ame and/or No.	
1. Type of Well O Gas Well O Other					8. Well Name			
2. Name of Operator RKI Explor	ŀ	Longview '1' Federal Well No.44 9. API Well No.						
3a Address 3817 NW Expres		3b. Phone No. (inci			30-015-38070			
Oklahoma City, 4 Location of Well (Footnee Sec.		405-996-	5/50			Pool, or Explorate rradura Bend		
4. Location of Well (Footoge, Sec., T., R., M., or Survey Description) 360' FSL & 330' FEL, Sec.1-Twp 23S-Rng 28E					East Herradura Bend Bone Spring 11. County or Parish, State Eddy County, New Mexico			
12. CHECK A	PPROPRIATE BOX(ES) TO	INDICATE NAT	URE OF N	OTICE, RE	PORT, OR	OTHER DAT	Ą	
TYPE OF SUBMISSION]	YPE OF A	CTION				
X Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat	Rec	clamation (Start	I	Water Shut-O Well Integrity		
Final Abandonment Notice	Change Plans		Plug and Abandon Temporarily Ab Plug Back Water Disposal			bandon Downhole Commingle		
following completion of the in	the Longview Federal wells the Delaware portion (bet action tests on that zone. Ercent from the top of the e pressure data as it is avail the wells may be separat rea.	are currently con ween approxima The vertical exten upper interval to ailable from any a ely metered in th	mpletion or re aircments, incl hpleted in t tely 5950' a hts of separ the bottor additional t e future. P	ecompletion in huding reclama the Bone Sp and 6265') ration betw n of the low testing that Production	a new interval, tion, have been by April or M veen comple wer interval may be cor from these	a Form 3160-4 st completed, and th tion and RKI i May 2011 and etions in the so crossflow aducted. More pools is matu	nall be filed once ne operator has i will subject is not nthly well re and	
The surface is owned U.S. B result of this commingling.	ureau of Land Manageme	-T COG	21-11		nent will no TTACHE		as a	
 I hereby certify that the fore Name (Printed/Typed) Ben 	egoing is true and correct Stone (903) 488-	9 850 Title	Consult	COND		OF APPR	OVAL	
Signature	Am .	Date				JU	EIVEI	
	THIS SPACE FOR	FEDERAL OF			USE	LNMON	5 2011	
Amountly ALCT	4. 2		1	AP	PROV	·D	ARTESIA	
Approved by Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant t	al or equitable title to those rights		Office	JU	IL 15 20	nı	SIA	
Title 18 U.S.C Section 1001 and Tit States any false, fictitious or fraudu	le 43 U.S.C. Section 1212, make it ilent statements or representations	a crime for any perso as to any matter with	n knowingly a n its jurisdict	and villfully to	o make to any	department or ag	ency of the United	
(Instructions on page 2)				BUREAU	SBAD FIELD	OFFICE		

Longview Federal 1-44 30-015-38070 RKI Exploration & Production, LLC July 15, 2011 Conditions of Approval

- 1. Send in a Notice of Intent on form 3160-5 with plans for completing the Delaware and the exact date that commingling of the two zones is to start.
- 2. Send in a subsequent sundry with completion report and allocation percentages after the zone has been tested.

TAM 071511

L

٢

٩,