Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

	NOTICES AND REPO is form for proposals to II. Use form 3160-3 (AP		ELLS CID	Arte	S. Least South No. aNMNM93772	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well Gas Well					8. Well Name and No. W SHUGART 19 FED 4		
2. Name of Operator Contact: MELISSA B SZUDERA BLACK MOUNTAIN OPERATING LLCE-Mail: mszudera@marathonoil.∞m					9. API Well No. 30-015-30647-00-S1		
3a. Address 500 MAIN STREET, SUITE 1200 FORT WORTH, TX 76102			3b. Phone No. (include area code) Ph: 713-296-3179		10. Field and Pool or Exploratory Area SHUGART		
4. Location of Well (Footage, Sec., T			11. County or Parish, State				
Sec 19 T18S R31E SWSW Lot 4 660FSL 660FWL				EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OF	F NOTICE,	REPORT, OR OTI	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Production (Start/Resume)		■ Water Shut-Off	
	☐ Alter Casing	☐ Hyd	aulic Fracturing		■ Well Integrity		
☐ Subsequent Report	□ Casing Repair	□ New	■ New Construction		lete	Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon		Tempora	▼ Temporarily Abandon		
	Convert to Injection	☐ Plug Back		☐ Water Disposal			
13. Describe Proposed or Completed Oplif the proposal is to deepen direction: Attach the Bond under which the wor following completion of the involved testing has been completed. Final Addetermined that the site is ready for for Marathon Oil Permian LLC. (Newlifer a period of one year.) Quantities. There is possible uto refrain from plugging and all	ally or recomplete horizontally rk will be performed or provide to operations. If the operation re- pandonment Notices must be fi- inal inspection. MOP) respectively reques The reason is at this time p hole recompletion opping the way to the provided the provided provided the provided manufactured to the provided provided the provided	, give subsurface e the Bond No. or esults in a multipl led only after all sts to temporal the well is un	locations and measure file with BLM/BIA. e completion or record requirements, including abandon the a economical in paragraph.	ed and true ver Required sub mpletion in a n ng reclamation above menti ying	rtical depths of all pertin sequent reports must be ew interval, a Form 316 i, have been completed a	nent markers and zones. Filed within 30 days 60-4 must be filed once	
Procedure for temporary abar 1. Safety meeting				N 3 3 5018			
2. RU Pulling unit, POOH w/ rods and pump 3. POOH w/ Tbg 4. RIH w/ 5-1/2?? GR/JB. If no obstructions POOH w/ GR. 5. RIH w/ 4.31?? OD CIBP. Set CIBP @ 7,557?. (+/- 50?-100? of top perf) 6. Bailor in cmt.					DISTRICT II-ARTESIA O.C.D.		
					Accepted for record NMOCD (5)/>1/18		
14. I hereby certify that the foregoing is	Electronic Submission #	NTAIN OPERA	ΠNG LLC, sent to	the Carlsba	ď	•	
Name(Printed/Typed) MELISSA B SZUDERA			Title REGULATORY COMPLIANCE REP				
Signature (Electronic S	bmission) Date 12/08/2017 (s/ lonathon Shenard						
	THIS SPACE F	OR FEDERA	L OR STATE (-	
/s/ Jonathon Shepard			Title PE			05/10/2018 Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office CF	2			


Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


Additional data for EC transaction #397400 that would not fit on the form Carlsbad Field Office

OCD Artesia

7. RIH w/ tbg tag cmt @ +/- 7520? (+/-37? cmt on top of CIBP)
8. Leave tubing in the hole.
9. RDMO pulling unit. Detached all production equipment on surface.

WBD's are attached, see portion B with BP setting. Leaving in the hole above BP.





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575 234 5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

