Submit 1 Copy To Appropriate District Office	State	e of New Mex	ico		Form C-103
District I - (575) 393-6161	Energy, Minerals and Natural Resources			Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283				WELL AI	PI NO. 5-03755
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION				te Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.				ATE 🔀 FEE 🗌
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505				Dil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				E-537	
	TICES AND REPORT	S ON WELLS			Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			C State		
1. Type of Well: Oil Well				8. Well Number 1	
Name of Operator     Tandem Energy Corporation				9. OGRID Number 236183	
3. Address of Operator				10. Pool name or Wildcat	
5065 Westheimer Rd, Ste 920, Houston, TX 77056				Grayburg-Jackson	
4. Well Location					
Unit Letter	2310 feet from	the South	line and	330	feet from the East line
Section 33	Township	p 17S Ran	ge 29E	NMPM	County Eddy
	11. Elevation (Sho		RKB, RT, GR, etc.)		1. 50 . 1. 1
		42 GL		<del></del>	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
PERFORM REMEDIAL WORK TEMPORARILY ABANDON DULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	CHANGE PLANS MULTIPLE COMP		SUBS REMEDIAL WORI COMMENCE DRII CASING/CEMENT	K LLING OPN	IT REPORT OF:  ALTERING CASING  S. P AND A
OTHER: Bring well back to pro	4		OTHER:		DJ
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
The proposed work is	to be completed 6/2	24/2018 to 6/2	6/2018		
MIRU workover rig.     Hiphona well and BOOH with rade and number.					
<ol> <li>Unhang well and POOH with rods and pump.</li> <li>Drop standing valve and test tubing. (If tubing tests ok, skip Step 4, 5, and 6).</li> </ol>					
4. NU BOPs.					RECEIVED
5. POOH with tubing, replace bad joints, RIH with good tubing.					
6. ND BOPs.					
7. PU new pump and F	RIH with pump and	rods.			JUN <b>2</b> 5 2018
<ol> <li>Hang rods.</li> <li>Load and test the tu</li> </ol>	hina				
10. Return the well to					DISTRICT II-ARTESIA O.C.D.
Spud Date:	] F	Rig Release Date	:		
I hereby certify that the information	above is true and con	plete to the best	of my knowledge	and belief.	
SIGNATURE TITLE IT Manager DATE 6/15/2018					
Type or print name Chris Sande	are ,	C	ChricCATEE	orav com	DUONE: 712 007 7240
For State Use Only		E-maii address:	ChrisS@T5En	ergy.com	PHONE: 713-987-7318
- State Cot Only		<b></b> ,	A		
APPROVED BY:	000	TITLE STAT	+ Mc		DATE_6-25-18
Conditions of Approval (if any):					